



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105227

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 27/07/2021
Reference CC6/CTI19019000/Ees3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKF 5413Y
Insured Veh. GZ 6160L
Claim No. SNM19D205080/C02
Policy No. DMCVSN10211319099
Accident Date 23/10/2019
Inspection Date 04/11/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI19019000/Ees3q2	Date: 27/07/2021
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 6160L	Veh. Inspected	SKF 5413Y	
Policy No.	DMCVSN10211319099	Coverage (\$)	0.00	
Claim No.	SNM19D205080/C02	Excess (\$)	0.00	
Assign From		Assign Date	04/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET CRUZE	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KL1JF6961BK188558	Colour	RED	
Odometer	124424 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/10/2019	Inspection Date	04/11/2019	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 5413Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED	980.00	980.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	30.00
1	REAR BUMPER RETAINER RH	BROKEN	30.00	30.00
1	REAR BUMPER RETAINER LH	BROKEN	30.00	30.00
1	REAR BUMPER TOW EYE	NOT NECESSARY	30.00	-
1	REAR BOOT COVER	DENTED	1,280.00	1,280.00
1	REAR CHEVROLET LOGO EMBLEM (ADDITIONAL)	NECESSARY	80.00	80.00
1	REAR CHEVROLET EMBLEM (ADDITIONAL)	NECESSARY	70.00	70.00
1	REAR CRUZE EMBLEM (ADDITIONAL)	NECESSARY	70.00	70.00
	LESS 10% DISCOUNT		-	-257.00
			2,620.00	2,313.00
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	NOT NECESSARY	200.00	-
			200.00	-
	<u>LABOUR</u>			
	SPRAY PAINTING REAR BUMPER AND REAR BOOT COVER .		500.00	400.00
	REMOVE ,REPLACE AND REPAIR ACCIDENT AFFECTED AREA.		500.00	400.00
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	30.00
	REMOVE AND REFIT REAR REVERSE SENSOR .	NOT NECESSARY	80.00	-
	CHECK AND RECTIFY ELECTRICAL WIRING .		30.00	30.00
			1,210.00	860.00
GRAND TOTAL			4,030.00	3,173.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	-----------------

Report Ref No. CC6/CTI19019000/Ees3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 5413Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 5413Y

RE-INSPECTION

