Adjuster Report Page 1 of 5

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19019058/QGA3Q2

Date: 07/07/2020

**REFERENCE** 

PNPV2018-00008486-01 Handling Insurer: FWD Singapore Pte. Ltd. Policy No:

Claimant FBP3849R

Insured Vehicle No: SLD5884U Vehicle No:

Date of Loss: 20/09/2019 TP Nature of Claim: Claim No: 1201900029641

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**FBP3849R** Reg No:

Make & Model: YAMAHA YZF-R15, 150cc (M) Engine No: G3J6E0184681

Reg. Date: 28/03/2019 (Man. Year: 2019) Chassis No: MH3RG4710KK099439

Colour: Odometer: 3107 km Black

**Engine Capacity:** 155 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

Front Tyre Size: 150/60 R17 Rear Tyre Size: 150/60 R17 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Rear Right Side: Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,132.00	1,328.80	4,803.20	78.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	200.00	350.00	63.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,682.00	1,528.80	5,153.20	77.12
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	6,682.00	1,200.00	5,482.00	82.04
Global Sum S	settlement (S\$)	0.00		

INSPECTION

30/10/2019 Date of Assignment:

Date Inspected: 30/10/2019 Inspected At: M2 Garage Pte Ltd (HQ)

61 WOODLANDS INDUSTRILA PARK

E9 PREMIER 9S (01-17) Singapore 757047

Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 5

Adjuster Report Page 3 of 5

### **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 07 Jul 2020)

Parts: N/A YAMAHA YZF-R15 150cc (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBP3849R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Scratched	110.00 F	*110.00 FL
2	1		*WINDSHIELD	Serviceable	120.00 F	*-FL
3	1		*BODY FRONT COWLING	Serviceable	98.00 F	*- FL
1	1		*FRONT COWLING L/H	Scratched	68.00 F	*68.00 FL
5	1		*FRONT COWLING R/H	Serviceable	68.00 F	*- FL
3	1		*VIEW MIRROR L/H	Scratched	80.00 F	*50.00 FL
7	1		*VIEW MIRROR R/H	Serviceable	80.00 F	*- FL
3	1		*COVER FRONT INNER L/H	Scratched	75.00 F	*75.00 FL
9	1		*COVER FRONT INNER R/H	Serviceable	75.00 F	*- FL
10	1		*BODY FRONT UPPER INNER	Scratched	80.00 F	*80.00 FL
11	1		*STAY FRONT COWLING	Serviceable	130.00 F	*- FL
12	1		*HEAD LIGHT	Scratched	587.00 F	*350.00 FL
13	1		*FRONT PANEL L/H	Cracked	125.00 F	*100.00 FL
14	1		*FRONT PANEL R/H	Serviceable	125.00 F	*-FL
15	1		*COVER UNDER L SIDE	Serviceable	95.00 F	*- FL
16	1		*COVER UNDER R SIDE	Serviceable	95.00 F	*- FL
17	1		*COVER INNER LOWER	Serviceable	90.00 F	*- FL
18	1		*PANEL CONSOLE L/H	Serviceable	48.00 F	*- FL
19	1		*PANEL CONSOLE R/H	Serviceable	48.00 F	*-FL
20	1		*PANEL INNER L/H	Serviceable	58.00 F	*-FL
21	1		*PANEL INNER R/H	Serviceable	58.00 F	*- FL
22	1		*FRONT FLASHER LIGHT L/H	Scratched	90.00 F	*60.00 FL
23	1		*REAR FLASHER LIGHT L/H	Scratched	90.00 F	*60.00 FL
24	1		*REAR MUDGUARD	Serviceable	58.00 F	*- FL
25	1		*BRAKET REAR MUDGUARD	Serviceable	68.00 F	*-FL
26	1		*REAR FENDER	Serviceable	55.00 F	*- FL
27	2		*HANDLE GRIP	Bent	36.00 F	*36.00 FL
28	1		*CLUTCH LEVER LEFT	Bent	28.00 F	*28.00 FL
29	2		*BAR END BALANCER	Scratched	56.00 F	*40.00 FL
30	1		*SIDE STAND	Bent	68.00 F	*40.00 FL
31	1		*GEAR SHIFTER	Bent	95.00 F	*95.00 FL
32	1		*FRONT FOOT REST L/H	Scratched	48.00 F	*30.00 FL
33	1		*FRONT FOOT REST BRACKET L/H	Serviceable	150.00 F	*- FL
34	1		*REAR FOOT ASSY L/H	Scratched	44.00 F	*30.00 FL
35	1		*REAR FOOT ASSY BRACKET L/H	Serviceable	220.00 F	*- FL
36	1		*FRONT HEAD LAMP BRACKET	Serviceable	350.00 F	*- FL
37	1		*COVER TANK CENTRER	Serviceable	70.00 F	*- FL
38	1		*COVER TANK L SIDE	Scratched	110.00 F	*110.00 FL
39	1		*COVER TANK R SIDE	Serviceable	110.00 F	*-FL
10	1		*UNDER BRACKET	Serviceable	350.00 F	*- FL
11	1		*STEERING CONE BEARING	Serviceable	90.00 F	*- FL
12	1		*STEERING CONE BEARING PLATE	Serviceable	25.00 F	*- FL
43	1		*HANDLE BAR L/H	Serviceable	180.00 F	*-FL
			Report was unsubmitted dur	ing this print out		
			report was unsubmitted dur	ing this print-out.		

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR COVER L/H	Scratched	98.00 F	*70.00 FL
45	1		*REAR COVER R/H	Serviceable	98.00 F	*- FL
46	1		*REAR COVER UPPER	Serviceable	57.00 F	*-FL
47	1		*COVER CENTER R SIDE	Serviceable	68.00 F	*- FL
48	1		*COVER CENTER L SIDE	Serviceable	68.00 F	*-FL
49	1		*COVER BETWEEN SEAT	Serviceable	38.00 F	*- FL
50	1		*BOLT FRONT FOOTREST	Serviceable	25.00 F	*- FL
51	1		*FRONT L SIDE STEP ASSEMBLY	Serviceable	350.00 F	*-FL
52	1		*MIRROR L/H	Repeated	85.00 F	*-FL
53	1		*COVER FRONT INNER L/H	Repeated	48.00 F	*- FL
54	1		*COVER FRONT INNER R/H	Repeated	48.00 F	*-FL
55	1		*BODY FRONT UPPER INNER	Repeated	95.00 F	*- FL
56	1		*MARKS FRONT PANEL L SIDE	Serviceable	75.00 F	*- FL
57	1		*MARKS FRONT PANEL R SIDE	Serviceable	75.00 F	*- FL
58	1		*RIVET 90269-06816 (25 PCS)	Necessary	200.00 FS	*40.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	6,132.00	1,472.00
	- List Item Discount on L Items 0.00/10.00% (S\$) 0.00 143.20					143.20
				Total Parts (S\$)	6,132.00	1,328.80
	Report was unsubmitted during this print-out.					

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING	New	150.00	0.00
2	LABOUR	New	400.00	200.00
		Gross Labour Cost (S\$)	550.00	200.00
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >