



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 6467X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REF TRUCK BOX -SUPPLY AND REPLACE TWO (2) NOS,BULKHEAD PVC CORNER CAPPING @\$120.00 (CONSISTENT)	NECESSARY	240.00	240.00
1	REF TRUCK BOX-SUPPLY AND REPLACE ONE (1) LOT ALUMINUM EXTRUSION CAPPING C/W STRUCTURE BONDING AND SEALANT (CONSISTENT)	DENTED	780.00	780.00
	LESS 15% DISCOUNT		-	-153.00
			1,020.00	867.00
	<u>SPECIAL NETT ITEMS</u>			
1	REF TRUCK BOX-SUPPLY AND REPLACE NEW ARTWORK ON RH PANEL FREEZER BOX (LOCAL REPAIR) (CONSISTENT) (SN)	NECESSARY	1,380.00	900.00
			1,380.00	900.00
	<u>LABOUR</u>			
	REF TRUCK BOX-FIBERGLASS REPAIR ON FREEZER BOX DAMAGE AREA AND MAKE GOOD C/W POLISHING .		380.00	380.00
	REF TRUCK BOX-TO DO ADJUSTMENT AND REALIGN FREEZER BOX.	NOT NECESSARY	350.00	-
	REF TRUCK BOX-SUPPLY LABOUR AND SERVICES TO COMPLATE ABOVE JOB.		700.00	700.00
			1,430.00	1,080.00
	GRAND TOTAL		3,830.00	2,847.00
	RECOMMENDED COST OF REPAIRS			2,847.00

Report Ref No. CC4/ASM19019065/Eps3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.