Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19019140/ATF3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant SKC230G Insured Vehicle No: GBD3403G

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC230G

Make & Model: HONDA ACCORD, 1.6 (M) Engine No: 2GR8703813

Reg. Date: 18/11/2010 (Man. Year: 2000) Chassis No: JTHBC965605023491

Colour: White Odometer: 225399 km

Engine Capacity: 3456 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,836.20	4,974.51	3,861.69	43.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,430.00	320.00	18.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,586.20	6,404.51	4,181.69	39.50
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	10,586.20	5,100.00	5,486.20	51.82

INSPECTION

Date of Assignment: 30/10/2019

Date Inspected: 30/10/2019 Inspected At: Tk Motor Workshop (HQ)

Blk 1 Kaki Bukit Ave 6 #02-56,

Autobay @ Kaki Bt Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2020)

Parts: 143 HONDA ACCORD 1.6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC230G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H FENDER	Dented	988.20 F	*988.20 FL
2	1		*FRONT L/H FENDER MOULDING	Not Necessary	161.10 F	*- FL
3	5		*FRONT L/H FENDER MOULDING CLIP	Not Necessary	19.50 F	*- FL
4	1		*FRONT BUMPER	Torn	684.90 F	*684.90 FL
5	1		*FRONT BUMPER L/H SIDE RETAINER	Necessary	35.60 F	*35.60 FL
6	8		*FRONT BUMPER CLIP	Necessary	30.40 F	*30.40 FL
7	2		*FRONT BUMPER SIDE CLIP	Necessary	25.60 F	*25.60 FL
8	1		*FRONT L/H HID HEADLAMP	Cut	2,875.40 F	*1,715.00 FL
9	1		*FRONT L/H SIDE MORROR	Damaged	1,214.20 F	*1,214.20 FL
10	1		*FRONT L/H DOOR	Repair	1,176.90 F	*- FL
11	1		*FRONT L/H DOOR LOWER MOULDING	Not Necessary	212.20 F	*- FL
12	1		*REAR L/H DOOR LOWER MOULDING	Not Necessary	212.20 F	*- FL
13	1		*FRONT L/H WHEEL RIM	Necessary	1,200.00 FS	*750.00 FS
F=Fra	anchise	part. S=SpcN	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	8,836.20	5,443.90
			- List Item Discount on L Items	0.00/10.00% (S\$)	0.00	469.39
				Total Parts (S\$)	8,836.20	4,974.51

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY PAINTING	New	1,100.00	900.00
3	TO LABOUR CHARGE FOR PANEL BEATING ,WELDING ,REMOVING ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC	New	600.00	500.00
	Gross Labour Cost (S\$)		1,750.00	1,430.00
	Report was unsubmitted durir	g this print-out.		

< END OF ESTIMATES >