

Surveyor

REF: CS1/SFF19019154/K/S/SF

Special Instruction: LS: \$5250/-

From (Person): Hafizul Farhan Rahmat

ASSIGNMENT (Office)

Estimated Cost:

Date/Time: 30/10/2019

Third Parties:

Claimant:

Surveyor: VAC

Workshop: CDGE

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SHC 1373 G

Insured: GZ3294 D

at Workshop m/s Comfort Delgro

Tel:

of 59 Loyang Drive

Policy No:

Claim No: AFMD/105/009/2019/081

Sum Insured:

Excess:

Make of Veh:

D.O.A. 1/8/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 4 days)

Date/Time: 31/10/19 Submit Final Fig \$4,000/- US 4 days (Red \$1,200/- 23%; Original 4 days)

Date/Time	Action/Instruction
	SHC 1373 G - X GZ3294 D - C1/TPD19013965/PC DCA: 1/8/2019
31/10/19	Range - \$ 4,000/- - \$ 5,000/- (Kalvin instruction) Recommended repair days : 4 weekends : 2 Total Days : 6

[Signature]
31/10/2019

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 2019

Para(3) : Nett Value

Market Value : _____
 Salvage Value : _____
 Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:
 Basic & Add
 Transport
 Photos
 Others
 Total

Date:

- 1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
- 3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
- 5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Wednesday, 30 October 2019 11:23 AM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF); SUR; Cui Fen ENG (SPF)
Subject: Request for Post-Survey of SHC1373G (vs GZ3294D & SKM9520H) DOA: 1/8/2019
Attachments: SHC1373G 2019-081.pdf

Ref no: AEMD/105/009/2019/081

Kindly conduct post-survey for **SHC1373G**. (refer to attached)

Thank you.

Best Regards,

*Hafizul Farhan Bin Rahmat
Assistant Logistics Support Officer
Logistics Support and Services Division
Police Logistics Department / Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848*



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Hafizul Farhan RAHMAT (SPF)
Sent: Tuesday, 20 August 2019 3:29 PM
To: 'Denise Tay (LKKAuto)' <denisetay@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>; Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: Request for Pre-Repair Survey of SKM9520H (vs GZ3294D & SHC1373G) DOA: 1/8/2019

Message Classification: Unclassified

Dear Denise,

The ref no: AEMD/105/009/2019/081.

Best Regards,

*Hafizul Farhan Bin Rahmat
AEMD / PLD*



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Tuesday, 20 August 2019 2:04 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>; Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: Request for Pre-Repair Survey of SKM9520H (vs GZ3294D & SHC1373G) DOA: 1/8/2019

Dear Hafizul,

Please provide your ref no.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 7 August 2019 3:52 PM
To: 'Hafizul Farhan RAHMAT (SPF)' <Hafizul_Farhan_RAHMAT@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: 'Frankie THAY (SPF)' <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>; 'Rosalyn TAN (SPF)' <Rosalyn_TAN@spf.gov.sg>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Subject: RE: Request for Pre-Repair Survey of SKM9520H (vs GZ3294D & SHC1373G) DOA: 1/8/2019

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 08/08/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

From: Hafizul Farhan RAHMAT (SPF) [mailto:Hafizul Farhan RAHMAT@spf.gov.sg]
Sent: Wednesday, 7 August 2019 2:29 PM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>; SUR <sur@lkkauto.com>; Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>
Subject: Request for Pre-Repair Survey of SKM9520H (vs GZ3294D & SHC1373G) DOA: 1/8/2019

Hi,

Kindly conduct Pre-repair survey for SKM9520H at

**JWG INTERNATIONAL PTE LTD
BLK 10 AMK IND PARK 2A
#03-08 AMK AUTOPOINT
SINGAPORE 568047**

Contact: KELVIN / HP: 9069 7882

Thank you.

Best Regards,

*Hafizul Farhan Bin Rahmat
AEMD / PLD
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4850*



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.
www.avg.com

COMFORTDELGRO ENGINEERING PTE LTD
 #205 Braddell Road
 Blk C Ext 1 3rd Level
 Singapore 579701



VICOM LTD
 385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 8555
 Facsimile (65) 6458 1040

WWW.VICOM.COM.SG
 Company Registration No. 193343008

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 547284	Claim No.	: 305321956
Accident Date	: 01/08/2019	Claim Type	: THIRD PARTY
Assignment Date	: 02/08/2019	Policy No.	:
Survey Date	: 02/08/2019	Finalised Dt.:	:
Survey Report Date	: 07/08/2019		
VEHICLE PARTICULARS			
Vehicle No.	: SHC1373G	Chassis No.	: KMHET41VMCA823078
Registration Date	: 19/04/2012	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1991 CC
Model	: SONATA	Transmission	: AUTO
		Colour	: BLUE
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 377480KM		
<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	215/60R16	HANKOOK	6
FRONT LH	215/60R16	HANKOOK	6
REAR RH	215/60R16	HANKOOK	6
REAR LH	215/60R16	HANKOOK	6
SURVEY CONDUCTED AT			
ComfortDelGro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969. Assignment given by: MVA Chiang (C.D.G.E.)			
REMARKS			
[1]Workshop Estimate : S\$ 9,356.42 [2]Our Adjustment : S\$ 5,250.00 [3]Repair Period : 4 days [4]We have not authorised repairs. This survey was carried out on without prejudice basis.			

Sin Ming
 385 Sin Ming Drive Singapore 575718

Bukit Batok
 511 Bukit Batok Ct 23 Singapore 670545

Kaki Bukit
 23 Kaki Bukit Ave 4 Singapore 415003

VICOM LTD
SURVEY REPORT

HC1373G @ 01/08/2019

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (\$)	VAC Adjustment (\$)
1	1	Boot Lid	Dented	2174.90	2174.90
2	1	Boot Lid Lock Upper X reuse	Distorted	132.10	132.10
3	1	Boot Lid Lock Lower X reuse	Distorted	31.70	31.70
4	1	Boot Lid Sonata Plate X not Added	Necessary	43.60	43.60
5	1	Boot Lid Hyundai Plate	Necessary	24.20	24.20
6	1	Boot Lid H Emblem	Necessary	26.10	26.10
7	1	Boot Lid Crdi Plate	Necessary	22.70	22.70
8	2	Boot Lid Lamp Rh/Lh LH cut RH x 3/4	Snapped/Cracked	1131.20	1131.20
9	1	Rear Bumper	Deformed	578.40	578.40
10	1	Rear Bumper Reinforcement	Snapped	483.30	483.30
11	10	Rear Bumper Clips	Necessary	22.00	22.00
	1	Rear Bumper Bracket X SVC	Necessary	49.00	49.00
13	1	Rear Bumper Sponge X SVC	Snapped	137.40	137.40
14	1	Rear Bumper Under Cover	Snapped	228.00	228.00
15	2	Rear Bumper Protector Lh/Rh X repair	Snapped	76.00	76.00
16	2	Tail Lamp Rh/Lh	Reuse	1395.60	0.00
17	1	Rear Panel X repair	Thrusted Inward	526.70	526.70
18	1	Rear Panel Garnish X reuse	Deformed	95.80	95.80
19	1	Front Bumper	Repair	538.80	0.00
20	2	Front Bumper Protector Rh/Lh	Reuse	58.40	0.00
			Subtotal	7775.90	5783.10
		Less 20 %		1555.18	1156.62
			TOTAL	6220.72	4626.48

SPECIAL NETT ITEM

1	1	Front Number Plate	Dented	25.00	25.00
2	1	Boot Lid Comfort Logo & Tel No. Sticker	Necessary	30.00	30.00
3	1	Rear Number Plate	Reuse	25.00	0.00
4	1	Rear Bumper Advertisement Logo	Necessary	50.00	50.00
5	2	Rear Fender Advertisement Rh/Lh	Necessary	200.00	200.00
6	1	Rear Bumper Reverse Sensor	Malfunction	135.70	135.70
			TOTAL	465.70	440.70

TOTAL FOR SPARE PARTS : **6686.42** **5067.18**

VICOM LTD
SURVEY REPORT

SHC1373G @ 01/08/2019

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	1250.00	600.00 500
2	Spray painting charges	1050.00	800.00
3	Wiring charges	50.00	20.00
4	Tuff kote	50.00	40.00 30
5	Remove/ refix reverse sensor	120.00	60.00 20
6	Remove/ refix rear exhaust pipe (waived)	150.00	0.00
TOTAL FOR LABOUR AND SPRAY PAINTING		2670.00	1520.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	6686.42	5067.18
TOTAL FOR LABOUR AND SPRAY PAINTING	2670.00	1520.00
TOTAL REPAIR COST	9356.42	6587.18

SURVEY REPORT

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained front and rear damage.

The damages seen during our survey were at front bumper, rear bumper, rear panel, boot lid and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$9,356.42. We adjusted it to S\$6,587.18 on a part-by-part basis.

As this vehicle was more than 7 years old during the accident, we assess repairs on a lumpsum basis is appropriate. By applying the market discount of 20% from the part-by-part repairs, the re-adjusted repair cost on lumpsum basis is S\$5,269.74, round upto S\$5,270.00 .

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$5,250.00.

The repairs would require a period of 4 working days.



Kamarudin Abdul Kadir
for VICOM Ltd

L/s \$4050 / 4 Days



Your Ref: AEMD/105/009/2019/081

Date: 01st November 2019

Our Ref: CS1/SPF19019154/K1sf3s2

M/s Automotive Engineering & MGT Division
Accident Claim Section (Singapore Police Force)
1 Mount Pleasant Road
Blk 8 Old Police Academy
Singapore 298333

Attn: Hafizul Farhan

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SHC 1373G
INSURED VEHICLE: GZ 3294D ACCIDENT DATE: 01/08/2019**

We thank you for your instruction on 30/10/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHC 1373G from M/s Vicom Ltd.
- b) Damaged vehicle photographs of SHC 1373G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHC 1373G
Make & Model	: Hyundai Sonata
Year of Registration	: 2012
Chassis Number	: KMHET41VMCA823078
Engine Capacity	: 1991 cc
2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1373G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	DENTED	2,174.90	2,174.90
1	BOOT LID LOCK UPPER	REUSE	132.10	-
1	BOOT LID LOCK LOWER	REUSE	31.70	-
1	BOOT LID SONATA PLATE	NOT FITTED	43.60	-
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID H EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP RH/LH	N/S CUT / O/S SERVICEABLE	1,131.20	565.60
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	SNAPPED	483.30	483.30
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET	SERVICEABLE	49.00	-
1	REAR BUMPER SPONGE	SERVICEABLE	137.40	-
1	REAR BUMPER UNDER COVER	SNAPPED	228.00	228.00
2	REAR BUMPER PROTECTOR LH/RH	TO REPAIR SEE LABOUR	76.00	-
2	TAIL LAMP RH/LH	REUSE	1,395.60	-
1	REAR PANEL	TO REPAIR SEE LABOUR	526.70	-
1	REAR PANEL GARNISH	REUSE	95.80	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	538.80	-
2	FRONT BUMPER PROTECTOR RH/LH	REUSE	58.40	-
	LESS 20% DISCOUNT		-1,555.18	-825.04
			6,220.72	3,300.16
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	DENTED	25.00	25.00
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE (SN)	REUSE	25.00	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT RH/LH (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	135.70	135.70
			465.70	440.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR BUMPER PROTECTOR LH/RH, REAR PANEL AND FRONT BUMPER.		1,250.00	500.00
	SPRAY PAINTING CHARGES.		1,050.00	800.00
	WIRING CHARGES.		50.00	20.00
	TUFF KOTE.		50.00	30.00
	REMOVE / REFIX REVERSE SENSOR.		120.00	30.00
	REMOVE / REFIX REAR EXHAUST PIPE.	WAIVED	150.00	-
			2,670.00	1,380.00
	GRAND TOTAL		9,356.42	5,120.86
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CS1/SPF19019154/K1sf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 - \$5,000.00

RECOMMENDED REPAIR DAYS : 4

WEEKENDS : 2

TOTAL DAYS : 6

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.