

ASS. REC. BY:

REF: CS/FCI 19019157/UVf3n2

Special Instruction:

Surveyor: MAKUS

ASSIGNMENT (Office)

From (Person): Kari

of FCI

Date/Time: 30.10.19 12.57p.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SPW 59P

Insured: SHC 8566X

at Workshop m/c: Zoom Automotiks

Tel: 94507920

of 130 Bedok Reservoir Road #06-1369

Policy No:

Claim No: D19006843MPSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30.10.19 1.05p.m

Person Contacted: Elin

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: Blk 15 Kale Buta Rd 4 #01-53 Banting Bz
	SPW 59P - NS/NC19019134/1912/1913 D.O.A - 26/10/2019
	SHC 8566X - NS/NC19019134/1912/1913 R.O.A - 26/10/2019
31/10/19	Informed FCI pending workshop est by email
26/12/19	Email preli revised to FCI

ASS. FILED BY:

MCCUS

RDR:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 20099 Smith plus-Dep 16k.

26/12/19 4/5 #7900 confirmed with Elin (Red 14, 864-65, 657)

mv: \$28K (EST) LTA: \$20,099 NV: \$7901

RECEIVED 26 DEC 2019

Date/Time, File Pass 10?

1)

Date/Time, File Return to?

2) 26/12 - typist

Report Formed:

Lump Sum / LBS:

CWS

L/S \$7900/2

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Week end %

Survey Fee:

Transportation:

3 + Rpt. St

Photos

Others:

580

26/12/19

12x15=180

170+180

50

50+50+50

133

683



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006843MFSH

Our ref: CS/FCI19019157/Uvf3

DATE:26/12/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO SFW 59P


We thank for your instruction on 30/10/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 30/10/2019 at the premises of M/s ZOOM AUTOWERKS PTE LTD

Workshop Estimate Amount	: S\$22,764.65
Revised Estimate Amount	: S\$7,900.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s rear portion. The undercarriage affected due to collision



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-10-2019	Our Ref No. D19006843MFSH
Accident Date	25-10-2019	Claim Type. Third Party
Insured Vehicle	SHC8566X	Third Party Vehicle. SFW59P
Survey Location	130 BEDOK RESERVOIR ROAD#08-1339	
Contact Person.	ELIN CAI	
Contact No.	0/ 94507920	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ZOOM AUTOWERKS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 December 2019 8:46 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Karen Tan'
Subject: RE: SURVEY ASSESSMENT - D19006843MFSH/1-SFW 59P
Attachments: SFW 59P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SFW 59P
Date of survey: 30/10/2019
Number of days (estimated) : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 31 October 2019 10:31 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006843MFSH/1-SFW 59P

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SFW 59P on 30/10/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 30 October 2019 1:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006843MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Wednesday, 30 October, 2019 12:57 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19006843MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 31 October 2019 10:31 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Karen Tan'
Subject: RE: SURVEY ASSESSMENT - D19006843MFSH/1-SFW 59P

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SFW 59P on 30/10/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Wednesday, 30 October 2019 1:08 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006843MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 30 October, 2019 12:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006843MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.

Home » Used Cars » Sanctuary Motor » Audi Q5 2.0A TFSI

Audi Q5 2.0A TFSI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$28,000
Depreciation ⓘ N.A.

 Reg Date 21-Apr-2010
(5mths 14days COE left)

Mileage 183,500 km (19.2k /yr)

 Manufactured ⓘ 2010

Road Tax ⓘ \$1,194 /yr

 Transmission Auto

Dereg Value ⓘ \$19,980 as of today (change)

 OMV ⓘ \$37,968

COE ⓘ \$21,899

 ARF ⓘ \$37,968

Engine Cap 1,984 cc

 Power 155.0 kW (207 bhp)

Curb Weight ⓘ 1,740 kg

 No. of Owners ⓘ 4
Type of Vehicle SUV**Features**

2L 4. Cylinders Turbocharged Engine, 207Bhp With 350Nm Of Torque, 7 Speed Gearbox, AWD. View specs of the Audi Q5 (2009-2017)

Accessories

Audi Infotainment System, 19" Sports Rims, Sunroof, Reverse Camera.

Description

Ideal For 10 Years COE Renewal, Please Call In Advance.

Category

PARF Car


Status

Available

Resources
[Compare](#)
[tion](#)

? Request to have this car evaluated professionally. Find out more

https://www.sgcarmart.com/used_cars/info.php?ID=842521&DL=1269



Location Map

[Shortlist](#)
[Compare](#)
[Report Error](#)
[More Action](#)
Seller Information

Company	Sanctuary Motor » dealer's price » 31 vehs sold
Address	22 Jalan Pari B Search cars near
Office No	64568382 / 6
Contact Person(s)	Roy Rich

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	658E
Vehicle Details	
Vehicle No.:	SFW59P
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Nov 2019
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	CDN074298
Chassis No.:	WAUZZZ8R6AA038233
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$38,620.00
Original Registration Date:	05 Apr 2010
First Registration Date:	05 Apr 2010
Transfer Count:	3
Actual ARF Paid:	\$38,620.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Apr 2020
PARF Rebate Amount:	\$19,310.00 ✓
Intended COE Rebate Details	
COE Expiry Date:	04 Apr 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$19,889.00
COE Rebate Amount:	\$789.00
Total Rebate Amount:	\$20,099.00

The information contained herein is correct as at 06 Nov 2019

OK



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Vehicle Number : SFW59P

Model : AUDI Q5 2.0 TFSI

Damaged Area: (Front Left Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Not Authorized

30/10/19

7 Jan 19900

L/S * 2/3/19/19

limited Repaired

Parts / Material :

- 1 Front Bumper 1669.22
- 2 Front Bumper Attachment Fixing Parts
- 3 Front Bumper Lower Spoiler 629.00
- 4 Front Bumper Closing Elements
- 5 Front Bumper Securing Strip
- 6 Front Bumper Air-Guide Grille 215.00
- 7 Front Bumper Air-Guide Grille Section
- 8 Front Bumper Angle Sensor 185.00
- 9 Front Bumper Angle Sensor Ring Set
- 10 Front Bumper Sensor Harness
- 11 Front Bumper Hallogen Fog Lamp 255.00
- 12 Front Bumper Foam
- 13 Front Bumper Reinforcement
- 14 Front Fender LH
- 15 Front Fender LH Attachment Fixing Parts
- 16 Front Fender Fender Bracket
- 17 Front Fender Centre Bracket
- 18 Front Fender Pop Riverts 12pcs Each Sides
- 19 Front Wheel Housing Liner
- 20 Front Wheel Housing Attachment Fixing Parts
- 21 Mounting For Main Headlight Beam
- 22 Headlamp Assy for Gas Discharge Lamp 2605 x 2 = 5210
- 23 Headlamp Lift Cylinder Washer System
- 24 Headlamp Washer Jet
- 25 Radiator Grille Assy 1400.00
- 26 Radiator Grille Upper Garnish
- 27 Lock Carrier

Quantity

\$ 2.3	2,237.00	✓
\$ 1.2	256.00	X
\$ 2.3	640.00	✓
\$ 1.2	180.00	X
\$ 64.00 X 2pcs	128.00	X
\$ 307.00 X 2Pcs	614.00	1pc
\$ 42.00 X 2pcs	84.00	X
\$ 298.00 X 4pcs	1,192.00	1pc
\$ 14.00 X 4pcs	56.00	X
\$ 1.2	556.00	X
\$ 298.00 X 2pcs	596.00	1pc
\$ 1.2	197.00	X
\$ 1.2	702.00	X
\$ 307.00	969.00	✓
\$ 1.2	58.00	X
\$ 47.00 X 2pcs	94.00	X
\$ 43.00 X 2pcs	86.00	X
\$ 35.00 X 2sets	70.00	X
\$ 281.00 X 2pcs	562.00	✓
\$ 1.2	89.00	X
\$ 115.00 X 2pcs	230.00	X
\$ 2,614.00 X 2pcs	5,228.00	✓
\$ 195.00 X 2pcs	390.00	X
\$ 298.00 X 2pcs	596.00	1pc
\$ 320	1,750.00	✓
\$ 1.2	196.00	X
\$ 1.2	891.00	✓
Parts : \$	18,647.00	
Less Parts 5% : \$	932.35	
Total Parts : \$	17,714.65	

Special Net Items :

- Front Number Plate With Garnish
Front LH Aluminium Rim
Radiator Coolant

\$ 1.2	80.00	14
\$ 1.2	1,185.00	X
\$ 1.2	85.00	X
Total S/N Parts : \$	1,350.00	

12283.22
11054.89

- To Remove & Renew Front Affected Accident Areas
- To Putty, Spray Paint on Front Affected Accident Areas
- To Check & Re-Connect all electrical wiring
- To Conduct AC Leakage Test & Top Up AC Gas
- To Conduct All Wheel Alignment
- To Re-Programme & Reset Diagnostic
- To Rust Proof Affected Areas

\$	1,500.00	680
\$	1,500.00	700
\$	50.00	20
\$	150.00	100
\$	150.00	80
\$	250.00	X
\$	100.00	X
Total Labour :	\$ 3,700.00	

TOTAL PARTS :	\$	17,714.65
TOTAL SPECIAL NET ITEM :	\$	1,350.00
TOTAL LABOUR :	\$	3,700.00
TOTAL REPAIR COST :	\$	<u>22,764.65</u>

1264f. ff

LKK Auto Consultants hence notify the Repairer of the following:

- Car must be driven to a safe parking
- The damaged and parts during resurvey
- The car must be kept on a safe condition
- The car must be on a "Without Prejudice" basis
- The car must be insured & allowed
- Super insurance must be resurveyed and as subject to final approval from Insurance Company

Acknowledged by Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19019157/Uvf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-01-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8566X	Veh. Inspected	SFW 59P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006843MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	30/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q5 (A)	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8R6AA038233	Colour	BLACK	
Odometer	148083	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/50 R19	FALKEN	6 mm	
L/H Front Tyre	255/50 R19	FALKEN	6 mm	
R/H Rear Tyre	255/50 R19	FALKEN	6 mm	
L/H Rear Tyre	255/50 R19	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/10/2019	Inspection Date	30/10/2019	
Survey held at	BLK 15 KAKI BUKIT ROAD 4 #01/53 BARTLEY BIZ #01-53			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFW 59P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	2,237.00	1,669.22
1	FRONT BUMPER ATTACHMENT FIXING PARTS	NOT NECESSARY	256.00	-
1	FRONT BUMPER LOWER SPOILER	DISTORTED	640.00	629.00
1	FRONT BUMPER CLOSING ELEMENTS	NOT NECESSARY	180.00	-
2	FRONT BUMPER SECURING STRIP @\$64.00	NOT NECESSARY	128.00	-
2	FRONT BUMPER AIR-GUIDE GRILLE @\$307.00	N/S DISTORTED	614.00	215.00
2	FRONT BUMPER AIR-GUIDE GRILLE SECTION @\$42.00	NOT NECESSARY	84.00	-
4	FRONT BUMPER ANGLE SENSOR @\$298.00	N/S TORN (1 PC ONLY)	1,192.00	185.00
4	SET FRONT BUMPER ANGLE SENSOR RING @\$14.00	NOT NECESSARY	56.00	-
1	FRONT BUMPER SENSOR HARNESS	NOT NECESSARY	556.00	-
2	FRONT BUMPER HALOGEN FOG LAMP @\$298.00	N/S CRACKED	596.00	255.00
1	FRONT BUMPER FOAM	NOT FITTED	197.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	702.00	-
1	FRONT FENDER LH	BENT / BUCKLED	969.00	969.00
1	FRONT FENDER LH ATTACHMENT FIXING PARTS	NOT NECESSARY	58.00	-
2	FRONT FENDER FENDER BRACKET @\$47.00	NOT NECESSARY	94.00	-
2	FRONT FENDER CENTRE BRACKET @\$43.00	NOT NECESSARY	86.00	-
2	SETS FRONT FENDER POP RIVETS 12 PCS EACH SIDES @\$35.00	NOT NECESSARY	70.00	-
2	FRONT WHEEL HOUSING LINER @\$281.00	TORN	562.00	562.00
1	FRONT WHEEL HOUSING ATTACHMENT FIXING PARTS	NOT NECESSARY	89.00	-
2	MOUNTING FOR MAIN HEADLIGHT BEAM @\$115.00	NOT NECESSARY	230.00	-
2	HEADLAMP ASSY FOR GAS DISCHARGE LAMP @\$2614.00	CRACKED	5,228.00	5,210.00
2	HEADLAMP LIFT CYLINDER WASHER SYSTEM @\$195.00	NOT NECESSARY	390.00	-
2	HEADLAMP WASHER JET @\$298.00	N/S CRACKED	596.00	298.00
1	RADIATOR GRILLE ASSY	BROKEN	1,750.00	1,400.00
1	RADIATOR GRILLE UPPER GARNISH	NOT NECESSARY	196.00	-
1	LOCK CARRIER	CRACKED	891.00	891.00
	LESS 5% DISCOUNT		-932.35	-

Report Ref No. CS/FCI19019157/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-	-1,228.32
			17,714.65	11,054.90
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH GARNISH (SN)	CRACKED	80.00	14.00
1	FRONT LH ALUMINIUM RIM (SN)	TO REPAIR SEE LABOUR	1,185.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	85.00	-
			1,350.00	14.00
	LABOUR			
	TO REMOVE & RENEW FRONT AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF FRONT LH ALUMINIUM RIM.		1,500.00	680.00
	TO PUTTY,SPRAY PAINT ON FRONT AFFECTED ACCIDENT AREAS.		1,500.00	700.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	20.00
	TO CONDUCT AC LEAKAGE TEST & TOP UP AC GAS.		150.00	100.00
	TO CONDUCT ALL WHEEL ALIGNMENT.		150.00	80.00
	TO RE-PROGRAMME & RESET DIAGNOSTIC.	NOT NECESSARY	250.00	-
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	100.00	-
			3,700.00	1,580.00
	GRAND TOTAL		22,764.65	12,648.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,900.00

Report Ref No. CS/FC19019157/Uvf3n2

MARKET VALUE: \$28,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,099.00=NETT VALUE: \$7,901.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.