



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005984
INV Date 01/09/2020
Reference CC4/LPC19019159/Gba3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SLC 752E
Insured Veh. SBL 1181S
Claim No. 19/19/19/VP05/022575
Policy No. Z19VP05024785
Accident Date 27/10/2019
Inspection Date 31/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19019159/Gba3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 01-09-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBL 1181S	Veh. Inspected	SLC 752E
Policy No.	Z19VP05024785	Coverage (\$)	0.00
Claim No.	19/19/19/VP05/022575	Excess (\$)	0.00
Assign From	GERALD	Assign Date	30/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA 1.5G	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707009825	Colour	BLUE
Odometer	79036	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	DUNLOP	6 mm
L/H Front Tyre	185/60 R15	DUNLOP	6 mm
R/H Rear Tyre	185/60 R15	DUNLOP	6 mm
L/H Rear Tyre	185/60 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/10/2019	Inspection Date	31/10/2019
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 752E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	1,014.00	535.10
2	FRONT BUMPER SIDE RETAINER @\$84.00	NOT NECESSARY	168.00	-
1	FRONT BUMPER FOGLAMP O/S	NOT NECESSARY	476.00	-
1	FRONT BUMPER FOGLAMP GARNISH O/S	CUT	193.00	113.00
1	FRONT BUMPER LOWER COWLING	NOT NECESSARY	243.00	-
1	HEADLAMP O/S	CUT	2,908.00	1,287.50
1	HEADLAMP LOWER BRACKET O/S	NOT NECESSARY	61.00	-
1	HEADLAMP SUPPORT O/S	NOT NECESSARY	316.00	-
1	BONNET	NOT NECESSARY	973.00	-
2	BONNET HINGE @\$77.00	NOT NECESSARY	154.00	-
1	BONNET SEAL	NOT NECESSARY	34.00	-
1	FRONT FENDER O/S	NOT NECESSARY	878.00	-
1	FRONT FENDER INNER COWLING O/S	NOT NECESSARY	185.00	-
1	FRONT SHOCK ABSORBER O/S	NOT NECESSARY	313.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING O/S	NOT NECESSARY	76.00	-
1	FRONT WHEEL BEARING O/S	NOT NECESSARY	229.00	-
1	FRONT KNUCKLE O/S	NOT NECESSARY	395.00	-
1	FRONT LOWER ARM O/S	NOT NECESSARY	353.00	-
1	FRONT ARB ENDLINK O/S	NOT NECESSARY	106.00	-
1	FRONT BUMPER GRILLE	NOT NECESSARY	569.00	-
1	FRONT BUMPER GRILLE CHROME MOULDING	NOT NECESSARY	227.00	-
1	FRONT BUMPER LOWER GRILLE	SCRATCHED	318.00	285.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	56.00	-
	LESS 25% DISCOUNT		-2,561.25	-555.15
			7,683.75	1,665.45
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIPS @\$4.50 (SN)	NECESSARY	45.00	45.00
10	BONNET INSULATOR CLIPS @\$4.50 (SN)	NOT NECESSARY	45.00	-
8	FRONT FENDER INNER COWLING O/S CLIPS @\$4.50 (SN)	NOT NECESSARY	36.00	-
1	FRONT ALLOY WHEEL R15 O/S (SN)	NOT NECESSARY	450.00	-

Report Ref No. CC4/LPC19019159/Gba3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE 185/65 R15 O/S (SN)	NOT NECESSARY	280.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			906.00	45.00
	LABOUR			
	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.		1,200.00	200.00
	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS.		50.00	30.00
	TO REMOVE AND REPLACE O/S FRONT TYRE & RIM.TO PERFORM TYRE BALANCING.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT O/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS.	NOT NECESSARY	150.00	-
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER,BONNET,O/S FRONT FENDER AND OTHER AFFECTED AREA/PANEL.		1,200.00	200.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR.	NOT NECESSARY	100.00	-
			2,850.00	430.00
GRAND TOTAL			11,439.75	2,140.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC4/LPC19019159/Gba3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 752E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 752E

RE-INSPECTION

