


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA SIENTA
 Engine/Chassis No.: NSP1707009825
 Date of accident:
 Damaged area: O/S Front

Date: 31/10/2019
 Claim Type: TP
 VRN: SLC752E



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Front bumper ✓ cut	1	\$ 1,014.00	\$ 1,014.00	535.1
2	Front bumper side retainer x nn	2	\$ 84.00	\$ 168.00	
3	Front bumper foglamp o/s x nn	1	\$ 476.00	\$ 476.00	
4	Front bumper foglamp garnish o/s ✓ cut	1	\$ 193.00	\$ 193.00	113
5	Front bumper lower cowling x nn	1	\$ 243.00	\$ 243.00	
6	Headlamp o/s ✓ cut	1	\$ 2,908.00	\$ 2,908.00	1287.5
7	Headlamp lower bracket o/s x nn	1	\$ 61.00	\$ 61.00	
8	Headlamp support o/s x nn	1	\$ 316.00	\$ 316.00	
9	Bonnet x nn	1	\$ 973.00	\$ 973.00	
10	Bonnet hinge x nn	2	\$ 77.00	\$ 154.00	
11	Bonnet seal x nn	1	\$ 34.00	\$ 34.00	
12	Front fender o/s x nn	1	\$ 878.00	\$ 878.00	
13	Front fender inner cowling o/s x nn	1	\$ 185.00	\$ 185.00	
14	Front shock absorber o/s x nn	1	\$ 313.00	\$ 313.00	
15	Front shock absorber top mounting o/s x nn	1	\$ 76.00	\$ 76.00	
16	Front wheel bearing o/s x nn	1	\$ 229.00	\$ 229.00	
17	Front knuckle o/s x nn	1	\$ 395.00	\$ 395.00	
18	Front lower arm o/s x nn	1	\$ 353.00	\$ 353.00	
19	Front ARB endlink o/s x nn	1	\$ 106.00	\$ 106.00	
20	Front bumper grille x nn	1	\$ 569.00	\$ 569.00	
21	Front bumper grille chrome moulding x nn	1	\$ 227.00	\$ 227.00	
22	Front bumper lower grille ✓ scr	1	\$ 318.00	\$ 318.00	285
23	Front bumper tow cover x nn	1	\$ 56.00	\$ 56.00	
Subtotal				\$ 10,245.00	2220.6
List discount				25.00%	
Total				\$ 7,683.75	1665.45

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Front bumper clips ✓ nec	10	\$ 4.50	\$ 45.00
2	Bonnet insulator clips x nn	10	\$ 4.50	\$ 45.00
3	Front fender inner cowling o/s clips x nn	8	\$ 4.50	\$ 36.00

Repair Estimate

4	Front alloy wheel R15 o/s	x nn	1	\$ 450.00	\$ 450.00
5	Front tyre 185/65R15 o/s	x nn	1	\$ 280.00	\$ 280.00
6	Sundries	x nn	1	\$ 50.00	\$ 50.00
Total					\$ 906.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and replace o/s front tyre & rim. To perform tyre balancing.	0.25	\$ 50.00
4	To remove and refit o/s front undercarriage for replacement of parts.	0.75	\$ 150.00
5	To conduct computerized wheel alignment.	0.5	\$ 100.00
6	Supply spray paint material and necessary items to respray front bumper, bonnet, o/s front fender and other affected area / panel.	6	\$ 1,200.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,850.00

200
30
x nn
x nn
x nn
200
x nn
430

Estimate Grand Total	\$ 11,439.75
-----------------------------	---------------------

2140.45
20%: 1700

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: