

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19019162/AHA3Q2

**Date:** 11/05/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SGD9312L **Insured Vehicle No :** SJX2848M

**Date of Loss:** 28/10/2019 **Nature of Claim:** TP **Claim No:** 9003415352SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SGD9312L  
**Make & Model:** BMW 420I COUPE, 2.0 AT D/AB HID SR NAV M SPORT (A) **Engine No:** A8690960N20B20B  
**Reg. Date:** 14/01/2015 (Man. Year: 2014) **Chassis No:** WBA4A12010GK06028  
**Colour:** Blue **Odometer:** 87066 km  
**Engine Capacity:** 1997 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 225/40 R19 **Rear Tyre Size:** 225/40 R19  
**Front Left Side:** Yokohama 6 mm **Rear Left Side:** Yokohama 6 mm  
**Front Right Side:** Yokohama 6 mm **Rear Right Side:** Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts  | 10,624.01         | 6,190.76          | 4,433.25          | 41.73         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour   | 3,040.00          | 800.00            | 2,240.00          | 73.68         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>13,664.01</b>  | <b>6,990.76</b>   | <b>6,673.25</b>   | <b>48.84</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>5,600.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 13,664.01         | 5,600.00          | 8,064.01          | 59.02         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 956.48            | 392.00            | 564.48            | 59.02         |
| <b>Nett Amount (S\$)</b>                         | <b>14,620.49</b>  | <b>5,992.00</b>   | <b>8,628.49</b>   | <b>59.02</b>  |
| <b>+ Loss of Use (3.0 x S\$100.00/day) (S\$)</b> |                   | 300.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 7.45              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>6,299.45</b>   |                   |               |

### INSPECTION

**Date of Assignment:** 29/10/2019

**Date Inspected:** 29/10/2019 Inspected At:

MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933

**Estimated Period of Repair:** 3.0 days

---

**Adjuster:** ADRIAN LING**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition            | Repairer's  | Amount       |
|-----|-----|----------|---|----------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                             | Torn                 | 2,300.00 FL | *1,980.00 FL |
| 2   | 2   |          | *FRONT BUMPER SIDE RETAINER               | Not Necessary        | 260.00 FL   | *- FL        |
| 3   | 1   |          | *FRONT BUMPER CENTRE INNER GRILLE         | Torn                 | 255.30 FL   | *255.30 FL   |
| 4   | 1   |          | *FRONT BUMPER LOWER GRILLE                | Torn                 | 388.20 FL   | *388.20 FL   |
| 5   | 1   |          | *FRONT BUMPER REINFORCEMENT               | Not Necessary        | 1,250.00 FL | *- FL        |
| 6   | 1   |          | *FRONT BUMPER REINFORCEMENT SPONGE        | Cracked              | 210.00 FL   | *210.00 FL   |
| 7   | 2   |          | *FRONT BUMPER REVERSE SENSOR              | Damaged (1 PCS ONLY) | 640.00 FL   | *250.00 FL   |
| 8   | 1   |          | *FRONT BUMPER REVERSE SENSOR WIRE HARNESS | Not Necessary        | 450.00 FL   | *- FL        |
| 9   | 1   |          | *FRONT NUMBER PLATE GARNISH               | Torn                 | 122.30 FL   | *122.30 FL   |
| 10  | 1   |          | *FRONT CENTRE GRILLE CHROME               | N/S Cracked          | 760.00 FL   | *215.00 FL   |
| 11  | 1   |          | *HEADLAMP LH                              | Cracked              | 4,200.00 FL | *2,980.00 FL |
| 12  | 1   |          | *FRONT NUMBER PLATE                       | Cracked              | 100.00 FS   | *80.00 FS    |
| 13  | 1   |          | *SET FRONT BUMPER CLIPS                   | Necessary            | 30.00 FS    | *30.00 FS    |
| 14  | 1   |          | *SET FRONT BUMPER LOWER GRILLE CLIPS      | Not Necessary        | 100.00 FS   | *- FS        |
| 15  | 1   |          | *SET HEADLAMP CLIPS                       | Not Necessary        | 100.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 11,165.80 6,510.80**  
**- List Item Discount on L Items 5.00/5.00% (\$\$) 541.79 320.04**

**Total Parts (\$\$) 10,624.01 6,190.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars  | Lab.Type | Repairer's      | Amount        |
|---------------------------------|--|----------|-----------------|---------------|
| <b><u>Labour Items</u></b>      |  |          |                 |               |
| 1                               | PANEL BEATING ,REMOVING AND REPLACING PARTS  | New      | 1,000.00        | 300.00        |
| 2                               | SPRAY PAINTING TO AFFECTED AREA  | New      | 1,000.00        | 250.00        |
| 3                               | TUFF COAT  | New      | 250.00          | 0.00          |
| 4                               | WIRING CHECK   | New      | 150.00          | 30.00         |
| 5                               | REMOVE AND REFIX FRONT REVERSE SENSOR  | New      | 160.00          | 60.00         |
| 6                               | REMOVE AND REFIX FRONT CAMERA  | New      | 180.00          | 60.00         |
| 7                               | TO CHECK DIAGNOSTICS OF VEHICLE<br>MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO<br>SPECIFICATION ETC | New      | 300.00          | 100.00        |
| <b>Gross Labour Cost (\$\$)</b> |  |          | <b>3,040.00</b> | <b>800.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >