

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019167/AKA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SLX7155Y **Insured Vehicle No :** SFD9393P

Date of Loss: 26/10/2019 **Nature of Claim:** TP **Claim No:** 0104890983SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7155Y		
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Engine No:	3ZRB712450
Reg. Date:	06/04/2018 (Man. Year: 2015)	Chassis No:	ZSU600070143
Colour:	Black	Odometer:	37872 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,077.00	4,130.75	3,946.25	48.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	2,110.00	870.00	29.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,057.00	6,240.75	4,816.25	43.56
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	11,057.00	5,000.00	6,057.00	54.78
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
Nett Liability (S\$)		5,720.00		

INSPECTION

Date of Assignment: 29/10/2019

Date Inspected: 29/10/2019 Inspected At:

Flying High Spray Painting (HQ)
BLK 1 Kaki Bukit Ave 6, #01-29 Auto
Bay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,343.00 F	*1,343.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Necessary	130.00 F	*130.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Deformed	489.00 F	*489.00 FL
5	1		*REAR BUMPER REFLECTOR	O/S Cracked	176.00 F	*88.00 FL
6	1		*REAR BUMPER SPONGE	Cracked	182.00 F	*182.00 FL
7	1		*REVERSE SENSOR	Damaged	480.00 FS	*380.00 FS
8	1		*REAR END PANEL	Dented	715.00 F	*715.00 FL
9	1		*REAR END PANEL TOP GARNISH	Deformed	367.00 F	*367.00 FL
10	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
11	1		*TAILLAMP	O/S Cracked	962.00 F	*481.00 FL
12	1		*TAILLAMP LOWER BRACKET	O/S Cracked	130.00 F	*65.00 FL
13	1		*TAILGATE	Repair	1,712.00 F	*- FL
14	1		*TAILGATE LOCK	Damaged	418.00 F	*418.00 FL
15	1		*TAILGATE WEATHERSTRIPE	Cut	353.00 F	*353.00 FL
16	1		*HARRIER WORDING	Necessary	74.00 F	*74.00 FL
17	1		*TAILGATE GLASS MOULDING	Not Necessary	210.00 F	*- FL
18	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 FS	*- FS
19	1		*TAILGATE LOCK SENSOR	Cracked	186.00 F	*186.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,077.00	5,361.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,230.25
Total Parts (\$\$)	8,077.00	4,130.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	900.00
2	SPRAY PAINTING	New	1,000.00	900.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE TAILGATE FITTINGS	New	150.00	80.00
7	TO REMOVE TAILGATE GLASS	New	180.00	0.00
8	TO UNDERSEAL	New	150.00	60.00
Gross Labour Cost (\$\$)			2,980.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >