



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Ref: CS/INC19019170/T1yf3e2

Date: 03-08-2020



ATTN : DAVID

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | GBC 628A       | <b>Veh. Inspected</b> | XE 3444Y   |
| <b>Policy No.</b>   |                | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | MT/1065964-002 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | THERESA VIMALA | <b>Assign Date</b>    | 30/10/2019 |

### 2. Vehicle Particulars & Condition

|                         |                    |                     |          |
|-------------------------|--------------------|---------------------|----------|
| <b>Make &amp; Model</b> | NISSAN CGB45CLSMNB | <b>c.c</b>          | 13074    |
| <b>Engine No.</b>       | HIDDEN             | <b>Year of Reg.</b> | 2007     |
| <b>Chassis No.</b>      | CGB4CLS00110       | <b>Colour</b>       | WHITE    |
| <b>Odometer</b>         | 330909 KM          | <b>Steering</b>     | IN ORDER |
| <b>Brakes</b>           | IN ORDER           | <b>Modification</b> | NIL      |
| <b>General</b>          | GOOD               |                     |          |

### 3. Conditions of Tyres

|                       | Size             | Make     | Balance |
|-----------------------|------------------|----------|---------|
| <b>R/H Front Tyre</b> | 295/80 R22.5     | ROADWING | 8 mm    |
| <b>L/H Front Tyre</b> | 295/80 R22.5     | ROADWING | 8 mm    |
| <b>R/H Rear Tyre</b>  | 295/80 R22.5 (D) | ROADWING | 8/8 mm  |
| <b>L/H Rear Tyre</b>  | 295/80 R22.5 (D) | ROADWING | 8/8 mm  |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |   |                            |                         |
|-----------------------|---|----------------------------|-------------------------|
| <b>Accident Date</b>  | 07/10/2019  | <b>Inspect Date / Time</b> | 30/10/2019 ( 03:21 PM ) |
| <b>Survey held at</b> | C L AUTO PTE LTD<br>48 TOH GUAN ROAD EAST<br>#02-127 ENTERPRISE HUP<br>SINGAPORE 608586 |                            |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

|  |                       |
|--|-----------------------|
| <b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b> | <b>7 Working Days</b> |
|--|-----------------------|