

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19019175/QGA3Q2

**Date:** 27/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMA5461K	<b>Insured Vehicle No :</b>	SHA7555U
Date of Loss: 28/10/2019	Nature of Claim: TP	Claim No: MCT19100659

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA5461K	Engine No:	LEB5599628
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71066576
Reg. Date:	12/06/2018 (Man. Year: 2018)	Odometer:	114553 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,739.20	3,098.80	640.40	17.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,540.00	500.00	24.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,779.20</b>	<b>4,638.80</b>	<b>1,140.40</b>	<b>19.73</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	404.54	324.72	79.82	19.73
<b>Nett Amount (\$\$)</b>	<b>6,183.74</b>	<b>4,963.52</b>	<b>1,220.22</b>	<b>19.73</b>
<b>+ Car Rental (7.0 x S\$107.00/day) (\$\$)</b>		749.00		
	<b>Nett Liability (\$\$)</b>	<b>5,712.52</b>		

### INSPECTION

Date of Assignment:	11/11/2019	
Date Inspected:	11/11/2019	Inspected At:
		Hua Hong Pte Ltd (Sungei Kadut)
		25D Sungei Kadut Street 1
		Singapore 729332
Estimated Period of Repair:	6.0 days	

**Adjuster:** OI SUN PIN

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
<b>Parts:</b>	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMA5461K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,050.60 FL	*1,050.60 FL
2	10		*REAR BUMPER CLIP	Necessary	39.00 FL	*30.00 FL
3	2		*REAR BUMPER RETAINER (LH/RH)	Necessary (1 PCS ONLY)	49.80 FL	*24.90 FL
4	2		*REAR BUMPER REFLECTOR (LH/RH)	Serviceable	85.60 FL	*- FL
5	1		*REAR TAILGATE	Dented	1,100.80 FL	*1,100.80 FL
6	1		*REAR TAILGATE LOCK	Broken	151.80 FL	*151.80 FL
7	1		*REAR TAILGATE LOGO (FREED)	Necessary	55.00 FL	*55.00 FL
8	1		*REAR TAILGATE LOGO (HYBRID)	Necessary	75.00 FL	*75.00 FL
9	1		*REAR TAILGATE CHROME GARNISH	Serviceable	320.30 FL	*- FL
10	1		*REAR EMBLEM	Necessary	27.40 FL	*27.40 FL
11	1		*REAR TAILGATE WEATHER STRIP	Broken	168.00 FL	*168.00 FL
12	1		*REAR WINDSCREEN MOULDING	Necessary	151.30 FL	*151.30 FL
13	1		*REAR END PANEL	Dented	623.70 FL	*623.70 FL
14	1		*REAR END PANEL TOP GARNISH	Broken	115.00 FL	*115.00 FL
15	1		*REAR REVERSE LAMP (LH)	Serviceable	360.70 FL	*- FL
16	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
17	1		*SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,614.00</b>	<b>3,813.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	874.80	714.70
<b>Total Parts (\$\$)</b>	<b>3,739.20</b>	<b>3,098.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE & CUT & WELD REAR END PANEL,CHARGE REAR BUMPER,REAR TAILGATE ,REAR LH REVERSE LAMP ,KNOCKING & PULL STRAIGH REAR TYRE FLOOR PANEL AND ALL AREA AFFECTED BY ACCIDENT	New	900.00	700.00
2	TO PERFORM WIRE CHECKING	New	20.00	20.00
3	TO DISMANTLE & REFIT REAR WINDSCREEN	New	100.00	100.00
4	TO DISMANTLE & TRANSFER REAR TAILGATE MECHANISM AND FITTING TO NEW TAILGATE	New	60.00	60.00
5	TO DISMANTLE & REFIT REAR BUMPER SENSOR	New	60.00	60.00
6	TO SPRAY REAR TAILGATE ,REAR BUMPER,REAR PANEL AND REAR TYRE FLOOR PANEL	New	900.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,040.00</b>	<b>1,540.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >