

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19019181/ASF3E2

Date: 15/10/2020

REFERENCE

Insured/Claimant:	HO GEOK ENG	Policy No:	
Date of Loss:	27/10/2019	Nature of Claim:	OD Claim No: 0227718936SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG3673X	Engine No:	CYG009319
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G2GN075995
Reg. Date:	31/03/2016 (Man. Year: 2015)	Odometer:	48218 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$105,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,322.00	12,086.24	7,235.76	37.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,772.00	3,022.00	2,750.00	47.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,094.00	15,108.24	9,985.76	39.79
- Excess (\$\$)	400.00	400.00	0.00	0.00
(\$\$)	24,694.00	14,708.24	9,985.76	40.44
+ GST 7.00/7.00% (\$\$)	1,728.58	1,029.58	699.00	40.44
Nett Amount (\$\$)	26,422.58	15,737.82	10,684.76	40.44

INSPECTION

Date of Assignment:	30/10/2019	
Date Inspected:	30/10/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,443.00 FS	*1,954.40 FS
2	1		*FRONT BUMPER GRILLE	Not Necessary	598.00 FS	*- FS
3	18		*FRONT BUMPER LOCKING CLIP	Not Necessary	65.00 FS	*- FS
4	1		*FRONT BUMPER CHROME TRIM	Not Necessary	276.00 FS	*- FS
5	1		*FRONT BUMPER FIXING PARTS	Not Necessary	45.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	199.00 FS	*- FS
7	1		*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,412.80 FS
9	1		*RADIATOR GRILLE COVER	Not Necessary	33.00 FS	*- FS
10	2		*FRONT PARKING AID SENSOR - LH / RH	Not Necessary	122.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	319.00 FS	*- FS
12	1		*FRONT BUMPER COVER - LH	Not Necessary	46.00 FS	*- FS
13	1		*FRONT WHEEL SPOILER - LH	Cracked	242.00 FS	*193.20 FS
14	1		*STONE CHIP GUARD	Necessary	66.00 FS	*52.72 FS
15	1		*ADHESIVE TAPE	Necessary	50.00 FS	*40.00 FS
16	2		*HEADLIGHT WASHER COVER CAP - LH / RH	Not Necessary	104.00 FS	*- FS
17	1		*HEADLIGHT HOSE	Not Necessary	413.00 FS	*- FS
18	1		*LIFT CYLINDER - LH	Damaged	216.00 FS	*172.40 FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	215.00 FS	*- FS
20	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	754.00 FS	*- FS
21	1		*FRONT BUMPER COVER	Not Necessary	112.00 FS	*- FS
22	1		*FRONT BUMPER GUIDE PIECE - LH	Damaged	34.00 FS	*27.12 FS
23	1		*FRONT BUMPER BRACE - LH	Not Necessary	27.00 FS	*- FS
24	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
25	1		*FRONT FENDER - LH	Buckled	1,269.00 FS	*1,015.20 FS
26	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	92.00 FS	*- FS
27	1		*STONE GUARD FILM - LH	Necessary	110.00 FS	*88.00 FS
28	1		*FRONT FENDER BRACE - LH	Not Necessary	75.00 FS	*- FS
29	1		*FRONT WHEEL HOUSING LINER - LH	Torn	256.00 FS	*204.80 FS
30	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PAR	Not Necessary	66.00 FS	*- FS
31	1		*FRONT TRIM BRACKET - LH	Not Necessary	15.00 FS	*- FS
32	1		*HEADLIGHT MOUNTING - LH	Not Necessary	107.00 FS	*- FS
33	1		*LED HEADLIGHT - LH	Cut	8,607.00 FS	*6,885.60 FS
34	1		*FRONT NO PLATE	Necessary	40.00 FS	*40.00 FS
35	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 19,322.00 12,086.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,300.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,772.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >