



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005481
INV Date 11/08/2020
Reference CC6/CTI19019186/Kks3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SMG 3816C
Insured Veh. SJW 1642B
Claim No. SNM19D205129C02/2
Policy No. DMPCSN3037221900
Accident Date 24/10/2019
Inspection Date 29/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19019186/Kks3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-08-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 1642B	Veh. Inspected	SMG 3816C
Policy No.	DMPCSN3037221900	Coverage (\$)	0.00
Claim No.	SNM19D205129C02/2	Excess (\$)	0.00
Assign From		Assign Date	29/10/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0310272	Colour	WHITE
Odometer	123067	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	4 mm
L/H Front Tyre	205/60 R16	MICHELIN	4 mm
R/H Rear Tyre	205/60 R16	MICHELIN	5 mm
L/H Rear Tyre	205/60 R16	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/10/2019	Inspection Date	29/10/2019
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 3816C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	1,006.00	1,006.00
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	187.00	-
1	TAILGATE MAZDA LOGO	NECESSARY	79.00	79.00
1	TAILGATE SKYCITY EMBLEM	NECESSARY	67.00	67.00
1	TAILGATE -MAZDA 3 EMLEM	NECESSARY	57.00	57.00
1	TAILGATE REFLECTOR	CRACKED	490.00	490.00
1	END PANEL	BENT	551.00	551.00
1	END PANEL TOP GARNISH	CRACKED	168.00	168.00
1	BOOT WEATHERSTRIP	SERVICEABLE	114.00	-
1	TAILLAMP	CRACKED	867.00	867.00
1	REAR BUMPER	BENT	947.00	947.00
1	REAR BUMPER RETAINER	DISTORTED	38.00	38.00
1	REAR BUMPER ENFORACEMENT	BENT	565.00	565.00
1	REAR BUMPER TOW COVER	MISSING	18.00	18.00
1	REAR BUMPER REFLECTOR	SERVICEABLE	53.00	-
1	BUMPER CLIP /FENDER COWLING CLIP	NOT NECESSARY	42.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,083.00	-
1	FRONT GARNISH	BUCKLED	351.80	351.80
1	GRILLE	CRACKED	610.70	610.70
	LESS 20% DISCOUNT		-	-1,163.10
			7,294.50	4,652.40
1	SPARE TYRE PANEL (ADDITIONAL)	TO REPAIR SEE LABOUR	551.00	-
	LESS 20% DISCOUNT		-110.20	-
			440.80	-
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			220.00	200.00

Report Ref No. CC6/CTI19019186/Kks3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS-RR. CUT N WELD DAMAGED PANEL REPAIR /RESHAPE DENTED AREAS REPLACE /ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF TAILGATE LOCK,FRONT BUMPER AND SPARE TYRE PANEL .		950.00	800.00
	TO SPRAY PAINT.		800.00	800.00
	CUT N WELD DAMAGED FRONT REPLACE PARTS. (ADDITIONAL)		550.00	300.00
	TO APPLY RUST PROOFING.(ADDITIONAL)		160.00	60.00
	TO SPRAY PAINT.(ADDITIONAL)		500.00	400.00
			2,960.00	2,360.00
	GRAND TOTAL		10,915.30	7,212.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,750.00

Report Ref No. CC6/CTI19019186/Kks3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3816C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3816C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMG 3816C

RE-INSPECTION

