

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Koh Ming Shao

Date: 04 Nov 2019

Preliminary Advice

Insured Vehicle No : SLT679U
TP Vehicle No : SHC8493Y
Make : HYUNDAI I40
Date of Inspection : 31/10/2019
Inspection At : Soon Hock Motor Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Singapore 568047
Accident Date : 30/10/2019
Assignment Date : 31/10/2019
Est. Duration of Repair : 6 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,620.48 |
| Revised Amount | :S\$ | 7,262.48 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 7,262.48 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.