

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG19019230/KQF3Q2

**Date:** 07/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SMN2337M **Insured Vehicle No :** SMA7736E

**Date of Loss:** 27/10/2019 **Nature of Claim:** TP **Claim No:** 4961916850SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	<b>SMN2337M</b>	<b>Engine No:</b>	A3190709L77X0134
<b>Make &amp; Model:</b>	OPEL INSIGNIA, 1.6 Turbo (A)	<b>Chassis No:</b>	W0VZM6EF1K1057189
<b>Reg. Date:</b>	29/07/2019 (Man. Year: 2019)	<b>Odometer:</b>	17573 km
<b>Colour:</b>	Metallic Dark Blue		
<b>Engine Capacity:</b>	1598 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$):</b>	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,708.00	3,859.29	12,848.71	76.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,480.00	980.00	1,500.00	60.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>19,188.00</b>	<b>4,839.29</b>	<b>14,348.71</b>	<b>74.78</b>
<b>Approved Total (Overridden) (\$)</b>		<b>3,850.00</b>		
<b>(\$)</b>	19,188.00	3,850.00	15,338.00	79.94
<b>+ GST 7.00/7.00% (\$)</b>	1,343.16	269.50	1,073.66	79.94
<b>Nett Amount (\$)</b>	<b>20,531.16</b>	<b>4,119.50</b>	<b>16,411.66</b>	<b>79.94</b>

### INSPECTION

Date of Assignment: 31/10/2019

Date Inspected: 31/10/2019 Inspected At:

Aero Garage Pte Ltd (HQ)  
160 Sin Ming Auto City, #08-13  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	2,450.00 F	*1,150.24 FL
2	1		*REAR BUMPER CENTRE BRACKET	Cracked	230.00 F	*230.00 FL
3	1		*REAR BUMPER RETAINERS	O/s Distorted	140.00 F	*70.00 FL
4	2		*REAR BUMPER REINFORCEMENT	Bent	880.00 F	*646.00 FL
5	1		*REAR BUMPER LOWER GARNISH	Bent/Cracked	875.00 F	*309.60 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
7	1		*REAR BOOTLID	Repair	3,120.00 F	*- FL
8	1		*TAILLAMPS	O/s Cut	2,240.00 F	*970.00 FL
9	1		*REAR END PANEL	Repair	2,780.00 F	*- FL
10	1		*REAR END PANEL TOP GARNISH	Mtg Distorted	493.00 F	*109.20 FL
11	1		*REAR SPARE TYRE COMPARTMENT	Repair	1,920.00 F	*- FL
12	1		*REVERSE SENSOR (4 Pcs)	Dented/Shorted (2 Pcs only)	1,480.00 F	*490.00 FL
13	1		*REAR NUMBER PLATE	Cracked	60.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (S\$) 16,708.00 4,060.04**  
**- List Item Discount on L Items 0.00/5.00% (S\$) 0.00 200.75**

**Total Parts (S\$) 16,708.00 3,859.29**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGE TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS	New	1,200.00	500.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS	New	800.00	400.00
3	TO REMOVE,REPLACE REAR TAILGATE FITTINGS TO FACILITATE REPAIR	New	250.00	0.00
4	TO REMOVE,REPLACE REVERSE SENSOR	New	150.00	60.00
5	TO CHECK WIRING AND LIGHTINGS	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,480.00</b>	<b>980.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >