

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19019231/EVF3N2
Date: 12/11/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D19MTMC01001612
Claimant Vehicle No : SHA8729D **Insured Vehicle No :** FBP2274E
Date of Loss: 30/10/2019 Nature of Claim: TP Claim No: CMTD1905077

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA8729D**
Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4FDGU695431
Reg. Date: 22/12/2016 (Man. Year: 2016) Chassis No: KMHLB41UMHU097223
Colour: Yellow Odometer: 462108 km
Engine Capacity: 1685 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Triangle 5 mm Rear Left Side: Triangle 5 mm
Front Right Side: Triangle 5 mm Rear Right Side: Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,404.18	772.46	631.72	44.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	430.00	200.00	31.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,034.18	1,202.46	831.72	40.89
Approved Total (Overridden) (S\$)		950.00		
(S\$)	2,034.18	950.00	1,084.18	53.30
+ GST 7.00/7.00% (S\$)	142.39	66.50	75.89	53.30
Nett Amount (S\$)	2,176.57	1,016.50	1,160.07	53.30

INSPECTION

Date of Assignment: 30/10/2019
Date Inspected: 01/11/2019 Inspected At: 31 Corporation Road
Estimated Period of Repair: 2.0 days Repairer: Ding Auto Pte Ltd

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2019)

Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/SHA8729D/12/11/2019 08:26

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	599.68 FL	*599.68 FL
2	1		*REAR BUMPER DIFFUSER	Cut	228.40 FL	*228.40 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	484.40 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT SPONGE	Not Necessary	98.99 FL	*- FL
5	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*30.00 FS
6	1		*REAR BUMPER ADS STICKER	Necessary	120.00 FS	*80.00 FS
7	1		*REAR BUMPER PROTECTOR PAD	Not Necessary	120.00 FS	*- FS
					Sub Total (\$\$)	1,686.47 938.08
					- List Item Discount on L Items 20.00/20.00% (\$\$)	282.29 165.62
					Total Parts (\$\$)	1,404.18 772.46

F=Franchise part. S=SpcNett. L=ListItemDisc.

LKK Auto Consultants Pte Ltd/SHA8729D/12/11/2019 08:26. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	350.00	200.00
2	RESPRAY REAR BUMPER	New	250.00	200.00
3	CHECK WIRING & LIGHTING SYSTEM	New	30.00	30.00
Gross Labour Cost (\$\$)			630.00	430.00

LKK Auto Consultants Pte Ltd/SHA8729D/12/11/2019 08:26. Not valid without Reference section.

< END OF ESTIMATES >