

AIG



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SME 4476 D

Parts	(a) Cost / List Price Items	\$	8,961.31
	Plus/Less 25%	\$	2,240.33
	Total of Cost / List	\$	6,720.98
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	295.00
Total Parts Cost		\$	7,015.98
Labour		\$	2,740.00
Total		\$	9,755.98

The above total will be subjected to 7% G.S.T.

*Not Authorized
Resurvey B4 paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 29/10/19 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
- (b) Recommended Days of Repair : 08 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$ _____
- (e) Signature of surveyor : Le Date: 29/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SME 4476 D**
Make & Model : **TOYOTA PRIUS ALPHA**
Chassis No : **ZVW400029990**

Submit By : **SERENCE**
Year Manufacture : **2018**
Engine No. : **2ZR0B92392**

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear number plate	1	\$45.00	S.N	X
2	Rear No.plate garnish	1	\$388.50		X
3	Rear windscreen moulding	1			X
4	Rear windscreen sealant	1	\$50.00	S.N	4012
5	Reverse sensor	2	\$200.00	S.N	✓
6	Rear bumper	1	\$489.30		✓
7	Rear bumper clip	10	\$40.00		✓
8	Rear bumper side retainer LH	1	\$107.40		X
9	Rear bumper side retainer RH	1	\$107.40		X
10	Rear bumper reflector LH	1	\$57.80		X
11	Rear bumper reflector RH	1	\$57.80		X
12	Tail door	1	\$972.40		✓
13	Tail door lock	1	\$391.60		✓
14	Tail door emblem	1	\$67.80		X
15	Wording "Priuscx"	1	\$76.61		✓
16	Wording "HYBRID SYNERGY"	1	\$45.81		✓
17	Tail door trim	1	\$391.73		?
18	Tail door trim clip	10	\$45.00		?
19	Rear wiper motor link	1	\$622.70		?
20	Rear wiper arm	1	\$49.70		X
21	Rear wiper blade	1	\$38.73		X
22	Tail end panel	1	\$678.10		✓
23	Tail end panel garnish	1	\$184.10		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Vehicle No. :

Submit By :

Make & Model :

TOYOTA PRIUS ALPHA

Year Manufacture :

2018

Chassis No :

ZVW400029990

Engine No. :

2ZR0B92392

[illegible]

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SME 4476 D** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	\$1,000.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, TAILDOOR, SPARE TYRE COMPARTMENT)	\$1,000.00	800
3	To tuff coat.	\$150.00	60
4	TO Check wiring	\$50.00	20
5	To transfer boot mechanism to new boot	\$120.00	60
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To remove & refit reverse sensor	\$150.00	50
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.