

ASS. REC. BY:

REF:

CS/FCI19019236/Avf3n2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Marina Chia

of

FCI

Date/Time: 31/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 2009U

Insured: SHA 8614T

at Workshop m/s N-51

Tel: 68420051

of 2 Kaki Bukit Ave 2 #01-18

Policy No:

Claim No:

D19006883MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 31/10

Person Contacted:

Zi Ting

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SLX 2009U-X
	SHA 8614T-X
11/11/19	Informed FCI pending workshop est by email
5/3/20	Adrian confirmed LS \$ 4850 (Ref 2238-24, 327)
5/3/20	Email preh revised to FCI



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19006883MFSH

Our ref: CS/FCI19019236/Avf3

Date : 5/3/2020

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLX 2009U


We thank you for your instruction on 31/10/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/11/2019 at the premises of M/s N-51 AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$7,088.24
Revised Estimate Amount	: S\$4,850.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	30-10-2019	Our Ref No. D19006883MFSH
Accident Date	29-10-2019	Claim Type. Third Party
Insured Vehicle	SHA8617T	Third Party Vehicle. SLX2009U
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veh Out

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 5 March 2020 3:14 PM
To: SUR; 'CWS Motor Claims'
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19006883MFSH/1-SLX 2009U
Attachments: SLX 2009U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLX 2009U
Date of survey: 11/11/2019
Number of days (estimated) : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 November 2019 4:59 PM
To: SUR <sur@lkkauto.com>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006883MFSH/1-SLX 2009U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLX 2009U on 11/11/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 31 October 2019 11:21 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006883MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 November 2019 4:59 PM
To: SUR; 'CWS Motor Claims'
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19006883MFSH/1-SLX 2009U

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLX 2009U on 11/11/2019.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 31 October 2019 11:21 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006883MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLX2009U
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Mar 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	LEB5924816
Chassis No.:	RU31224803
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$23,431.00
Original Registration Date:	20 Mar 2018
First Registration Date:	20 Mar 2018
Transfer Count:	1
Actual ARF Paid:	\$14,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Mar 2028
PARF Rebate Amount:	\$11,103.00
Intended COE Rebate Details	
COE Expiry Date:	19 Mar 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,001.00
COE Rebate Amount:	\$31,347.00
Total Rebate Amount:	\$42,450.00

The information contained herein is correct as at 05 Mar 2020

OK

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 96901047

TP 1st Cap.
Veron.

ESTIMATE

Repair Code : CLM15730

Date in : 29/10/2019

Vehicle Num. : SLX2009U

Model : HONDA VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31224803/LEB5924816

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Replaced</i>	1	762.70	762.70 ✓
REAR BUMPER LOWER COVER <i>torn</i>	1	250.00	250.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>seen</i>	2	23.00	46.00 ✓
REAR END PANEL <i>Replaced</i>	1	415.60	415.60 ✓
REAR END PANEL ANTENNA SENSOR <i>Replaced</i>	1	60.10	60.10 ✓
REAR END PANEL BUZZLE SENSOR	1	85.20	85.20 ✓
REAR END PANEL INNER TOP GARNISH <i>Replaced</i>	1	98.00	98.00 ✓
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>Replaced</i>	1	485.30	485.30 ✓
REAR FLOOR PANEL INNER TOP BOARD COVER <i>Replaced</i>	1	430.30	430.30 ✓
REAR RH BUMPER SIDE <i>Replaced</i>	1	195.00	195.00 ✓
REAR RH TAILLAMP <i>checked</i>	1	474.60	474.60 ✓
REAR TAILGATE <i>Replaced</i>	1	953.30	953.30 ✓
REAR TAILGATE 'HYBRID' EMBLEM <i>Replaced</i>	1	75.80	75.80 ✓
REAR TAILGATE 'VEZEL' EMBLEM	1	56.20	56.20 ✓
REAR TAILGATE INNER PULL GARNISH <i>seen</i>	1	27.50	27.50 +
REAR TAILGATE INNER TRIM GARNISH <i>seen</i>	1	153.40	153.40 +
REAR TAILGATE MECHANISM LOCK <i>Replaced</i>	1	180.00	180.00 ✓
REAR TAILGATE MECHANISM LOCK STRIKER <i>Replaced</i>	1	27.50	27.50 +



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 96901047

ESTIMATE

Repair Code : CLM15730

Date in : 29/10/2019

Vehicle Num. : SLX2009U

Model : HONDA VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31224803/LEB5924816

REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	18.50	37.00	4
REAR TAILGATE WEATHER STRIP	1	96.80	96.80	4
REAR TAILGATE WINDSCREEN INNER SEAL	2	50.00	100.00	60
REAR TAILGATE WINDSCREEN MOULDING	2	50.00	100.00	60
Subtotal before discount			5,110.30	
Percentage discount 20%			1,022.06	
Sub-total 1			4,088.24	
REAR BUMPER CLIPS - SET	1	50.00	50.00	30
REAR BUMPER REVERSE SENSOR - SET	1	250.00	250.00	20
REAR RH TAILLAMP CLIPS - SET	1	20.00	20.00	1
REAR TAILGATE ARTWORK STICKER	1	250.00	250.00	150
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00	4
Subtotal before discount			620.00	
Percentage discount 0%			0.00	
Sub-total 2			620.00	
Parts-total			4,708.24	

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

50.00 30

120.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 96901047

ESTIMATE

Repair Code : CLM15730

Date in : 29/10/2019

Vehicle Num. : SLX2009U

Model : HONDA VEZEL 1.5 HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31224803/LEB5924816

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

100.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1,000.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

950.00

To apply anti-rust chemical on repaired and replaced panel.

80.00

To remove, reinstall tailgate mechanism and check for function

80.00

Labour Total

2,380.00

Parts & Labour Total

7,088.24

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
2/5 11/11/19.
06 Days.

total: 6100.48

4/5: 4850 ✓



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19019236/Avf3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-03-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8617T	Veh. Inspected	SLX 2009U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006883MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	31/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	RU31224803	Colour	WHITE	
Odometer	142579	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DAVANTI	6 mm	
L/H Front Tyre	215/60 R16	DAVANTI	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/10/2019	Inspection Date	11/11/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 2009U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	762.70	762.70
1	REAR BUMPER LOWER COVER	TORN	250.00	250.00
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	NECESSARY	46.00	46.00
1	REAR END PANEL	DENTED	415.60	415.60
1	REAR END PANEL ANTENNA SENSOR	CRACKED	60.10	60.10
1	REAR END PANEL BUZZLE SENSOR	CRACKED	85.20	85.20
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	98.00	98.00
1	REAR FLOOR PANEL COMPARTMENT TRAY GARNISH	DEFORMED	485.30	485.30
1	REAR FLOOR PANEL INNER TOP BOARD COVER	DEFORMED	430.30	430.30
1	REAR RH BUMPER SIDE	DEFORMED	195.00	195.00
1	REAR RH TAILLAMP	CRACKED	474.60	474.60
1	REAR TAILGATE	DENTED	953.30	953.30
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	75.80	75.80
1	REAR TAILGATE "VEZEL" EMBLEM	NECESSARY	56.20	56.20
1	REAR TAILGATE INNER PULL GARNISH	NOT NECESSARY	27.50	-
1	REAR TAILGATE INNER TRIM GARNISH	NOT NECESSARY	153.40	-
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	180.00	180.00
1	REAR TAILGATE MECHANISM LOCK STRIKER	NOT NECESSARY	27.50	-
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R @\$18.50	NOT NECESSARY	37.00	-
1	REAR TAILGATE WEATHER STRIP	NOT NECESSARY	96.80	-
2	REAR TAILGATE WINDSCREEN INNER SEAL @\$50.00	NECESSARY	100.00	60.00
2	REAR TAILGATE WINDSCREEN MOULDING @\$50.00	NECESSARY	100.00	60.00
	LESS 20% DISCOUNT		-1,022.06	-937.62
			4,088.24	3,750.48
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR RH TAILLAMP CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR TAILGATE ARTWORK STICKER (SN)	NECESSARY	250.00	150.00

Report Ref No. CS/FCI19019236/Avf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
			620.00	400.00
	LABOUR			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		50.00	30.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		120.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		100.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	800.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		950.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		80.00	60.00
	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.		80.00	80.00
			2,380.00	1,950.00
GRAND TOTAL			7,088.24	6,100.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,850.00

Report Ref No. CS/FCI19019236/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.