

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019245/FTF3N2
Date: 12/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30728318000
Claimant Vehicle No :	GBH1521R	Insured Vehicle No :	GBE4547M
Date of Loss:	26/10/2019	Nature of Claim:	TP
			Claim No: SNM19D205093C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH1521R	Engine No:	1KD2753248
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	KDH2015029757
Reg. Date:	29/01/2018 (Man. Year: 2017)	Odometer:	83665 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Firemax 7 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Firemax 7 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,952.00	2,888.75	1,063.25	26.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.00	1,140.00	250.00	17.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,342.00	4,028.75	1,313.25	24.58
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,342.00	3,200.00	2,142.00	40.10
+ GST 7.00/7.00% (S\$)	373.94	224.00	149.94	40.10
Nett Amount (S\$)	5,715.94	3,424.00	2,291.94	40.10

INSPECTION

Date of Assignment:	31/10/2019	
Date Inspected:	16/01/2020	Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	4.0 days	

Adjuster: PARASURAM SHANMUGAM

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Feb 2020)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/GBH1521R/12/02/2020 17:40	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,200.00 FL	*800.00 FL
2	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	105.00 FL	*85.00 FL
3	1		*LH FRONT MIRROR	Broken	950.00 FL	*800.00 FL
4	1		*LH FRONT MIRROR COVER	Scratched	65.00 FL	*50.00 FL
5	1		*FRONT WHEEL CAP LH	Scratched	165.00 FL	*80.00 FL
6	1		*REAR WHEEL CAP LH	Repair	165.00 FL	*- FL
7	1		*FRONT HEADLAMP LH	Scratched	2,506.00 FL	*1,950.00 FL
8	1		*SEALANT	Necessary	60.00 FS	*40.00 FS
9	1		*IU BRACKET	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,241.00	3,830.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,289.00	941.25
Total Parts (\$\$)	3,952.00	2,888.75

LKK Auto Consultants Pte Ltd/GBH1521R/12/02/2020 17:40. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	500.00	400.00
2	LABOUR FOR SPRAYPAINTING	New	700.00	600.00
3	WIRING	New	40.00	40.00
4	LABOUR FOR REMOVE & REPLACE FRONT WINDSCREEN GLASS	New	150.00	100.00
Gross Labour Cost (S\$)			1,390.00	1,140.00

LKK Auto Consultants Pte Ltd/GBH1521R/12/02/2020 17:40. Not valid without Reference section.

< END OF ESTIMATES >