

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019246/AES3N2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700082349
Claimant
Vehicle No : SJP863Z **Insured Vehicle No :** SLT9255A
Date of Loss: 29/10/2019 Nature of Claim: TP Claim No: 5472734694SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJP863Z**
Make & Model: NISSAN SYLPHY, 1.6 (A) Engine No: HR16937222C
Reg. Date: 17/12/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0033851
Colour: Bronze Odometer: 13190 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,873.60	3,397.59	12,476.01	78.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	1,230.00	2,210.00	64.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,313.60	4,627.59	14,686.01	76.04
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	19,313.60	3,700.00	15,613.60	80.84
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,067.45		

INSPECTION

Date of Assignment: 31/10/2019
Date Inspected: 31/10/2019 Inspected At: Ho Beng Trading (HQ)
Blk 3020A #01-33, Ubi Road 1
Singapore 408714
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	685.00 F	*685.00 FL
2	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
3	1		*FRONT BUMPER FOG LAMP COVER -RH	Not Necessary	120.00 F	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	561.90 F	*- FL
5	1		*FRONT BUMPER INNER SPONGE	Not Necessary	222.40 F	*- FL
6	2		*FRONT BUMPER BRACKET	Not Necessary	336.80 F	*- FL
7	1		*FRONT SUPPORT PANEL	Not Necessary	669.60 F	*- FL
8	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	307.00 F	*- FL
9	1		*FRONT BUMPER TOWING COVER	Not Necessary	56.10 F	*- FL
10	1		*FRONT BUMPER SIDE BRACKET	O/S Necessary	134.40 F	*67.20 FL
11	1		*FRONT BUMPER CENTER LOWER GARNISH	Not Necessary	215.00 F	*- FL
12	8		*FRONT BUMPER CLIPS	Not Necessary	40.00 F	*- FL
13	8		*FRONT BUMPER CLIPS	Necessary	28.00 F	*28.00 FL
14	1		*FRONT GRILLE	Not Necessary	315.00 F	*- FL
15	1		*FRONT GRILLE CENTRE GARNISH	Not Necessary	325.00 F	*- FL
16	1		*FRONT GRILLE EMBLE LOGO	Not Necessary	50.00 F	*- FL
17	8		*FRONT GRILLE CLIPS	Not Necessary	40.00 F	*- FL
18	1		*FRONT HEADLAMP -RH	Cracked	855.00 F	*855.00 FL
19	1		*FRONT FENDER RH	Dented	585.20 F	*585.20 FL
20	1		*FRONT R/H FENDER COWLING	Not Necessary	115.20 F	*- FL
21	10		*FRONT R/H FENDER COWLING CLIPS	Not Necessary	35.00 F	*- FL
22	1		*FRONT R/H FENDER INNER SIDE COVER	Not Necessary	88.20 F	*- FL
23	6		*FRONT L/H FENDER INNER SIDE COVER CLIPS	Not Necessary	30.00 F	*- FL
24	1		*FRONT R/H FENDER SIGNAL LAMP	Cracked	58.00 F	*58.00 FL
25	1		*FRONT DOOR -RH	Not Necessary	980.00 F	*- FL
26	1		*FRONT DOOR SIDE MIRROR -RH	Not Necessary	458.20 F	*- FL
27	1		*FRONT KNUCKLE ARM -RH	Damaged	367.90 F	*367.90 FL
28	1		*FRONT WHEEL BEARING -RH	Necessary	293.80 F	*293.80 FL
29	1		*FRONT DRIVESHAFT -RH	Not Necessary	877.70 F	*- FL
30	1		*FRONT STEERING RACK -RH	Not Necessary	1,552.70 F	*- FL
31	1		*FRONT SHOCK ABSORBER -RH	Bent	385.00 F	*385.00 FL
32	1		*FRONT RIM RH	Cut	450.00 F	*450.00 FL
33	1		*FRONT TYRE -RH	Not Necessary	350.00 F	*- FL
34	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	325.20 F	*- FL
35	6		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 F	*- FL
36	2		*REAR FENDER -RH	Not Necessary	957.50 F	*- FL
37	1		*REAR BUMPER	Not Necessary	784.40 F	*- FL
38	2		*REAR BUMPER SIDE BRACKET	Not Necessary	170.00 F	*- FL
39	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	300.00 F	*- FL
40	1		*REAR TAIL LAMP -RH	Not Necessary	388.20 F	*- FL
41	1		*REAR TYRE -RH	Not Necessary	350.00 F	*- FL
42	1		*REAR RIM -RH	Not Necessary	400.00 F	*- FL
43	1		*REAR SHOCK ABSORBER -RH	Not Necessary	325.00 F	*- FL
44	1		*REAR WHEEL BEARING -RH	Not Necessary	185.20 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	15,873.60	3,775.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	377.51
Total Parts (\$)	15,873.60	3,397.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	0.00
2	REMOVE AND REFIX FRONT & REAR RH UNDERCARRIAGE	New	400.00	220.00
3	TOWING FEE	New	100.00	0.00
4	WHEEL ALIGNMENT (COMPUTER)	New	120.00	80.00
5	TO CHECK WIRING SYSTEM	New	80.00	30.00
6	TO REMOVE & REFIX REAR CUSHION	New	120.00	0.00
7	TUFF KOTE	New	120.00	0.00
8	PANEL BEATING	New	1,200.00	500.00
9	SPRAY PAINTING	New	1,200.00	400.00
Gross Labour Cost (S\$)			3,440.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >