Adjuster Report Page 1 of 5

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19019252/KGA3Q2

**Date:** 09/02/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800114654

Claimant
Vehicle No: SHD9386L Insured Vehicle No: GBG7843C

Date of Loss: 26/10/2019 Nature of Claim: TP Claim No: 2915977444SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHD9386L

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2C03945

Reg. Date: 29/03/2019 (Man. Year: 2018) Chassis No: JTDKB3FUX03079660

Colour: Metallic Pearl White/Red Odometer: 115569 km

Engine Capacity: 1798 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Giti 9 mm Rear Left Side: Giti 9 mm
Front Right Side: Giti 9 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,572.85	736.75	9,836.10	93.03
Miscellaneous Items		0.00	0.00	0.00	
Labour		11,340.00	340.00	11,000.00	97.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	21,912.85	1,076.75	20,836.10	95.09
+	GST 7.00/7.00% (S\$)	1,533.90	75.37	1,458.53	95.09
	Nett Amount (S\$)	23,446.75	1,152.12	22,294.63	95.09
	+ Car Rental (4.0 x S\$	6113.40/day) (S\$)	453.60		
	+ Doc	/Search Fee (S\$)	7.45		
	N	lett Liability (S\$)	1,613.17		

**INSPECTION** 

Date of Assignment: 30/10/2019

Date Inspected: 30/10/2019 Inspected At: Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

# **REPAIR DETAILS**

## **Recommended Parts**

2	1				
		*REAR BUMPER	Repair	442.60 FL	*- FL
	1	*REAR BUMPER RE-INFORCEMENT	Bent	332.70 FL	*332.70 FL
3	1	*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*-FL
4	1	*REAR BUMPER UNDER COVER (BLACK)	Bent	576.30 FL	*576.30 FL
5	1	*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	
6	1	*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*-FL
7	1	*ANTENNA,ELECTRICAL KEY	Serviceable	72.00 FL	*-FL
8	1	*REAR TAILGATE	Repair	1,147.80 FL	*-FL
9	1	*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*-FL
10	1	*COVER,REAR COMBINATION LAMP,RH	Serviceable	64.50 FL	*-FL
11	1	*COVER,REAR COMBINATION LAMP,LH	Serviceable	64.50 FL	*-FL
12	1	*GARNISH,BACK DOOR SIDE,LH	Serviceable	95.60 FL	*- FL
13	1	*GARNISH,BACK DOOR SIDE,RH	Serviceable	95.60 FL	*-FL
14	1	*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	56.50 FL	*-FL
15	1	*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	56.50 FL	*-FL
16	1	*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	*-FL
17	1	*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	52.10 FL	*-FL
18	1	*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*-FL
19	1	*PANEL SUB-ASSY,BODY LOWER BACK	Serviceable	650.30 FL	*-FL
20	1	*TAILLAMP LOWER RH	Serviceable	502.00 FL	*-FL
21	1	*TAILLAMP UPPER RH	Serviceable	451.80 FL	*-FL
22	1	*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*-FL
23	1	*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*-FL
24	1	*TAILLAMP LOWER LH	Serviceable	502.00 FL	*-FL
25	1	*TAILLAMP UPPER LH	Serviceable	443.30 FL	*-FL
26	1	*BOARD,BACK DOOR TRIM	Serviceable	225.20 FL	*-FL
27	1	*PANEL ASSY,DECK TRIM SIDE,RH	Serviceable	355.90 FL	*-FL
28	1	*PANEL ASSY,DECK TRIM SIDE,LH	Serviceable	355.90 FL	*-FL
29	1	*COVER,DECK TRIM REAR	Serviceable	126.70 FL	*-FL
30	1	*COVER,FLOOR UNDER.NO 1	Serviceable	175.10 FL	*-FL
31	1	*COVER,FLOOR UNDER.NO 2	Serviceable	241.90 FL	*-FL
32	1	*COVER,REAR FLOOR	Serviceable	229.90 FL	*-FL
33	1	*SET PARKING AID	Serviceable	700.00 FS	*-FS
34	1	*SET REAR BUMPER CLIP	Necessary	55.00 FS	*55.00 FS
35	2	*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
36	1	*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
37	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
38	1	*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*-FS
39	1	*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*-FS
40	1	*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*-FS
41	1	*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
42	1	*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*-FS
43	1	*REAR BUMPER PROTECTOR		100.00 FS	*-FS

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
44	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*-FS
45	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*-FS
46	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*-FS
F=Fra	anchise	part. S=S	pcNett. L=ListItemDisc.			
				Sub Total (S\$)	12,915.55	964.00
			- List Item Discount on L Items 2	5.00/25.00% (S\$)	2,342.70	227.25
				Total Parts (S\$)	10,572.85	736.75
			Report was unsubmitted during this prin	t-out.		

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	220.00
3	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
13	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	4,500.00	120.00
	Gross Labour	Cost (S\$)	11,340.00	340.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >