

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19019253/AES3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800126331

**Claimant**  
**Vehicle No :** SLP1703Y **Insured Vehicle No :** SKU1727P

Date of Loss: 20/10/2019 Nature of Claim: TP Claim No: 6390711950SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP1703Y		
Make & Model:	OPEL ASTRA, 999cc HB (A)	Engine No:	B1163237GT2X0621
Reg. Date:	04/05/2017 (Man. Year: 2017)	Chassis No:	W0LBE8EA5H8040340
Colour:	Red	Odometer:	53134 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,169.10	4,585.90	5,583.20	54.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	830.00	2,590.00	75.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>13,589.10</b>	<b>5,415.90</b>	<b>8,173.20</b>	<b>60.15</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (\$\$)</b>		500.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>5,923.35</b>		

### INSPECTION

Date of Assignment: 30/10/2019

Date Inspected: 30/10/2019 Inspected At: Xin Hua Workshop Pte Ltd (HQ)  
23 Kaki Bukit Ave 4 #04-01  
Singapore 415933

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Deformed	1,966.00 FL	*1,966.00 FL
2	1		*RR BUMPER SPONGE	Cracked	180.00 FL	*180.00 FL
3	1		*RR BUMPER SIDE RETAINER RH	Necessary	154.00 FL	*154.00 FL
4	1		*RR BUMPER CENTER RETAINER	Necessary	160.00 FL	*160.00 FL
5	1		*RR BUMPER SIDE RETAINER LH	Necessary	154.00 FL	*154.00 FL
6	1		*RR BUMPER LOW BRACKET RH	Necessary	86.00 FL	*86.00 FL
7	1		*RR BUMPER LOW BRACKET LH	Necessary	86.00 FL	*86.00 FL
8	1		*RR BUMPER REINFORCEMENT	Bent	716.00 FL	*716.00 FL
9	1		*RR BUMPER LOW GARNISH	Cut	332.00 FL	*332.00 FL
10	4		*RR BUMPER REVERSE SENSOR	Damaged (1 PCS ONLY)	528.00 FL	*132.00 FL
11	4		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary (1 PCS ONLY)	48.00 FL	*12.00 FL
12	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	390.00 FL	*- FL
13	1		*RR BUMPER REFLECTOR LH	Not Necessary	144.00 FL	*- FL
14	1		*RR TAILGATE	Repair	2,488.00 FL	*- FL
15	1		*RR TAILGATE LOGO	Necessary	222.00 FL	*222.00 FL
16	1		*RR TAILGATE ASTRA EMBLEM	Necessary	174.00 FL	*174.00 FL
17	1		*RR TAILGATE ECO EMBLEM	Necessary	154.00 FL	*154.00 FL
18	1		*RR TAILGATE LOCK	Not Necessary	320.00 FL	*- FL
19	1		*RR TAILGATE LOCK CATCHER	Not Necessary	146.00 FL	*- FL
20	1		*RR TAILGATE LOCK KEYLESS RECEIVER SENSOR	Not Necessary	274.00 FL	*- FL
21	1		*RR TAILGATE WEATHER STRIP	Not Necessary	252.00 FL	*- FL
22	1		*RR TAILGATE STOPED	Not Necessary	56.00 FL	*- FL
23	1		*RR TAILGATE HANDS FREE SENSOR	Cracked	423.00 FL	*423.00 FL
24	1		*RR END PANEL	Not Necessary	816.00 FL	*- FL
25	1		*RR END PANEL TOP GARNISH	Not Necessary	280.00 FL	*- FL
26	10		*FENDER INNERSHIELD CLIP	Not Necessary	60.00 FS	*- FS
27	10		*RR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
28	10		*RR TAILGATE INNER TRIM BOARD CLIP	Not Necessary	60.00 FS	*- FS
29	10		*RR TAILGATE TOP SPOILER CLIP	Not Necessary	60.00 FS	*- FS
30	5		*RR END PANEL TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS
31	1		*RR WINDSCREEN SEALANT	Not Necessary	65.00 FS	*- FS
32	1		*RR WINDSCREEN INNER SEAL	Not Necessary	40.00 FS	*- FS
33	1		*RR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS
34	1		*RR TAILGATE EMBLEM	Necessary	40.00 FS	*40.00 FS
35	1		*RR TAILGATE VXR EMBLEM	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 11,224.00 5,081.00  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** 1,054.90 495.10

**Total Parts (\$\$)** 10,169.10 4,585.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	350.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR BUMPER ,RR END PANEL,RR TAILGATE ,RR TAILGATE TOP SPOILER ,RR FENDER RH ,RR FENDER LH	New	1,000.00	400.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	180.00	30.00
4	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	400.00	0.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	80.00	0.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	200.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIR OF VEHICLE	New	80.00	0.00
9	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	New	200.00	0.00
10	TO RESET FAULTY CODE	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,420.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >