

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019255/KRA3Q2

Date: 11/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800130066

Claimant
Vehicle No : SME2528B **Insured Vehicle No :** GBE4471Y

Date of Loss: 30/10/2019 Nature of Claim: TP Claim No: 7259842987SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME2528B		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB6720033
Reg. Date:	24/09/2018 (Man. Year: 2018)	Chassis No:	RU31300026
Colour:	Metallic Black	Odometer:	98295 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Neuton 9 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Neuton 9 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,592.20	7,415.84	1,176.36	13.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	1,610.00	940.00	36.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,142.20	9,025.84	2,116.36	18.99
+ GST 7.00/7.00% (S\$)	779.95	631.81	148.14	18.99
Nett Amount (S\$)	11,922.15	9,657.65	2,264.50	18.99
+ Car Rental (7.0 x S\$84.00/day) (S\$)		588.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,253.10		

INSPECTION

Date of Assignment: 31/10/2019

Date Inspected: 31/10/2019 Inspected At:

Esteem Performance Pte Ltd - Sin
Ming (HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	892.60 FL	*892.60 FL
2	1		*BONNET LOCK	Repair	98.50 FL	*- FL
3	1		*BONNET HINGE LH	Repair	48.50 FL	*- FL
4	1		*BONNET HINGE RH	Distorted	48.50 FL	*48.50 FL
5	1		*HEADLAMP RH	Cracked	1,820.20 FL	*1,820.20 FL
6	1		*HEADLAMP LOWER PANEL RH	Cracked	48.50 FL	*48.50 FL
7	1		*FRONT GRILLE BASE	Cracked	398.00 FL	*398.00 FL
8	1		*FRONT GRILLE CHROME	Cracked	480.00 FL	*480.00 FL
9	1		*FRONT GRILLE EMBLEM	Necessary	35.40 FL	*35.40 FL
10	1		*FRONT GRILLE LOWER	Serviceable	162.60 FL	*- FL
11	1		*FRONT SUPPORT PANEL (COMPLETE)	Bent	586.20 FL	*586.20 FL
12	1		*FRONT SUPPORT PANEL TOP GARNISH	Serviceable	105.00 FL	*- FL
13	10		*FRONT SUPPORT PANEL TOP GARNISH CLIP	Not Necessary	35.00 FL	*- FL
14	1		*CONDENSER	Bent	568.10 FL	*568.10 FL
15	1		*RADIATOR	Punctured	1,376.50 FL	*1,376.50 FL
16	1		*RADIATOR AIR GUIDE RH	Cracked	46.60 FL	*46.60 FL
17	1		*FRONT BUMPER	Bent	851.70 FL	*851.70 FL
18	10		*FRONT BUMPER CLIP	Necessary	35.00 FL	*35.00 FL
19	1		*FRONT BUMPER REINFORCEMENT	Bent	380.60 FL	*380.60 FL
20	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	35.60 FL	*- FL
21	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	35.60 FL	*35.60 FL
22	1		*FRONT BUMPER BRACKET LH	Repair	48.50 FL	*- FL
23	1		*FRONT BUMPER BRACKET RH	Cracked	48.50 FL	*48.50 FL
24	1		*FRONT BUMPER TOW COVER	Serviceable	27.10 FL	*- FL
25	1		*FOG LAMP RH	Service item	338.90 FL	*- FL
26	1		*FOG LAMP GARNISH RH	Dented	78.00 FL	*78.00 FL
27	1		*FRONT BUMPER LOWER SPOILER	Serviceable	391.00 FL	*- FL
28	1		*RH FRONT FENDER	Bent	598.00 FL	*598.00 FL
29	1		*RH FRONT FENDER UNDERSHIELD	Cracked	155.00 FL	*155.00 FL
30	10		*RH FRONT FENDER UNDERSHIELD CLIP	Not Necessary	35.00 FL	*- FL
31	1		*RHF FENDER WORDING HYBRID	Necessary	58.70 FL	*58.70 FL
32	1		*RH FRONT FENDER PROTECTOR	Dented	196.00 FL	*196.00 FL
33	10		*RH FRONT FENDER PROTECTOR CLIP	Necessary	35.00 FL	*35.00 FL
34	1		*HEAD LAMP BRACKET LH	Bent	68.50 FL	*48.50 FL
35	1		*HEAD LAMP BRACKET RH	Repair	68.50 FL	*- FL
36	1		*WASHER TANK	Dented	95.00 FL	*95.00 FL
37	1		*WASHER TANK MOTOR	Cracked	79.60 FL	*79.60 FL
38	1		*BONNET HEAT INSULATOR	Cracked	153.20 FL	*153.20 FL
39	10		*BONNET HEAT INSULATOR CLIP	Necessary	40.00 FL	*40.00 FL
40	1		*FRONT BUMPER BEAM CENTRE	Bent	65.80 FL	*65.80 FL
41	1		*FUEL BOX COVER RH	Dented	15.00 FL	*15.00 FL
42	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,729.00	9,269.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,136.80	1,853.96
Total Parts (\$\$)	8,592.20	7,415.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,SUPPORT PANEL,BONNET RHF FENDER)	New	1,200.00	600.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER ,SUPPORT PANEL,BONNET RHF FENDER)	New	1,000.00	800.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	50.00	20.00
4	TO REMOVE & REFIT RADIATOR ,CONDENSER TO ASSIST WORK LOAD ,TO TOP UP A/C GAS	New	150.00	100.00
5	TO TUFF COAT	New	150.00	90.00
Gross Labour Cost (\$\$)			2,550.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >