

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19019257/BKS3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800110602

Claimant
Vehicle No : SJT9687K **Insured Vehicle No :** SMD606C

Date of Loss: 25/10/2019 Nature of Claim: TP Claim No: 0811547838SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9687K		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX986812
Reg. Date:	11/11/2009 (Man. Year: 2009)	Chassis No:	MR053HY9305135665
Colour:	Beige	Odometer:	246724 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,212.10	2,410.72	1,801.38	42.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	1,380.00	740.00	34.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,332.10	3,790.72	2,541.38	40.13
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	6,332.10	3,050.00	3,282.10	51.83
+ GST 7.00/7.00% (S\$)	443.25	213.50	229.75	51.83
Nett Amount (S\$)	6,775.35	3,263.50	3,511.85	51.83
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,805.95		

INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 25/10/2019 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	536.00 FL	*536.00 FL
2	1		*BOOTLID VIOS BADGE	Necessary	48.00 FL	*48.00 FL
3	1		*BOOTLID TRD BADGE	Necessary	50.00 FL	*30.00 FL
4	1		*BOOTLID CENTRE LOGO BADGE	Necessary	55.00 FL	*55.00 FL
5	1		*BOOTLID LOCK -TOP	Dented	100.00 FL	*100.00 FL
6	1		*BOOTLID LOCK LATCH BOTTOM	Not Necessary	28.00 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Torn	175.00 FL	*175.00 FL
8	2		*BOOTLID RUBBER STOPPER	Not Necessary	35.60 FL	*- FL
9	3		*BOOTLID LOCK CABLE CLIP	Not Necessary	12.90 FL	*- FL
10	3		*BOOTLID WIRE HARNESS CLIP	Not Necessary	12.90 FL	*- FL
11	2		*BOOTLID HINGE	Not Necessary	120.00 FL	*- FL
12	1		*REAR END PANEL	Dented	605.00 FL	*539.13 FL
13	1		*REAR END PANEL INNER TRIM	Dislodged	80.70 FL	*80.70 FL
14	3		*REAR END PANEL INNER TRIM CLIP	Necessary	11.40 FL	*11.40 FL
15	2		*REAR LAMP	Broken	780.00 FL	*498.80 FL
16	4		*REAR LAMP CLIP HOLDER	Necessary	71.20 FL	*50.00 FL
17	1		*REAR BUMPER	Dented	435.00 FL	*419.60 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	200.00 FL	*164.00 FL
19	2		*REAR BUMPER SIDE HOLDER	Broken	70.00 FL	*70.00 FL
20	1		*REAR BUMPER REFLECTOR	N/S Broken	180.00 FL	*80.00 FL
21	8		*REAR BUMPER FASTENER CLIP	Necessary	34.40 FL	*30.00 FL
22	2		*REAR BUMPER SPLASHIELD COVER	Torn	100.00 FL	*60.00 FL
23	1		*REAR LUGGAGE FLOOR CARDBOARD	Not Necessary	115.50 FL	*- FL
24	2		*REAR LUGGAGE SIDE FOAM	Not Necessary	428.00 FL	*- FL
25	1		*REAR EXHAUST BOX	Not Necessary	635.00 FL	*- FL
26	1		*REAR EXHAUST BOX CHROME CUTTLER	Not Necessary	43.30 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	39.90 FL	*- FL
28	1		*SET REAR BUMPER PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
29	1		*REAR LUGGAGE FLOOR INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,462.80	3,147.63
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,250.70	736.91
Total Parts (\$\$)	4,212.10	2,410.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	60.00	60.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	60.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	40.00	40.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	120.00	60.00
5	TO TRANSFER OF BOOTLID FITINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	100.00	60.00
6	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	80.00	0.00
7	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	800.00	500.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	600.00
Gross Labour Cost (\$)			2,120.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >