

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019264/BDA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100456670
Claimant
Vehicle No : SJK8708M **Insured Vehicle No :** SLB2167L
Date of Loss: 23/10/2019 **Nature of Claim:** TP **Claim No:** 4626102565SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJK8708M**
 Make & Model: HONDA FREED HYBRID, 1.5 G (A) Engine No: LEB5590957
 Reg. Date: 07/09/2018 (Man. Year: 2018) Chassis No: GB71059468
 Colour: Silver Odometer: 117208 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65R15 Rear Tyre Size: 185/65R15
 Front Left Side: West Lake 6 mm Rear Left Side: Goodride 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: Goodride 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,224.00	23,785.04	14,438.96	37.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,430.00	6,160.00	6,270.00	50.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	50,654.00	29,945.04	20,708.96	40.88
+ Loss of Use (27.0 x S\$70.00/day) (S\$)		1,890.00		
+ Doc/Search Fee (S\$)		36.49		
Nett Liability (S\$)		31,871.53		

INSPECTION

Date of Assignment: 29/10/2019
 Date Inspected: 29/10/2019 Inspected At: Team Auto Pro Pte Ltd - Sin Ming (HQ)
 160 Sin Ming Drive #01-14 Sin Ming Autocity
 Singapore 575722
 Estimated Period of Repair: 21.0 days

Adjuster: Lim Teow Guan

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,050.00 FL	*837.50 FL
2	1		*FRONT BUMPER LOWER GRILLE	Broken	326.00 FL	*165.80 FL
3	2		*FRONT BUMPER LOWER GRILLE SIDE GARNISH	Not Necessary	262.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Bent	486.00 FL	*486.00 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	144.00 FL	*59.00 FL
6	2		*HEADLAMP ASSY	Broken	3,909.60 FL	*3,480.00 FL
7	2		*HEADLAMP BRACKET	Broken	152.00 FL	*152.00 FL
8	1		*FRONT RADIATOR GRILLE	Broken	630.00 FL	*630.00 FL
9	1		*FRONT RADIATOR GRILLE LOWER RUBBER	Torn	137.00 FL	*137.00 FL
10	1		*FRONT RADIATOR GRILLE OUTER PANEL	Not Necessary	299.80 FL	*- FL
11	1		*FRONT RADIATOR GRILLE CHROME	Broken	168.00 FL	*168.00 FL
12	1		*FRONT RADIATOR GRILLE CHROME LOWER	Broken	175.00 FL	*144.00 FL
13	1		*FRONT RADIATOR GRILLE UPPER BRACKET (CENTRE)	Bent	91.00 FL	*47.80 FL
14	1		*FRONT TOWING COVER	Dislodged	98.00 FL	*25.60 FL
15	1		*BONNET	Dented	1,034.70 FL	*720.60 FL
16	1		*BONNET LOCK ASSY	Dented	234.60 FL	*154.40 FL
17	2		*BONNET HINGE	Bent	178.00 FL	*115.80 FL
18	2		*BONNET RUBBER (SHORT)	Necessary	182.00 FL	*182.00 FL
19	1		*BONNET RUBBER (LONG)	Necessary	135.00 FL	*135.00 FL
20	1		*BONNET STAND	Bent	62.00 FL	*62.00 FL
21	1		*WINDSCREEN	Cracked	1,800.00 FL	*1,055.00 FL
22	1		*FRONT SUPPORT TOP PANEL	Bent	898.00 FL	*752.60 FL
23	1		*FRONT SUPPORT TOP PANEL GARNISH	Not Necessary	185.00 FL	*- FL
24	1		*FRONT FENDER LH	Repair	756.00 FL	*- FL
25	1		*FRONT FENDER RH	Dented	756.00 FL	*440.00 FL
26	2		*FRONT FENDER EMBLEM HYBRID	Necessary	150.00 FL	*68.70 FL
27	1		*FRONT FENDER INNER SHIELD RH	Not Damaged	134.20 FL	*- FL
28	1		*CANISTER	Not Necessary	386.50 FL	*- FL
29	1		*FRONT WIPER GARNISH	Broken	56.00 FL	*56.00 FL
30	1		*FRONT WIPER TANK	Dented	265.80 FL	*89.50 FL
31	1		*FRONT DRIVER AIR BAG	Activated	2,980.00 FL	*2,165.00 FL
32	1		*DASHBOARD AIR BAG	Activated	4,200.00 FL	*2,880.00 FL
33	2		*AIRBAG SENSOR	Activated	318.00 FL	*278.80 FL
34	2		*FRONT SAFETY BELT	Jammed	1,621.00 FL	*1,196.80 FL
35	2		*FRONT SAFETY BELT KNUCKLE	Not Damaged	336.00 FL	*- FL
36	1		*RADIATOR	Broken	987.90 FL	*630.00 FL
37	1		*RADIATOR FAN MOTOR	Broken	538.00 FL	*301.80 FL
38	1		*RADIATOR FAN COWLING	Broken	215.60 FL	*105.80 FL
39	1		*RADIATOR FAN BLADE	Not Damaged	116.00 FL	*- FL
40	1		*RADIATOR TOP HOSE	Not Damaged	94.00 FL	*- FL
41	1		*A C COMPRESSOR BELT	Necessary	194.50 FL	*80.00 FL
42	1		*AIRCON CONDENSER	Broken	985.00 FL	*985.00 FL
43	1		*AIRCON SUCTION HOSE	Bent	398.00 FL	*398.00 FL
44	1		*AIRCON DISCHARGE HOSE	Bent	352.00 FL	*352.00 FL
45	1		*AIR DUCT	Not Damaged	86.90 FL	*- FL
46	1		*AIR CLEANER BOX	Not Damaged	294.50 FL	*- FL
47	1		*THROTTLE BODY	Not Damaged	1,430.80 FL	*- FL
48	1		*EXHAUST MANIFOLD COVER	Not Damaged	94.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*FRONT CHASIS MEMBER	Bent	567.80 FL	*567.80 FL
50	1		*FRONT ENGINE MOUNTING	Not Damaged	467.80 FL	*- FL
51	1		*TAILGATE	Dented	1,331.20 FL	*1,207.90 FL
52	1		*TAILGATE LOGO	Necessary	75.90 FL	*51.00 FL
53	1		*TAILGATE EMBLEM FREED	Necessary	89.40 FL	*45.60 FL
54	1		*TAILGATE EMBLEM HYBRID	Necessary	75.00 FL	*55.00 FL
55	1		*TAILGATE OUTER CHROME MOULDING	Dislodged	320.40 FL	*275.20 FL
56	2		*TAILGATE NUMBER PLATE LAMP	Repeated	87.20 FL	*- FL
57	2		*TAILGATE LAMP	Broken	779.20 FL	*779.20 FL
58	1		*TAILGATE WEATHERSTRIP	Torn	124.50 FL	*124.50 FL
59	2		*TAILGATE HINGE	Not Damaged	135.60 FL	*- FL
60	2		*TAILGATE HYDRAULIC DAMPER	Not Damaged	275.00 FL	*- FL
61	1		*TAILGATE INNER LOCK	Jammed	243.50 FL	*243.50 FL
62	1		*TAILGATE LOCK STRIKER	Bent	54.70 FL	*28.70 FL
63	1		*TAILGATE WIPER MOTOR	Not Damaged	320.00 FL	*- FL
64	1		*TAILGATE WIPER LINK	Not Damaged	58.00 FL	*- FL
65	1		*TAILGATE WIPER BLADE	Not Damaged	42.80 FL	*- FL
66	1		*TAILGATE TRIMBOARD	Broken	284.10 FL	*284.10 FL
67	1		*TAILGATE INNER HANDLE	Broken	71.50 FL	*29.50 FL
68	1		*TAILGATE WINDSCREEN MOULDING	Necessary	95.60 FL	*95.60 FL
69	1		*TAILGATE WINDSCREEN GLASS RUBBER	Necessary	120.00 FL	*60.00 FL
70	1		*REAR BUMPER	Dented	678.40 FL	*678.40 FL
71	2		*REAR BUMPER SIDE RETAINER	Necessary	224.00 FL	*49.80 FL
72	1		*REAR BUMPER CENTRE BEAM	Not Necessary	172.50 FL	*- FL
73	1		*REAR BUMPER TOW COVER	Not Damaged	35.00 FL	*- FL
74	2		*REAR BUMPER REFLECTOR	Broken	128.00 FL	*128.00 FL
75	2		*REAR SPLASH GUARD	Not Damaged	297.20 FL	*- FL
76	2		*TAILLAMP	Broken	1,160.00 FL	*1,160.00 FL
77	2		*TAILLAMP QUARTER PANEL	Not Damaged	196.00 FL	*- FL
78	1		*REAR END PANEL INNER	Dented	95.00 FL	*95.00 FL
79	1		*REAR END PANEL OUTER	Dented	623.70 FL	*623.70 FL
80	1		*REAR END PANEL TOP GARNISH	Dislodged	89.90 FL	*89.90 FL
81	1		*REAR FLOOR PANEL	Dented	956.00 FL	*956.00 FL
82	2		*REAR FLOOR PANEL SIDE	Not Necessary	420.00 FL	*- FL
83	1		*REAR FLOOR PANEL TOP BOARD	Distorted	750.00 FL	*466.30 FL
84	2		*REAR FENDER INNER TRIM	Broken	930.20 FL	*591.60 FL
85	2		*REAR FENDER INNER SHIELD	Broken	557.80 FL	*300.00 FL
86	1		*REAR WINDSCREEN GLASS (DARK COLOUR)	Not Damaged	1,200.00 FL	*- FL
87	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	40.00 FL	*40.00 FL
88	1		*REAR WINDSCREEN GLASS LOWER MOULDING	Necessary	80.00 FL	*80.00 FL
89	2		*REAR NUMBER PLATE LAMP	Not Damaged	67.20 FL	*- FL
90	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
91	1		*FRONT RADIATOR GRILLE CLIPS	Necessary	60.00 FS	*30.00 FS
92	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
93	2		*NUMBER PLATE WITH CASING	Necessary	160.00 FS	*100.00 FS
94	1		*FRONT WINDSCREEN CLIPS	Necessary	50.00 FS	*30.00 FS
95	1		*FRONT WINDSCREEN PRIMER AND CLEANER	Not Necessary	100.00 FS	*- FS
96	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*50.00 FS
97	1		*FRONT WINDSCREEN INNER SEAL	Necessary	80.00 FS	*50.00 FS
98	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
99	1		*FRONT HEADLAMP CLIPS	Necessary	50.00 FS	*30.00 FS
100	1		*COOLANT	Necessary	100.00 FS	*30.00 FS
101	1		*SUNDRIES		50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
102	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary		
103	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Necessary	50.00 FS	*30.00 FS
104	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
105	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	100.00 FS	*50.00 FS
106	1		*TAILGATE SEALANT	Necessary	80.00 FS	*30.00 FS
107	1		*TAILGATE INNER TRIMBOARD CLIP	Necessary	100.00 FS	*30.00 FS
108	1		*REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
109	1		*REAR END PANEL SEALANT	Necessary	45.00 FS	*30.00 FS
110	1		*REAR END PANEL GARNISH CLIPS	Not Necessary	100.00 FS	*30.00 FS
111	2		*REAR FENDER INNER TRIMBOARD CLIPS	Not Necessary	25.00 FS	*- FS
112	2		*REAR FENDER INNER COWLING CLIPS	Necessary	200.00 FS	*30.00 FS
113	2		*TAILLAMP SEAL	Necessary	100.00 FS	*30.00 FS
114	2		*TAILLAMP CLIP	Not Necessary	80.00 FS	*- FS
115	1		*REAR SENSOR WITH MODULE	Not Necessary	40.00 FS	*- FS
116	1		*REAR FLOOR PANEL INSULATION	Dislodged	300.00 FS	*200.00 FS
				Not Damaged	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	47,165.00	29,513.80
- List Item Discount on L Items 20.00/20.00% (S\$)	8,941.00	5,728.76
Total Parts (S\$)	38,224.00	23,785.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING FRONT	New	2,200.00	1,200.00
2	SPRAY PAINTING FRONT	New	1,800.00	900.00
3	RUST PROOFING	New	300.00	100.00
4	PANEL BEAT REAR	New	2,200.00	1,200.00
5	SPRAY PAINT REAR	New	2,000.00	1,200.00
6	CHECK WIRING / BULB	New	200.00	80.00
7	TUFF COAT (FRONT)	New	150.00	0.00
8	R&R RADIATOR	New	150.00	80.00
9	R&R CONDENSER WITH TOP UP GAS	New	150.00	120.00
10	R&R AIR BAG	New	300.00	200.00
11	R&R WINDSCREEN FRONT	New	150.00	80.00
12	R&R TAILGATE WINDSCREEN REAR	New	150.00	80.00
13	R&R REVERSE SENSOR	New	300.00	60.00
14	R&R TAILGATE COMPONENT	New	150.00	100.00
15	UPHOLSTERY	New	200.00	80.00
16	R&R ECU SYSTEM	New	300.00	80.00
17	R&R HYBRID CONVERTER UNIT, DIAGNOSIS & CHECK FOR FUNCTION	New	500.00	0.00
18	R&R HYBRID BATTERY TO FACILITATE REPAIR	New	350.00	100.00
19	MOUNT WORK BENCH	New	350.00	200.00
20	CHASIS ALIGNMENT	New	350.00	200.00
21	R&R DASHBOARD	New	180.00	100.00
Gross Labour Cost (\$\$)			12,430.00	6,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >