



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19019289/Atf3e2

73 BRAS BASAH ROAD

Date: 24-04-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN : ENG HUEY HUEY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLJ 6566A	Veh. Inspected	SLD 5790G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1084628-001	Excess (\$)	0.00
Assign From	HAZALYSA BTE IBRAHIM	Assign Date	31/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707029885	Colour	BLACK
Odometer	55525 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	KUMHO	6 mm
L/H Front Tyre	205/50 R16	KUMHO	6 mm
R/H Rear Tyre	205/50 R16	KUMHO	6 mm
L/H Rear Tyre	205/50 R16	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	30/10/2019	Inspect Date / Time	01/11/2019 (12:25 PM)
Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------