

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19019296/UDA3Q2**Date:** 11/11/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900000667
Claimant
Vehicle No : FBJ5748S **Insured Vehicle No :** SMH1617T
Date of Loss: 14/06/2019 Nature of Claim: TP Claim No: 1415862037SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ5748S**
Make & Model: SYM JOYRIDE 200I, 171cc EVO CVT Engine No: KB219539
Reg. Date: 22/07/2014 (Man. Year: 2014) Chassis No: RFGLF18WYES014904
Colour: Black Odometer: 42350 km
Engine Capacity: 171 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 110-90-13 Rear Tyre Size: 130-70-12
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,076.00	4,420.30	1,655.70	27.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,505.00	735.00	770.00	51.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,581.00	5,155.30	2,425.70	32.00
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	7,581.00	4,000.00	3,581.00	47.24
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
		4,120.00		

INSPECTION

Date of Assignment: 31/10/2019
Date Inspected: 31/10/2019 Inspected At: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62
AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOP COWLING	Cracked	75.00 FL	*75.00 FL
2	1		*FRONT FAIRING	Cracked	450.00 FL	*450.00 FL
3	1		*FRONT FAIRING INNER PANEL	Cracked	265.00 FL	*265.00 FL
4	1		*FRONT LOWER FAIRING	Cracked	210.00 FL	*210.00 FL
5	1		*HEADLAMP	Cracked	225.00 FL	*225.00 FL
6	2		*FRONT SIGNALS	N/S Cracked /O/S Scratched	210.00 FL	*210.00 FL
7	1		*FRONT MUDGUARD	Cracked	155.00 FL	*155.00 FL
8	1		*FRONT FORK ASSY	Bent / Twisted	850.00 FL	*850.00 FL
9	1		*FORK UNDER BRACKET	Twisted	220.00 FL	*220.00 FL
10	1		*FRONT RIM	Repair	310.00 FL	*- FL
11	1		*FRONT BRAKE DISC	Serviceable	165.00 FL	*- FL
12	1		*LOWER BELLY PANEL	Cracked	285.00 FL	*285.00 FL
13	1		*FRONT RIM SHAFT	Not Necessary	45.00 FL	*- FL
14	1		*CENTRE INNER COWLING	Cracked	175.00 FL	*175.00 FL
15	1		*CENTRE INNER COWLING TOP COVER	Cracked	110.00 FL	*110.00 FL
16	1		*WINDSHIELD	Serviceable	165.00 FL	*- FL
17	1		*SIDE MIRROR -R/H	Cut	80.00 FL	*80.00 FL
18	1		*HANDLE BAR	Bent	125.00 FL	*125.00 FL
19	1		*HANDLE BAR END	Scratched	25.00 FL	*25.00 FL
20	1		*BRAKE LEVER	Scratched	32.00 FL	*32.00 FL
21	1		*HANDLE BAR TOP COVER	Cracked	100.00 FL	*100.00 FL
22	1		*HANDLE BAR LOWER COVER	Not Necessary	68.00 FL	*- FL
23	1		*REAR FAIRING -R/H	Repair	355.00 FL	*- FL
24	1		*FOOTSTEP PANEL	Cut	105.00 FL	*105.00 FL
25	1		*EXHAUST ASSY	Dented / Bent	550.00 FL	*550.00 FL
26	1		*EXHAUST PROTECTOR	Torn	55.00 FL	*55.00 FL
27	1		*MAINT STAND	Repair	120.00 FL	*- FL
28	1		*REAR FOOTREST -R/H	Cut	65.00 FL	*65.00 FL
29	1		*REAR TAILLAMP	Not Necessary	320.00 FL	*- FL
30	1		*REAR MUDGUARD	Not Necessary	165.00 FL	*- FL
31	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
32	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
33	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
34	1		*SET STEERING CONE	Necessary	85.00 FS	*85.00 FS
35	1		*REAR BOX	Missing	250.00 FS	*250.00 FS
36	1		*REAR BOX BRACKET	Cracked	100.00 FS	*100.00 FS
37	1		*JOYRIDE 200 EMBLE	Scratched	55.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,684.00	4,857.00
- List Item Discount on L Items 10.00/10.00% (\$)	608.00	436.70
Total Parts (\$)	6,076.00	4,420.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	45.00	35.00
2	TO PROVIDE LABOUR	New	380.00	300.00
3	TO RESPRAY PAINTING	New	600.00	400.00
4	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION	New	400.00	0.00
5	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
			Gross Labour Cost (\$\$)	735.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >