

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Oct 2019		01 Nov 2019 09:56	<b>S\$9,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$9,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	<b>JAK ENGINEERING &amp; CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201006478R	
Vehicle Reg. No.:	<b>WC5815U</b>	Date of Loss: 25/10/2019 13:00 - :59 [81 Months From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM19D205069C02/CML/BEN</b>	Policy/Cover Note No.: DMCVSN1929101900
Vehicle Reg. No. (Insured):	<b>GBJ7004S</b>	Policy No. (Claimant): 5104409426-01 (COMP)
		Excess: S\$350.00
Repairer:	<b>Ae Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive, #06-01, Sin Ming AutoCity, 575722 Sin Ming - Tel:	
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]	
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:	
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 12/11/2019]	
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>CHINA_TAIPING (09/08/2020): <b>Alert - Adj Mandate Approved (S\$0.00) - WC5815U - Claim Handler: Elaine Cheong</b></li> </ul>		
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>
<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>
<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>
<b>Done?</b>		
No results.		



## Claim Documents

**\*WC5815U (SNM19D205069C02/CML/BEN)**  
**[GBJ7004S]**  
**TP**  
**JAK ENGINEERING & CONSTRUCTION PTE LTD**  
**Oct 25 2019 1:00PM**  
**[-]**  
**Ae Auto Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>
<b>Assessment Reports</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Finalized On	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	<b>Thumbnail</b> <b>Print</b>
1	07/08/20 16:41	<b>Adjuster Immediate Advice</b>	1 <a href="#">Load HTM</a>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Finalized On	<b>VAC (Sin Ming)</b>	<b>Thumbnail</b> <b>Print</b>
1	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
2	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
3	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
4	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
5	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
6	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
7	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
8	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
9	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
10	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
11	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
12	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
13	25/10/19 16:50	<b>Accident Photo</b> [Linked Accident Report Documents]	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Finalized On	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b>	<b>Thumbnail</b> <b>Print</b>
1	01/11/19 09:57	<b>PRS - WC5815U</b>	1 <a href="#">Load PDF</a>
No	Finalized On	<b>VAC (Sin Ming)</b>	<b>Thumbnail</b> <b>Print</b>
1	25/10/19 16:52	<b>Sketch Plan</b> [Linked Accident Report Documents]	1 <a href="#">Load TIF</a>
2	25/10/19 16:52	<b>Sketch Plan #2</b> [Linked Accident Report Documents]	1 <a href="#">Load TIF</a>
No	<b>Relabel/Reorder</b>	<b>LKK Auto Consultants Pte Ltd (HQ)</b>	<b>Thumbnail</b> <b>Print</b>
1	12/08/20 11:59	<b>LKK SURVEYOR PHOTO 1.pdf</b>	1 <a href="#">Load PDF</a>

## Linked Accident Report Documents

			<b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span>
<b>Assessment Reports</b>			1 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Finalized On	<b>VAC (Sin Ming)</b>	<b>Thumbnail</b> <b>Print</b>
1	06/12/19 18:24	<b>Accident Statement</b>	1 <a href="#">Load HTM</a>
<b>Photos/Images</b>			3 per page <span style="border: 1px solid black; padding: 2px;">v</span> <input checked="" type="checkbox"/>
No	Finalized On	<b>VAC (Sin Ming)</b>	<b>Thumbnail</b> <b>Print</b>
1	25/10/19 16:50	<b>Accident Photo</b>	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>
2	25/10/19 16:50	<b>Accident Photo</b>	1 <a href="#">Load JPG</a> <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
3	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	25/10/19 16:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

  

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	25/10/19 16:52	Sketch Plan	Load TIF	
2	25/10/19 16:52	Sketch Plan #2	Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p><b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b></p> <div style="border: 1px solid gray; height: 40px; width: 100%;"></div> <p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI19019310/KSF3S2**Date:** 14/08/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1929101900

**Claimant Vehicle No :** WC5815U **Insured Vehicle No :** GBJ7004S

Date of Loss: 25/10/2019 Nature of Claim: TP Claim No: SNM19D205069C02/CML/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WC5815U**

Make & Model: ISUZU CYH52S, 15.7 D (M) Engine No: 6WG1417800

Reg. Date: 25/01/2013 (Man. Year: 2012) Chassis No: JALCYH52SC7000380

Colour: Multi-colour Odometer: 264524 km

Engine Capacity: 15681 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Golden Wing 7/3 mm Rear Left Side: Ecoster 9/9/9/9 mm

Front Right Side: KAPSEN 7/3 mm Rear Right Side: Ecoster 9/9/9/9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	23,343.50	10,350.00	12,993.50	55.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	1,560.00	1,710.00	52.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>26,613.50</b>	<b>11,910.00</b>	<b>14,703.50</b>	<b>55.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>26,613.50</b>	<b>9,200.00</b>	<b>17,413.50</b>	<b>65.43</b>

INSPECTION

Date of Assignment: 01/11/2019

Date Inspected: 05/08/2020 Inspected At: Ae Auto Pte Ltd (HQ)  
160 Sin Ming Drive,#06-01, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 14 Aug 2020)	
<b>Parts:</b>	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for WC5815U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL LAMP LH	Serviceable	590.00 FL	*- FL
2	1		*TAILLAMP BRACKET LH	Repair	420.00 FL	*- FL
3	1		*REAR GUTTER TOP	Bent / Distorted	2,500.00 FS	*1,600.00 FS
4	1		*REAR GUTTER DRAINAGE BOTTOM	Buckled	3,000.00 FS	*1,800.00 FS
5	1		*REAR GUTTER GEAR ASSY	Jammed / Punctured	5,800.00 FS	*3,800.00 FS
6	1		*REAR LH BUCKLE	Bent	1,850.00 FS	*1,100.00 FS
7	1		*SET REAR LH BUCKLE BOLT & NUT	Necessary	250.00 FS	*250.00 FS
8	1		*REAR LH BUCKLE BRACKET	Repair	385.00 FS	*- FS
9	1		*REAR SAFETY BAR	Bent	5,500.00 FS	*1,800.00 FS
10	1		*REAR SAFETY BAR LH BRACKET	Repair	900.00 FS	*- FS
11	1		*REAR LH STEP PANEL ASSY	Repair	2,300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>23,495.00</b>	<b>10,350.00</b>
<b>- List Item Discount on L Items 15.00/15.00% (\$\$)</b>	151.50	0.00
<b>Total Parts (\$\$)</b>	<b>23,343.50</b>	<b>10,350.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO DO CUTTING, WELDING ALIGN ADJUST, REPLACE REPAIR ON REAR ACCIDENT AFFECTED AREA.	New	1,400.00	800.00
2	TO DO ANTI RUST.	New	120.00	60.00
3	TO DO REAR BODY CHASSIS BODY ALIGNMENT.	New	350.00	0.00
4	TO DO SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREA.	New	1,400.00	700.00
			<b>Gross Labour Cost (\$\$)</b>	<b>3,270.00</b>
				<b>1,560.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >