

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Cheong

Date: 07 Aug 2020

Preliminary Advice

Insured Vehicle No : GBJ7004S
TP Vehicle No : WC5815U
Make : ISUZU CYH52S
Date of Inspection : 05/08/2020
Inspection At : Autoexcel Engineering Pte Ltd (HQ)
160 Sin Ming Drive #06-01,, Sin Ming AutoCity
Singapore 575722

Accident Date : 25/10/2019
Assignment Date : 01/11/2019
Est. Duration of Repair : 4 Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 26,613.50 |
| Revised Amount | :S\$ | 12,810.00 |
| Check Items (Estimated) | :S\$ | 7,650.00 |
| Total | :S\$ | 20,460.00 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP