HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23, #02-02, Midview Building, Singapore 659578

Tel: 68966619 Fax: 62678616 Email: huachinmotor@singnet.com.sg

ASSESSMENT FOR REPAIR: FBL5055Y YAMAHA YZF-R15-150CC (M)

		(List)	**
S/N	DESCRIPTION	Amount	
1	Rear Number Plate bt	\$30.00	P- P-925
2	Rear Number Plate Light SvC	\$45.00	× 163
3	Number Plate Bracket (Outer) Cul	\$85.00	00 0000
4	Number Plate Bracket (Inner) 54/	\$120.00	41 837.30
5	Rear Tyre 🔸 SVL	\$185.00	1×
6	Rear Rim 5†/	\$485.00	S/N-300
7	Signal Light @2 (n/(1).()		0-45
8	Exhaust Pipe	\$550.00	0/
9	Labour Charge	\$300.00	2:00 } Labour Labour - 3515
10	Wheel Alignment	\$270.00	50 Slabour
11	Side cover @2 RH-sur/LH-Rank	\$190.00	Ciecy 0-95/
12	Tail Light X SFC	\$155.00	×
13	Swing Arm	> \$350.60	100 (Local reain) (Labour)
	TO REPAIR SWING ARM (RASUL REMARKS ON 29/04/2020)	\$2,855.00	
	Gst	\$199.85	
	Total	\$3,054.85	

Lump Sum Repair Adjustment: \$3055.00

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

Signature:

26/11/19 Resurs Sefore prient