

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBL 5055Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NUMBER PLATE	BENT	30.00	30.00
1	REAR NUMBER PLATE LIGHT	SERVICEABLE	45.00	-
1	NUMBER PLATE BRACKET (OUTER)	CUT	85.00	85.00
1	NUMBER PLATE BRACKET (INNER)	BENT	120.00	120.00
1	REAR TYRE	SERVICEABLE	185.00	-
2	SIGNAL LIGHT	CRACKED (1PC ONLY)	90.00	45.00
1	EXHAUST PIPE	BENT	550.00	550.00
2	SIDE COVER	O/S SCRATCHED / N/S TO REPAIR SEE LABOUR	190.00	95.00
1	TAIL LIGHT	SERVICEABLE	155.00	-
	LESS 10% DISCOUNT		-	-92.50
			1,450.00	832.50
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RIM (SN)	BENT	485.00	300.00
			485.00	300.00
	<u>LABOUR</u>			
	LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF N/S SIDE COVER.		300.00	200.00
	WHEEL ALIGNMENT.		270.00	50.00
	TO REPAIR SWING ARM.		350.00	100.00
			920.00	350.00
	GRAND TOTAL		2,855.00	1,482.50
	RECOMMENDED COST OF REPAIRS			1,482.50

Report Ref No. CS/FCI19019319/R1sf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.