

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19019334/ASF3E2

**Date:** 08/09/2020

### REFERENCE

Insured/Claimant:	CHONG LEE FONG	Policy No:	1800080001	
Date of Loss:	30/10/2019	Nature of Claim:	OD	Claim No: 5950844995SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT9963M			
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK064081	
Reg. Date:	20/07/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF49JN015027	
Colour:	Grey	Odometer:	21940 km	
Engine Capacity:	1984 cc			
Market Value/New Car Price:	S\$125,000.00			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,502.00	1,117.04	11,384.96	91.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,402.00	3,052.00	2,350.00	43.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>17,904.00</b>	<b>4,169.04</b>	<b>13,734.96</b>	<b>76.71</b>
<b>- Excess (\$\$)</b>	<b>1,600.00</b>	<b>1,600.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>16,304.00</b>	<b>2,569.04</b>	<b>13,734.96</b>	<b>84.24</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>1,141.28</b>	<b>179.83</b>	<b>961.45</b>	<b>84.24</b>
<b>Nett Amount (\$\$)</b>	<b>17,445.28</b>	<b>2,748.87</b>	<b>14,696.41</b>	<b>84.24</b>

### INSPECTION

Date of Assignment:	01/11/2019	
Date Inspected:	01/11/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,999.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	56.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	123.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
6	1		*FRONT FENDER - LH	Dented	700.00 FS	*559.60 FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	183.00 FS	*- FS
8	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	45.00 FS	*- FS
9	1		*FRONT FENDER BRACKET - LH	Not Necessary	32.00 FS	*- FS
10	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	Not Necessary	45.00 FS	*- FS
11	1		*FRONT FENDER BRACKET - LH	Not Necessary	29.00 FS	*- FS
12	1		*FRONT FENDER BRACE - LH FRONT	Not Necessary	107.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	223.00 FS	*- FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	82.00 FS	*- FS
15	1		*WHEEL SPOILER	Not Necessary	66.00 FS	*- FS
16	1		*WHEEL SPOILER TRIM - LH	Not Necessary	32.00 FS	*- FS
17	1		*STONE CHIP GUARD - LH	Necessary	46.00 FS	*36.64 FS
18	1		*FENDER LEDGE COVER - LH	Not Necessary	28.00 FS	*- FS
19	1		*FENDER TOP LEDGE COVER - LH	Not Necessary	21.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	231.00 FS	*- FS
21	4		*PARKING AID SEAL RING	Not Necessary	12.00 FS	*- FS
22	1		*LED HEADLIGHT - LH	Not Necessary	7,087.00 FS	*- FS
23	1		*FRONT ALUMINIUM RIM - LH	Cut	651.00 FS	*520.80 FS
24	4		*ALUMINIUM RIM RUBBER VALVE	Not Necessary	13.00 FS	*- FS
25	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.					<b>Total Parts (S\$)</b>	<b>12,502.00 1,117.04</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00
4	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>5,402.00</b>	<b>3,052.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**