

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG19019335/AEA3Q2**Date:** 13/05/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKQ6591B**Insured Vehicle No :** GBF4108S

Date of Loss: 17/10/2019

Nature of Claim: TP

Claim No: 1075251009SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKQ6591B**

Make &amp; Model: VOLKSWAGEN TOURAN, 1.6 TDI (A)

Engine No: CAYAE4588

Reg. Date: 17/12/2014 (Man. Year: 2014)

Chassis No: WVGZZZ1TZFW009980

Colour: Black

Odometer: 96164 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Linglong 6 mm

Rear Left Side: Linglong 6 mm

Front Right Side: Linglong 6 mm

Rear Right Side: Linglong 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,410.50	3,372.18	4,038.32	54.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,270.00	1,660.00	2,610.00	61.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,680.50</b>	<b>5,032.18</b>	<b>6,648.32</b>	<b>56.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,680.50</b>	<b>4,000.00</b>	<b>7,680.50</b>	<b>65.75</b>
<b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b>		420.00		
<b>(S\$)</b>		4,420.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>2,210.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>2,239.00</b>		

INSPECTION

Date of Assignment: 31/10/2019

Date Inspected: 31/10/2019 Inspected At:

Cas Garage Pte Ltd (HQ)  
No.1, Kaki Bukit Ave 6, #02-22 Autobay  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

*ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Repair	1,470.30 F	*- FL
2	1		*FRONT DOOR PROTECTOR LH	Not Necessary	158.60 F	*- FL
3	1		*REAR DOOR LH	Dented	1,456.80 F	*1,456.80 FL
4	1		*REAR DOOR PROTECTOR LH	Cut	158.90 F	*158.90 FL
5	1		*REAR DOOR OUTER HANDLE LH	Not Necessary	225.30 F	*- FL
6	1		*REAR DOOR INNER TRIM LH	Not Necessary	659.30 F	*- FL
7	1		*SIDE ROCKER PANEL LH	Repair	956.80 F	*- FL
8	1		*REAR FENDER LH	Dented	1,278.90 F	*1,278.90 FL
9	1		*REAR RIM LH	Cut	785.60 F	*785.60 FL
10	1		*SET REAR BUMPER CLIPS	Not Necessary	30.00 FS	*- FS
11	1		*SET REAR DOOR INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
12	1		*SET TAILGATE INNER TRIM CLIPS	Not Necessary	120.00 FS	*- FS
13	2		*REAR FENDER GLASS SEALANTS	Necessary	80.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					7,410.50	3,740.20
- List Item Discount on L Items 0.00/10.00% (\$)					0.00	368.02
Total Parts (\$)					7,410.50	3,372.18

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RENEW DAMAGED PARTS ,REPLACE ,BEAT ,WELD ,REALIGN AND ALIGNE ALL PARTS	New	1,600.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,600.00	600.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	60.00
4	TO REMOVE/REFIT INTERIOR UPHOLSTERY	New	180.00	80.00
5	TO APPLY SEALANT AND UNDERCOATING TO THE ACCIDENT AREAS	New	200.00	60.00
6	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
7	TO REMOVE/REFIT REVERSE SENSORS AND DISTANCE SETTLING	New	180.00	0.00
8	TO REMOVE/REFIT REAR FENDER GLASS	New	160.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,270.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >