

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19019336/UBA3Q2**Date:** 19/04/2021REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant**Vehicle No :** CB6132S**Insured Vehicle No :** SBU21E

Date of Loss: 30/10/2019

Nature of Claim:

TP

Claim No: 2134449225SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **CB6132S**

Make & Model: TOYOTA HIACE, 3.0 D DX (A)

Engine No: 1KD2736457

Reg. Date: 24/11/2017 (Man. Year: 2017)

Chassis No: KDH2010229325

Colour: White

Odometer: 74307 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,307.60	1,798.55	1,509.05	45.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,960.00	840.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,107.60	3,758.55	2,349.05	38.46
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	6,107.60	3,000.00	3,107.60	50.88
+ GST 7.00/7.00% (S\$)	427.53	210.00	217.53	50.88
Nett Amount (S\$)	6,535.13	3,210.00	3,325.13	50.88
+ Car Rental (8.0 x S\$200.00/day + 7.00% GST) (S\$)		1,712.00		
(S\$)		4,922.00		
Liabile Amount (30.00%) (S\$)		1,476.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,478.60		
Global Sum Settlement (S\$)		1,080.00		

INSPECTION

Date of Assignment: 01/11/2019

Date Inspected: 01/11/2019 Inspected At:

Stytech Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2 #02-30, Kaki Bukit

Autohub
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER (RIGHT)	Badly Dented	2,091.40 F	*2,091.40 FL
2	2		*REAR FENDER GLASS SELANT	Necessary	120.00 FS	*80.00 FS
3	1		*FRONT WHEEL COVER (RIGHT)	Cut	120.00 FS	*120.00 FS
4	1		*FRONT RIM (RIGHT)	Serviceable	100.00 FS	*- FS
5	1		*SCHOOL BUS STICKER	Necessary	30.00 FS	*30.00 FS
6	1		*FRONT WHEEL HUB (RIGHT)	Not Necessary	385.40 F	*- FL
7	1		*FRONT KNUCKLE (RIGHT)	Not Necessary	420.80 F	*- FL
8	1		*INNER TRIM BOARD CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,307.60	2,321.40
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	522.85
Total Parts (\$)	3,307.60	1,798.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT WHEEL ALIGNMENT	New	80.00	60.00
2	INTERIOR UPHOLSTERY TO REMOVE & REFIX }	New	150.00	100.00
3	REMOVE & REFIX INNER SEAT }	New	350.00	0.00
4	REAR FENDER GLASS FIXING	New	240.00	150.00
5	PANEL BEATING	New	1,000.00	980.00
6	PAINT WORK	New	800.00	600.00
7	ANTI RUST PROOFING	New	100.00	50.00
8	CHECK WIRING	New	80.00	20.00
Gross Labour Cost (\$\$)			2,800.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >