

Vehicle: CB6132S

Make & Model: *not allocated*  
*h/m* *h/s #3000/7dy.*  
 TOYOTA HIACE

Chassis No: \_\_\_\_\_

S/N	Parts/Labour	QTY	Condition	Price	Recommend
1	Rear Fender (Right) <i>3000</i>			\$ 2,091.40	—
2	Rear Fender Glass Selant <i>nu</i>	2	\$ 60.00 SN	\$ 120.00 SN	<i>to s.n</i>
3	Front Wheel Cover (Right) <i>cu7</i>			\$ 120.00 SN	<i>cu7 ✓ s.n</i>
4	Front Rim (Right) <i>su</i>			\$ 100.00 SN	<i>su x</i>
5	SCHOOL BUS Sticker <i>nu</i>			\$ 30.00 SN	<i>nu ✓ s.n</i>
6	Front Wheel Hub (Right) <i>17</i>			\$ 385.40	<i>x</i>
7	Front Knuckle (Right) <i>17</i>	<i>(252)</i>		\$ 420.80	<i>x</i>
8	Inner Trim Board Chips <i>11</i>			\$ 40.00 SN	<i>x</i>
9	<del>Wheel Alignment</del> <i>To conduct wheel alignment</i>			\$ 80.00 SN	<i>60</i>
10					
11					
	Labour				
1	Interior Upholstery <i>to remove &amp; refix</i>			\$ 150.00	<i>100</i>
2	Rear Fender Glass Fixing	2	120	\$ 240.00	<i>150</i>
3	Remove & Refix inner seat			\$ 350.00	<i>x</i>
4	Panel Beating			\$ 1,000.00	<i>980</i>
5	Paint work			\$ 800.00	<i>600</i>
6	Anti Rust Proofing			\$ 100.00	<i>50</i>
7	Check Wiring			\$ 80.00	<i>20</i>
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• Resurvey before/after spray painting</li> <li>• To do it. Damaged part(s) during resurvey</li> <li>• Price/price are subject to confirmation</li> <li>• The repairer is on "Without Prejudice" basis</li> <li>• Material admittance(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul>					
<b>STYTECH AUTO PTE. LTD.</b> 2 Kaki Bukit Ave 2 #02-30 C1-03 Kaki Bukit Autohub Singapore 417921 Tel: 6444 8126 Fax: 6445 3310 GST Reg. No.: 201601539K Co. Reg. No.: 201601539K					

Acknowledged by Repairer

Signature:

Date:

*P-2091.4*  
*252*  
*7-1568.88*  
*S.N-230.00*  
*L-1960.00*

*3758.88*  
*3006*