

ASS. REC. BY:

REF: CSIC71 190193491 Kv f3

Special Instruction:

SURVIVOR: Kenneth

ASSIGNMENT (Office)

From (Person): Eam Dwong of C12 Date/Time: 1.11.19 15:40p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 1388T Insured: SJ P 9812

at Workshop m/s Ah Lim motor Tel: 64831206

of 10 Amc Industrial Park 2A #01-09

Policy No: DMPCSN30598219022 Claim No: SNM 19D2051 00C02

Sum Insured: Excess:

Make of Veh: D.O.A. 25.10.2019
(Client's Record) 4.11.19

CA / REV / REP. / REV 24 HRS

Date/Time: 1/11/19 4:18 p.m. Person Contacted: Zila Vehicle: IN/OUT

H.O.D. Endorsement:

Date/Time	Action/Instruction (✓) Estimate
	SMJ 1388T - X
	SJP 9812 - CCB / AG / LCC / JAG / A46342 ROP - 20/07/2016
	30/10 @ 400 4.32 Confirmed (Recd 28.1.69, 16/1)

REG. BY:

REF: 91

ASSIGNMENT

From:

Date: 4.11.2019

Estimated Cost:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SMJ 1388T

at Workshop m/s Ah Lim Motor

of 10 Amk Industrial Park 24 #01-09

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Morning 12.00pm over walky

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SMJ 1388T Regn: 05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante cc 159,

Colour:

White A/C: Insured / Std / NI / NA

Sp. Reading:

6397 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMI10841CMKU909297

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Humho

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 25/10/19

D.O.I. 4/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 1 DEC 2019

30/12/2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Date/Time, File Return to?

23/12 - typist

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Wheel and (\$)

Rep. Format: MEIMEN

Lump Sum / U/C: P/P \$4004.32

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2019		01 Nov 2019 15:40 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	TOH WEE MENG, ID: S7107983Z		
Vehicle Reg. No.:	SMJ1388T	Date of Loss:	25/10/2019 08:00 - :59
Claim Type:	TP / SNM19D205100C02	Policy/Cover Note No.:	DMPCSN30589819022
Vehicle Reg. No. (Insured):	SJP98R	Policy No. (Claimant):	P2287026
		Excess:	S\$500.00
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/11/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 983Z

Vehicle Details

Vehicle No.: SMJ1388T
Vehicle to be Exported: No
Intended Deregistration Date: 25 Oct 2019
Vehicle Make: HYUNDAI
Vehicle Model: AD AVANTE 1.6 GLS (A) S
Primary Colour: White
Manufacturing Year: 2019
Engine No.: G4FGKU145650
Chassis No.: KMHD841CMKU909297
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$14,494.00
Original Registration Date: 08 May 2019
First Registration Date: 08 May 2019
Transfer Count: 0
Actual ARF Paid: \$14,494.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 May 2029
PARF Rebate Amount: \$10,870.00

Intended COE Rebate Details

COE Expiry Date: 07 May 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$29,159.00
COE Rebate Amount: \$27,796.00
Total Rebate Amount: \$38,666.00

The information contained herein is correct as at 25 Oct 2019

OK

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TOH WEE MENG
 637B PUNGGOL DRIVE
 #14-411
 SINGAPORE 822637

Estimate No: MC1900793
Date: 30 Oct 2019
Policy No: P2287026
Veh Reg No: SMJ1388T
Make/Model: HYUNDAI AD AVANTE
 1.6 GLS

ATTN:

Your Ref No: SMJ1388T
Claim Type: Third Party
Accident Date: 25/10/2019
TP Veh Reg No: SJP98R

like
 1030am

Not withain
 Repair by paint
 8 days

Estimate Repair Cost to Vehicle No :SMJ1388T

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT BONNET HINGE LH & RH	2 PC	98.20	X
2 HEADLAMP ASSY RH	1 PC	1,756.40	✓
3 HEADLAMP LOWER BEAM RH	1 PC	28.00	7 ✓
4 FRONT BUMPER	1 PC	474.40	✓
5 FRONT BUMPER SIDE RETAINER H	1 PC	15.00	✓
6 FRONT BUMPER CLIPS	15 PC	30.00	✓
7 AIR DUCT SIDE AIR GRILLE RH	1 PC	25.00	7 ✓
8 FRONT BUMPER SIGNAL LAMP RH	1 PC	164.80	✓
9 FRONT BUMPER LOWER GARNISH	1 PC	63.70	7 X
10 FRONT BUMPER UNDER COVER	1 PC	133.31	X
11 FRONT BUMPER UNDER COVER CLIPS	8 PC	16.00	X
12 FRONT FENDER RH	1 PC	966.80	✓
13 FRONT FENDER COWLING LH & RH	2 PC	171.40	X
14 FRONT FENDER COWLING CLIPS	16 PC	32.00	X
15 WIPER WASHER TANK	1 PC	57.50	7 ✓
		4,032.51	
	Less 20%	806.50	3,226.01
Special Nett			
16 TYRE LHF - CHECK PRICE	1 PC	0.00	XX
17 SPORT RIM LHF - CHECK PRICE	1 PC	0.00	✓ 280 ✓
		0.00	0.00
LABOUR			
18 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS. TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
19 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
20 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	301
21 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR FRONT INNER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	4001
22 TO SPRAY FRONT BUMPER, FRONT FENDER RH.	1 PC	600.00	4001
		1,280.00	1,280.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TOH WEE MENG
637B PUNGGOL DRIVE
#14-411
SINGAPORE 822637

ATTN:

Estimate No: MC1900793
Date: 30 Oct 2019
Policy No: P2287026
Veh Reg No: SMJ1388T
Make/Model: HYUNDAI AD AVANTE
1.6 GLS

Your Ref No: SMJ1388T
Claim Type: Third Party
Accident Date: 25/10/2019
TP Veh Reg No: SJP98R

Estimate Repair Cost to Vehicle No :SMJ1388T

Description	Quantity	List Price	Amount
		SS	SS
	4786.01	Total	S\$ 4,506.01
		Add GST @ 7%	315.42
		Total Amount Payable	S\$ 4,821.43

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND EIGHT HUNDRED TWENTY ONE AND CENTS FORTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



LOK Auto Consultants Hence notify
the Repairer of the following:
• To survey before/after repair
• To display damaged parts during survey
• Parts prices are subject to confirmation
• Third party involvement is "Third Party" basis
• No legal responsibility is allowed
• Complimentary warranty will be provided (if
subject to final approval from Insurance Company)

Acknowledged by Repairer:

Signature:

Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TOH WEE MENG
637B PUNGGOL DRIVE
#14-411
SINGAPORE 822637

Estimate No: MC1900793
Date: 30 Oct 2019
Policy No: P2287026
Veh Reg No: SMJ1388T
Make/Model: HYUNDAI AD AVANTE
1.6 GLS

ATTN:

Your Ref No: SMJ1388T
Claim Type: Third Party — *UKE*
Accident Date: 25/10/2019 *1030am*
TP Veh Reg No: SJP98R

*Not withain
Murray B & paint
4 days*

Estimate Repair Cost to Vehicle No :SMJ1388T

Description	Quantity	List Price	Amount
		SS	SS

SPARE PARTS

1 FRONT BONNET HINGE LH & RH	2 PC	<i>R</i> 98.20	<i>X</i>
2 HEADLAMP ASSY RH	1 PC	<i>CM</i> 1,756.40	<i>✓</i>
3 HEADLAMP LOWER BEAM RH	1 PC	28.00	<i>7 Photo</i>
4 FRONT BUMPER	1 PC	<i>Bu</i> 474.40	<i>✓</i>
5 FRONT BUMPER SIDE RETAINER H	1 PC	<i>ru</i> 15.00	<i>✓</i>
6 FRONT BUMPER CLIPS	15 PC	<i>ru</i> 30.00	<i>✓</i>
7 AIR DUCT SIDE AIR GRILLE RH	1 PC	25.00	<i>7 Photo</i>
8 FRONT BUMPER SIGNAL LAMP RH	1 PC	<i>CM</i> 164.80	<i>✓</i>
9 FRONT BUMPER LOWER GARNISH	1 PC	63.70	<i>7 Photo</i>
10 FRONT BUMPER UNDER COVER	1 PC	<i>ru</i> 133.31	<i>X</i>
11 FRONT BUMPER UNDER COVER CLIPS	8 PC	<i>ru</i> 16.00	<i>X</i>
12 FRONT FENDER RH	1 PC	<i>Bu</i> 966.80	<i>✓</i>
13 FRONT FENDER COWLING LH & RH	2 PC	<i>ru</i> 171.40	<i>X</i>
14 FRONT FENDER COWLING CLIPS	16 PC	<i>ru</i> 32.00	<i>X</i>
15 WIPER WASHER TANK	1 PC	57.50	<i>7 Photo</i>
		4,032.51	
	Less 20%	806.50	3,226.01

Special Nett

16 TYRE LHF - CHECK PRICE	1 PC	0.00	<i>7</i>
17 SPORT RIM LHF - CHECK PRICE	1 PC	0.00	<i>✓</i>
		0.00	0.00

LABOUR

18 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>20d</i>
19 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	<i>60d</i>
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>30d</i>
21 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR FRONT INNER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>400d</i>
22 TO SPRAY FRONT BUMPER, FRONT FENDER RH.	1 PC	600.00	<i>40d</i>
		1,280.00	1,280.00

Auto Consultants hence notify the Repairer of the following:
To resurvey before auto spray painting.
Supply damaged parts during resurvey.
• Parts prices are subject to confirmation.
• Third party survey is on a "without prejudice" basis.
• No illegal modification to the vehicle.
• Supplemental charges may be levied and is subject to the Motor Vehicle Insurance Company.
Acknowledged by: *[Signature]*
Signature:
Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : TOH WEE MENG
637B PUNGGOL DRIVE
#14-411
SINGAPORE 822637

Claim No: MC1900793
No: MF1900802
Date: 24 Dec 2019
Policy No: P2287026
Veh Reg No: SMJ1388T
Make/Model: HYUNDAI AD AVANTE
1.6 GLS
Chassis No: KMHD841CMKU909297
TP Ins Co: CHINA

ATTN:

Your Ref No: SMJ1388T
Claim Type: Third Party
Accident Date: 25/10/2019
TP Veh Reg No: SJP98R

Repair Cost to Vehicle No (For Finalization):SMJ1388T

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP ASSY RH	1 PC	1,756.40	
2 HEADLAMP LOWER BEAM RH	1 PC	28.00	
3 FRONT BUMPER	1 PC	474.40	
4 FRONT BUMPER SIDE RETAINER H	1 PC	15.00	
5 FRONT BUMPER CLIPS	15 PC	30.00	
6 AIR DUCT SIDE AIR GRILLE RH	1 PC	25.00	
7 FRONT BUMPER SIGNAL LAMP RH	1 PC	164.80	
8 FRONT FENDER RH	1 PC	966.80	
9 WIPER WASHER TANK	1 PC	57.50	
		3,517.90	
	Less 20%	703.58	2,814.32
Special Nett			
10 SPORT RIM LHF	1 PC	280.00	
		280.00	280.00
LABOUR			
11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
12 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	60.00	
13 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
14 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT INNER PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
15 TO SPRAY FRONT BUMPER,FRONT FENDER RH.	1 PC	400.00	
		910.00	910.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : TOH WEE MENG
637B PUNGGOL DRIVE
#14-411
SINGAPORE 822637

ATTN:

Your Ref No: SMJ1388T
Claim Type: Third Party
Accident Date: 25/10/2019
TP Veh Reg No: SJP98R

Claim No: MC1900793
No: MF1900802
Date: 24 Dec 2019
Policy No: P2287026
Veh Reg No: SMJ1388T
Make/Model: HYUNDAI AD AVANTE
1.6 GLS
Chassis No: KMHD841CMKU909297
TP Ins Co: CHINA

Repair Cost to Vehicle No (For Finalization):SMJ1388T

Description	Quantity	List Price S\$	Amount S\$
		Total	S\$ 4,004.32
		Add GST @ 7%	280.30
		Total Amount Payable	S\$ 4,284.62

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED EIGHTY FOUR AND CENTS SIXTY TWO ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 04/11/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
AUTHORISED SIGNATURE
10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel 6483 1244 Fax 6483 6170

***Veron Chen (LKKAUTO)**

From: Mui Hong @ Ah Lim Motor <muihong@ahlimmotor.com.sg>
Sent: Friday, 27 December 2019 3:10 PM
To: Veron Chen (LKKAUTO)
Subject: FW: Draft Finalisation - SMJ1388T
Attachments: Draft Finalisation - SMJ1388T.pdf; DSCN7259(1).JPG; DSCN7260(1).JPG; DSCN7261(1).JPG; DSCN7262(1).JPG; DSCN7263(1).JPG; DSCN7264(1).JPG; DSCN7265(1).JPG; DSCN7266(1).JPG; DSCN7267(1).JPG; DSCN7268(1).JPG; DSCN7269(1).JPG; DSCN7270(1).JPG; DSCN7271(1).JPG; DSCN7272(1).JPG; DSCN7273(1).JPG; DSCN7274(1).JPG; DSCN7275(1).JPG; DSCN7276(1).JPG; DSCN7277(1).JPG; DSCN7278(1).JPG; DSCN7279(1).JPG; DSCN7280(1).JPG; DSCN7281(1).JPG; DSCN7281(1).JPG; DSCN7282(1).JPG; DSCN7283(1).JPG; DSCN7284(1).JPG; DSCN7285(1).JPG

Dear Veron,

As per request

Best Regards,

Kee Mui Hong
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170

From: Mui Hong @ Ah Lim Motor
Sent: Tuesday, 24 December 2019 3:13 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: Draft Finalisation - SMJ1388T

Dear Kenneth,

Pls see attached the Draft Finalisation – SMJ1388T for your approval.

Pls advise

Thanks

Best Regards,

Kee Mui Hong
Ah Lim Motor @ AMK
10, Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint S568047
Tel : 6483 1244 Fax : 6483 6170

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19019349/KVF3N2
Date: 07/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30589819022
Claimant Vehicle No: SMJ1388T Insured Vehicle No: SJP98R
Date of Loss: 25/10/2019 Nature of Claim: TP Claim No: SNM19D205100C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMJ1388T
Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A) Engine No: G4FGKU145650
Reg. Date: 08/05/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU909297
Colour: White Odometer: 6397 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Kumho 9 mm Rear Left Side: Kumho 9 mm
Front Right Side: Kumho 9 mm Rear Right Side: Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,506.01	3,094.32	411.69	11.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	910.00	370.00	28.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,786.01	4,004.32	781.69	16.33
+ GST 7.00/7.00% (S\$)	335.02	280.30	54.72	16.33
Nett Amount (S\$)	5,121.03	4,284.62	836.41	16.33

INSPECTION

Date of Assignment: 01/11/2019
Date Inspected: 04/11/2019 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jan 2020)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ1388T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT BONNET HINGE LH & RH	Repair	98.20 FL	*- FL
2	1		*HEADLAMP ASSY RH	Cracked	1,756.40 FL	*1,756.40 FL
3	1		*HEADLAMP LOWER BEAM RH	Cracked	28.00 FL	*28.00 FL
4	1		*FRONT BUMPER	Buckled	474.40 FL	*474.40 FL
5	1		*FRONT BUMPER SIDE RETAINER H	Necessary	15.00 FL	*15.00 FL
6	15		*FRONT BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
7	1		*AIR DUCT SIDE AIR GRILLE RH	Cracked	25.00 FL	*25.00 FL
8	1		*FRONT BUMPER SIGNAL LAMP RH	Cracked	164.80 FL	*164.80 FL
9	1		*FRONT BUMPER LOWER GARNISH	Serviceable	63.70 FL	*- FL
10	1		*FRONT BUMPER UNDER COVER	Serviceable	133.31 FL	*- FL
11	8		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	16.00 FL	*- FL
12	1		*FRONT FENDER RH	Buckled	966.80 FL	*966.80 FL
13	2		*FRONT FENDER COWLING LH & RH	Serviceable	171.40 FL	*- FL
14	16		*FRONT FENDER COWLING CLIPS	Not Necessary	32.00 FL	*- FL
15	1		*WIPER WASHER TANK	Dented	57.50 FL	*57.50 FL
16	1		*TYRE LHF (NPA)	Serviceable	0.00 FS	*- FS
17	1		*SPORT RIM LHF	Dented	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,312.51	3,797.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	806.50	703.58
Total Parts (\$\$)	3,506.01	3,094.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS.TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	80.00	60.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	30.00
4	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT INNER PANEL INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	500.00	400.00
5	TO SPRAY FRONT BUMPER,FRONT FENDER RH	New	600.00	400.00
Gross Labour Cost (S\$)			1,280.00	910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >