

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG19019373/AGA3Q2
Date: 05/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	GBG5666K	Insured Vehicle No :	SMG7326Z
Date of Loss:	27/10/2019	Nature of Claim:	TP
		Claim No:	1444098623SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG5666K		
Make & Model:	SUZUKI EVERY, 658cc PA 660 (A)	Engine No:	R06A2116780
Reg. Date:	30/08/2017 (Man. Year: 2017)	Chassis No:	DA17V251883
Colour:	White	Odometer:	53177 km
Engine Capacity:	658 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	155R12C	Rear Tyre Size:	155R12C
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,237.31	2,722.27	5,515.04	66.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,890.00	1,780.00	48.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,907.31	4,612.27	7,295.04	61.27
Approved Total (Overridden) (S\$)		3,600.00		

Nett Amount (S\$)	11,907.31	3,600.00	8,307.31	69.77
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,087.45		

INSPECTION

Date of Assignment: 30/10/2019

Date Inspected: 30/10/2019

Estimated Period of Repair: 6.0 days

Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre
 Singapore 417807

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,375.00 FL	*899.60 FL
2	1		*REAR TAILGATE LOCK	Damaged	279.00 FL	*145.00 FL
3	1		*REAR TAILGATE CENTRE LOGO	Necessary	65.00 FL	*45.00 FL
4	2		*REAR TAILGATE ABSORBER LH & RH	Not Necessary	600.00 FL	*- FL
5	1		*REAR TAILGATE INNER BOARD	Not Necessary	418.00 FL	*- FL
6	1		*REAR TAILGATE RUBBER	Not Necessary	235.00 FL	*- FL
7	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	101.00 FL	*- FL
8	1		*REAR BUMPER	Deformed	511.00 FL	*511.00 FL
9	2		*REAR BUMPER SIDE RETAINER LH & RH	Necessary	161.00 FL	*161.00 FL
10	1		*REAR BUMPER SIDE LOWER GARNISH	Not Necessary	250.20 FL	*- FL
11	1		*REAR END PANEL	Dented	543.50 FL	*543.50 FL
12	1		*REAR END PANEL AIR VENT	Not Necessary	95.00 FL	*- FL
13	1		*REAR FLOOR PANEL	Not Necessary	1,120.00 FL	*- FL
14	1		*REAR FLOOR PANEL TOP MAT	Not Necessary	695.00 FL	*- FL
15	1		*REAR TAILLAMP LH & RH	N/S Cracked	691.20 FL	*175.20 FL
16	1		*REAR EXHAUST SILENCER	Not Necessary	785.00 FL	*- FL
17	1		*REAR EXHAUST SILENCER RUBBER	Not Necessary	98.00 FL	*- FL
18	1		*REAR FENDER INNER SHIELD LH	Not Necessary	163.00 FL	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
20	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
21	1		*REAR TAILGATE INNER BOARD CLIPS	Not Necessary	100.00 FS	*- FS
22	1		*STICKER 70KM/H	Necessary	70.00 FS	*15.00 FS
23	1		*STICKER EVERY	Necessary	70.00 FS	*35.00 FS
24	1		*REAR BUMPER STICKER	Necessary	180.00 FS	*150.00 FS
25	1		*REAR TAILGATE STICKER	Necessary	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,055.90	2,970.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	818.59	248.03
Total Parts (\$\$)	8,237.31	2,722.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,600.00	800.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	800.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION	New	150.00	30.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	210.00	60.00
5	CAVITY TREATMENT ON NEW PARTS	New	120.00	0.00
6	TO REMOVE AND REFIX REAR BOOTLID MECHANISM	New	150.00	80.00
7	TO CONDUCT WATER SEEPAGE TEST	New	120.00	0.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			3,670.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >