

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19019376/ADA3Q2**Date:** 30/10/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMM1748Y **Insured Vehicle No :** SKQ9281B

Date of Loss: 24/10/2019 Nature of Claim: TP Claim No: 2633624711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1748Y	Engine No:	LEB6447970
Make & Model:	HONDA GRACE HYBRID, 1.5 DX (A)	Chassis No:	GM41207944
Reg. Date:	19/06/2019 (Man. Year: 2018)	Odometer:	59061 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,793.00	560.00	1,233.00	68.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	430.00	530.00	55.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,753.00	990.00	1,763.00	64.04
Approved Total (Overridden) (S\$)		800.00		
(S\$)	2,753.00	800.00	1,953.00	70.94
+ GST 7.00/7.00% (S\$)	192.71	56.00	136.71	70.94
Nett Amount (S\$)	2,945.71	856.00	2,089.71	70.94
+ Loss of Use (2.0 x S\$70.00/day) (S\$)		140.00		
(S\$)		996.00		
Liab Amount (50.00%) (S\$)		498.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		505.45		

INSPECTION

Date of Assignment: 25/10/2019

Date Inspected: 25/10/2019 Inspected At:

Green Forest Automobile Pte Ltd (Kaki Bukit)
8 Kaki Bukit Avenue 4, #05-25,,
Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H FENDER	Dented	655.00 F	*655.00 FL
2	1		*FRONT R/H FENDER COWLING	Not Necessary	188.00 F	*- FL
3	10		*FRONT R/H FENDER COWLING CLIPS	Not Necessary	50.00 F	*- FL
4	1		*FRONT R/H FENDER HYBRID LOGO	Necessary	45.00 F	*45.00 FL
5	1		*FRONT RH SIDE MIRROR ASSY	Repair	855.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	1,793.00	700.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	140.00
Total Parts (\$)	1,793.00	560.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	60.00	30.00
2	TUFF KOTE	New	100.00	0.00
3	PANEL BEATING	New	400.00	200.00
4	SPRAY PAINTING	New	400.00	200.00
Gross Labour Cost (\$\$)			960.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >