

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19019380/UDA3N2

**Date:** 20/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLU9218C **Insured Vehicle No :** SLR1640J

Date of Loss: 30/10/2019 Nature of Claim: TP Claim No: 4517314529SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLU9218C</b>		
Make & Model:	HONDA STREAM, 1.8 X (A)	Engine No:	R18A1769701
Reg. Date:	18/07/2008 (Man. Year: 2008)	Chassis No:	RN61062520
Colour:	Brown	Odometer:	132831 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,656.32	2,510.24	1,146.08	31.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,830.00	700.00	27.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,186.32</b>	<b>4,340.24</b>	<b>1,846.08</b>	<b>29.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>(S\$)</b>	6,186.32	3,000.00	3,186.32	51.51
<b>+ GST 7.00/7.00% (S\$)</b>	433.04	210.00	223.04	51.51
<b>Nett Amount (S\$)</b>	<b>6,619.36</b>	<b>3,210.00</b>	<b>3,409.36</b>	<b>51.51</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,717.45</b>		

### INSPECTION

Date of Assignment: 18/11/2019

Date Inspected: 18/11/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd  
(Bedok)  
Blk 3011, Bedok Industrial Park E.,  
#01-2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	903.20 FL	*903.20 FL
2	1		*TAILGATE EMBLEM	Not Necessary	35.00 FL	*- FL
3	1		*TAILGATE LOGO -STREAM	Necessary	24.70 FL	*24.70 FL
4	1		*TAILGATE INNER LOCK	Dented / Shorted	181.50 FL	*181.50 FL
5	1		*TAILGATE DAMPER LH	Not Necessary	118.60 FL	*- FL
6	1		*TAILGATE DAMPER RH	Not Necessary	118.60 FL	*- FL
7	1		*TAILLAMP O/S	Scratched	352.80 FL	*352.80 FL
8	1		*END PANEL	Badly Dented	306.70 FL	*306.70 FL
9	1		*REAR BUMPER	Distorted	588.60 FL	*588.60 FL
10	1		*REAR BUMPER RETAINER RH	Bent	19.40 FL	*19.40 FL
11	1		*REAR BUMPER RETAINER LH	Not Necessary	19.40 FL	*- FL
12	1		*TAIL LAMP PANEL RH	Repair	145.90 FL	*- FL
13	1		*REAR EXHAUST PIPE	Repair	514.20 FL	*- FL
14	1		*REAR BUMPER BRACKET RH	Bent	20.90 FL	*20.90 FL
15	1		*REAR BUMPER BRACKET LH	Not Necessary	20.90 FL	*- FL
16	1		*TAILGATE WINDSCREEN MOULDING	Necessary	65.00 FL	*65.00 FL
17	2		*WINDSCREEN SEALANT	Necessary	48.00 FS	*40.00 FS
18	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*SET REVERSE CAMERA	Cracked	580.00 FS	*300.00 FS
20	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
21	1		*REAR FLOOR PANEL (NPA)	Repair	0.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,343.40</b>	<b>3,002.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	687.08	492.56
<b>Total Parts (\$\$)</b>	<b>3,656.32</b>	<b>2,510.24</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,000.00	800.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	800.00
3	ANTI RUST COATING	New	300.00	60.00
4	TO REMOVE & REFIT WINDSCREEN	New	180.00	120.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,530.00</b>	<b>1,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >