

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8190H
GUNASILAN RACHAEL VANITHA
NO

SINGAPORE
TEL : FAX :
PH : 91082084
ATTN :

ESTIMATE BILL

Number : EB00005320
Date : 01/11/2019
Case No : AD00010764
Vehicle No : SLU9218C
Chassis : RN61062520
Year of Mfr 2008
Policy No
Model : HONDA STREAM

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	TAILGATE <i>Bodys</i>	1.0	903.20	20	722.56
2	TAILGATE EMBLEM <i>11</i>	1.0	35.00	20	28.00
3	TAILGATE LOGO - STREAM <i>11</i>	1.0	24.70	20	19.76
4	TAILGATE INNER LOCK <i>10/11</i>	1.0	181.50	20	145.20
5	TAILGATE DAMPER LH <i>11</i>	1.0	118.60	20	94.88
6	TAILGATE DAMPER RH <i>11</i>	1.0	118.60	20	94.88
7	REAR FENDER LAMP RH <i>tail lamp o/s scr</i>	1.0	352.80	20	282.24
8	END PANEL <i>Bodys</i>	1.0	306.70	20	245.36
9	REAR BUMPER <i>D.S</i>	1.0	588.60	20	470.88
10	REAR BUMPER RETAINER RH <i>Bed</i>	1.0	19.40	20	15.52
11	REAR BUMPER RETAINER LH <i>11</i>	1.0	19.40	20	15.52
12	TAIL LAMP PANEL RH <i>Rx</i>	1.0	145.90	20	116.72
13	REAR EXHAUST PIPE <i>R</i>	1.0	514.20	20	411.36
14	REAR BUMPER BRACKET RH <i>Bent</i>	1.0	20.90	20	16.72
15	REAR BUMPER BRACKET LH <i>11</i>	1.0	20.90	20	16.72
16	TAILGATE WINDSCREEN MOULDING <i>11</i>	1.0	65.00	20	52.00
List Price - Parts Sub Total					2,748.32
17	WINDSCREEN SEALANT <i>11</i>	2.0	24.00	0	48.00
18	REVERSE SENSOR <i>shrub</i>	1.0	280.00	0	280.00
19	REVERSE CAMERA <i>11</i>	1.0	580.00	0	580.00
20	REAR FENDER RH - REPAIR <i>Rx</i>	1.0			
21	REAR FLOOR PANEL - REPAIR <i>Rx</i>	1.0			
Special Nett Price - Parts Sub Total					908.00
Parts Total					3,656.32
22	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
23	SPRAY PAINT ON THE AFFECTED AREAS	1.0	900.00	0	900.00
24	ANTI-RUST COATING	1.0	300.00	0	300.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
26	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,530.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Page 1 of 2

* N = Item not subjected to GST

Issued by : Anysia

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011.BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX8190H
GUNASILAN RACHAEL VANITHA
NO

SINGAPORE
TEL : FAX :
PH : 91082084
ATTN :

ESTIMATE BILL

Number : EB00005320
Date : 01/11/2019
Case No : AD00010764
Vehicle No : SLU9218C
Chassis: RN61062520
Year of Mfr 2008
Policy No
Model : HONDA STREAM

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : SIX THOUSAND SIX HUNDRED NINETEEN AND CENTS THIRTY-SIX ONLY			Less Excess		0.00
			SUBTOTAL		6,186.32
			GST 7.00%		433.04
			TOTAL		6,619.36

Date of accident : 30/10/2019 01:35 PM. Place : BRADDELL ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE