

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III19019387/ABA3Q2**Date:** 03/12/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKB1012T	Insured Vehicle No :	SHA7865A
Date of Loss: 30/10/2019	Nature of Claim: TP	Claim No: MCT19100710

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB1012T		
Make & Model:	MERCEDES-BENZ S320L, 3.0 R19 LED (A)	Engine No:	27682430378119
Reg. Date:	01/12/2016 (Man. Year: 2016)	Chassis No:	WDD2221622A274498
Colour:	Silver	Odometer:	17498 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40 R19	Rear Tyre Size:	275/45 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	49,786.00	20,621.60	29,164.40	58.58	
Miscellaneous Items	0.00	0.00	0.00		
Labour	7,330.00	3,750.00	3,580.00	48.84	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	57,116.00	24,371.60	32,744.40	57.33	
Approved Total (Overridden) (S\$)		16,000.00			
	(S\$)	57,116.00	16,000.00	41,116.00	71.99
+ GST 7.00/7.00% (S\$)	3,998.12	1,120.00	2,878.12	71.99	
Nett Amount (S\$)	61,114.12	17,120.00	43,994.12	71.99	
+ Loss of Use (12.0 x S\$120.00/day) (S\$)		1,440.00			
+ Doc/Search Fee (S\$)		7.45			
	Nett Liability (S\$)	18,567.45			
	Global Sum Settlement (S\$)	18,550.00			

INSPECTION

Date of Assignment:	30/10/2019	
Date Inspected:	30/10/2019 Inspected At:	New Hock Teck Motor Pte Ltd (HQ) 1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2020)
Parts: 143	MERCEDES-BENZ S320L 3.0 R19 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB1012T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR R/H DOOR	Dented	3,950.00 F	*3,280.00 FL
2	2		*REAR R/H DOOR HINGE	Not Necessary	490.00 F	*- FL
3	1		*REAR R/H DOOR GLASS TOP CHROME	Not Necessary	316.00 F	*- FL
4	1		*REAR R/H DOOR GLASS LOWER CHROME	Not Necessary	420.00 F	*- FL
5	1		*REAR R/H DOOR LOWER MOULDING	Not Necessary	205.00 F	*- FL
6	1		*REAR R/H DOOR LOWER CHROME	Cut	320.00 F	*320.00 FL
7	1		*REAR R/H DOOR WEATHERSTRIP	Necessary	330.00 F	*330.00 FL
8	2		*REAR R/H DOOR FRAME STICKER	Necessary	190.00 F	*190.00 FL
9	1		*REAR R/H DOOR INNER LOCK	Damaged	855.00 F	*855.00 FL
10	1		*REAR R/H DOOR INNER TRIM BOARD	Not Necessary	3,570.00 F	*- FL
11	10		*REAR R/H DOOR INNER TRIM BOARD CLIP	Not Necessary	80.00 F	*- FL
12	1		*REAR R/H DOOR WINDOW REGULAR & MOTOR ASSY	Damaged	1,925.00 F	*995.00 FL
13	1		*REAR R/H DOOR WINDOW SUNSHADE MOTOR ASSY	Not Necessary	2,380.00 F	*- FL
14	1		*REAR R/H DOOR PILALR	Repair	3,890.00 F	*- FL
15	1		*REAR R/H DOOR FRAME PANEL	Repair	4,810.00 F	*- FL
16	1		*REAR R/H FENDER	Buckled	6,340.00 F	*5,488.00 FL
17	1		*REAR R/H TYRE	Punctured	680.00 FS	*380.00 FS
18	1		*REAR R/H RIM	Cut	2,550.00 FS	*1,500.00 FS
19	1		*REAR R/H WHEEL HUB COVER	Not Necessary	155.00 F	*- FL
20	1		*REAR R/H LOWER ARM	Bent	580.00 F	*580.00 FL
21	1		*REAR R/H UPPER ARM	Bent	685.00 F	*685.00 FL
22	1		*REAR R/H CONTROL ARM	Bent	695.00 F	*695.00 FL
23	1		*REAR R/H KNUCKLE ARM & BEARING ASSY	Damaged	2,270.00 F	*1,940.00 FL
24	1		*REAR R/H SHOCK ABSORBER	Damaged	4,855.00 F	*4,570.00 FL
25	1		*REAR R/H DRIVE SHAFT	Not Necessary	3,510.00 F	*- FL
26	1		*REAR BUMPER	Repair	2,265.00 F	*- FL
27	10		*REAR BUMPER CLIP	Not Necessary	80.00 F	*- FL
28	1		*R/H ROCKER PANEL SKIRT	Deformed	1,290.00 F	*866.00 FL
29	10		*R/H ROCKER PANEL SKIRT CLIP	Necessary	100.00 F	*30.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 49,786.00 22,704.00
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 2,082.40

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	49,786.00	20,621.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT REAR R/H DOOR ,GLASS,LOCK ,RUBBER ,FRAME STICKER,TRIM BOARD ,REGULATOR MOTOR & SUNSHADE MOTOR	New	480.00	150.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
3	GUM	New	80.00	80.00
4	TO REMOVE & REFITREAR R/H FUEL TANK	New	380.00	120.00
5	TO REMOVE & REFIT REAR DRIVE SHAFT & UNDERCARRIAGE	New	680.00	350.00
6	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
7	TO CHECK WIRING	New	200.00	50.00
8	TO RESET COMPUTER	New	450.00	150.00
9	TOWING FEE	New	150.00	150.00
10	TUFF KOTE	New	200.00	100.00
11	PANEL BEATING	New	2,400.00	1,200.00
12	SPRAY PAINTING	New	2,000.00	1,200.00
Gross Labour Cost (\$\$)			7,330.00	3,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >