

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI19019425/Uga3s2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date: 17-07-2020 Code: EQI		
1.		Policy Particulars	- THIRD PARTY CLAIM		
	ured Veh.	YP 5043M	Veh. Inspected	GBD 1851J	
	licy No.	DMCPHQ19-001490	Coverage (\$)	0.00	
_	aim No.	DM19HO02983/JT	Excess (\$)	0.00	
	sign From		Assign Date	04/11/2019	
2. Vehicle Particulars & Condition					
	ke & Model	NISSAN CABSTAR (M)	c.c	2953	
1	gine No.	HIDDEN	Year of Reg.	2014	
	assis No.	JN1SC2F24Z0856016	Colour	WHITE	
Ode	ometer	163037	Steering	IN ORDER	
Bra	akes	IN ORDER	Modification	NIL	
Gei	neral	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
R/H	H Front Tyre	195 R15	ULTIMA-X	6 mm	
L/H	I Front Tyre	195 R15	ULTIMA-X	6 mm	
R/H	HRear Tyre	155 R13 (D)	ULTIMA-X	6/6 mm	
	l Rear Tyre	155 R13 (D)	ULTIMA-X	6/6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
		04/11/2019	Inspection Date	04/11/2019	
Sur	rvey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
EST	TIMATED NORM	MAL PERIOD FOR REPAIR:	5 Working Days		