

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019437/GPA3Q2

Date: 30/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100394412
Claimant Vehicle No :	SLG25A	Insured Vehicle No :	SKQ5373X
Date of Loss:	24/10/2019	Nature of Claim:	TP
		Claim No:	7814617040SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG25A		
Make & Model:	MITSUBISHI EVO 10, 2.0 GSR (M)	Engine No:	4G63MM1549
Reg. Date:	03/11/2006 (Man. Year: 2006)	Chassis No:	CT9A0500890
Colour:	Grey	Odometer:	256201 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40Z R18	Rear Tyre Size:	235/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,027.30	737.10	290.20	28.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	650.00	200.00	23.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,877.30	1,387.10	490.20	26.11
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	1,877.30	1,100.00	777.30	41.41
+ GST 7.00/7.00% (S\$)	131.41	77.00	54.41	41.40
Nett Amount (S\$)	2,008.71	1,177.00	831.71	41.41
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,579.00		
Global Sum Settlement (S\$)		1,550.00		

INSPECTION

Date of Assignment:	04/11/2019	
Date Inspected:	14/02/2020 Inspected At:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	769.00 FL	*769.00 FL
2	1		*REAR BUMPER BEAM	Not Necessary	90.00 FL	*- FL
3	2		*REAR BUMPER RETAINER	Not Necessary	92.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
5	2		*REAR BUMPER NUMBER PLATE LAMP	Not Necessary	96.00 FL	*- FL
6	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,137.00	819.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	109.70	81.90
Total Parts (\$\$)	1,027.30	737.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT	New	300.00	200.00
2	TO PAINT TREATING	New	300.00	250.00
3	LABOUR CHARGES	New	250.00	200.00
Gross Labour Cost (S\$)			850.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >