

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19019449/AES3Q2

**Date:** 23/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SLX3063E **Insured Vehicle No :** SJA1757U

**Date of Loss:** 25/10/2019 **Nature of Claim:** TP **Claim No:** 8161821184SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SLX3063E</b>                   | Engine No:  | R16B25500108      |
| Make & Model:               | HONDA CIVIC, 1.3 EC8 (M)          | Chassis No: | MRHFC5650JT000051 |
| Reg. Date:                  | 23/03/2018 (Man. Year: 2018)      | Odometer:   | 145031 km         |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1597 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |     |                          |     |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification:    | No  | Pre-accident Condition:  |     |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/55 R16    | Rear Tyre Size:  | 205/55 R16    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                           | 9,838.24         | 3,797.68        | 6,040.56        | 61.40        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00            |              |
| Labour                                          | 4,360.00         | 1,920.00        | 2,440.00        | 55.96        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00            |              |
| Towing                                          | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>14,198.24</b> | <b>5,717.68</b> | <b>8,480.56</b> | <b>59.73</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>4,500.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                        | <b>14,198.24</b> | <b>4,500.00</b> | <b>9,698.24</b> | <b>68.31</b> |
| <b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b> |                  | 400.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 29.00           |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>4,929.00</b> |                 |              |

### INSPECTION

Date of Assignment: 05/11/2019

Date Inspected: 05/11/2019 Inspected At: Cas Garage Pte Ltd (HQ)  
No.1, Kaki Bukit Ave 6, #02-22  
Autobay  
Singapore 417883

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition            | Repairer's | Amount     |
|-----|-----|----------|---------------------------------------|----------------------|------------|------------|
| 1   | 1   |          | *BOOTLID                              | Dented               | 785.60 FL  | *572.10 FL |
| 2   | 2   |          | *BOOTLID STOPPER                      | Not Necessary        | 40.00 FL   | *- FL      |
| 3   | 1   |          | *BOOTLID OUTER GARNISH                | Not Necessary        | 298.60 FL  | *- FL      |
| 4   | 1   |          | *BOOTLID SMART KEY ANTENNA            | Cracked              | 152.30 FL  | *152.30 FL |
| 5   | 1   |          | *BOOTLID BUZZER                       | Cracked              | 105.60 FL  | *105.60 FL |
| 6   | 1   |          | *BOOTLID INNER TRIM                   | Not Necessary        | 215.60 FL  | *- FL      |
| 7   | 1   |          | *BOOTLID EMBLEM CIVIC                 | Not Necessary        | 78.50 FL   | *- FL      |
| 8   | 1   |          | *BOOTLID EMBLEM IV-TEC                | Not Necessary        | 73.60 FL   | *- FL      |
| 9   | 1   |          | *BOOTLID LOGO                         | Not Necessary        | 89.70 FL   | *- FL      |
| 10  | 2   |          | *BOOTLID LAMP                         | Not Necessary        | 411.20 FL  | *- FL      |
| 11  | 2   |          | *BOOTLID LAMP INNER SEALER            | Not Necessary        | 76.00 FL   | *- FL      |
| 12  | 1   |          | *BOOTLID INNER LOCK                   | Damaged              | 169.50 FL  | *169.50 FL |
| 13  | 1   |          | *BOOTLID LOWER CATCH                  | Not Necessary        | 46.20 FL   | *- FL      |
| 14  | 2   |          | *BOOTLID HINGES                       | Not Necessary        | 150.40 FL  | *- FL      |
| 15  | 1   |          | *BOOTLID WEATHERSTRIP                 | Cut                  | 159.20 FL  | *159.20 FL |
| 16  | 1   |          | *REAR BUMPER                          | Deformed             | 758.90 FL  | *668.20 FL |
| 17  | 2   |          | *REAR BUMPER RETAINERS                | Necessary            | 104.60 FL  | *104.60 FL |
| 18  | 2   |          | *REAR BUMPER CENTRE BRACKETS          | Not Necessary        | 91.20 FL   | *- FL      |
| 19  | 1   |          | *REAR BUMPER LOWER SIDE GARNISH RH    | Not Necessary        | 69.70 FL   | *- FL      |
| 20  | 1   |          | *REAR BUMPER REINFORCEMENT            | Dented               | 305.80 FL  | *305.80 FL |
| 21  | 2   |          | *REAR BUMPER SIDE REFLECTORS          | Not Necessary        | 119.60 FL  | *- FL      |
| 22  | 2   |          | *REAR BUMPER SIDE REFLECTORS COVER    | Not Necessary        | 197.40 FL  | *- FL      |
| 23  | 4   |          | *REAR BUMPER REVERSE SENSOR           | Damaged (2 PCS ONLY) | 580.00 FL  | *290.00 FL |
| 24  | 4   |          | *REAR BUMPER REVERSE SENSOR HOLDER    | Not Necessary        | 144.00 FL  | *- FL      |
| 25  | 1   |          | *REAR REVERSE SENSOR HARDNESS         | Not Necessary        | 252.30 FL  | *- FL      |
| 26  | 1   |          | *TAILLAMPS                            | N/S Cracked          | 785.20 FL  | *546.00 FL |
| 27  | 1   |          | *TAILLAMPS INNER SEALER               | N/S Necessary        | 76.40 FL   | *38.20 FL  |
| 28  | 2   |          | *TAILLAMPS PANEL                      | Repair               | 691.60 FL  | *- FL      |
| 29  | 2   |          | *REAR FENDER INNER COWLING            | Not fitted           | 312.40 FL  | *- FL      |
| 30  | 1   |          | *REAR END PANEL                       | Dented               | 568.20 FL  | *385.00 FL |
| 31  | 1   |          | *REAR END PANEL TOP GARNISH           | Deformed             | 125.60 FL  | *125.60 FL |
| 32  | 2   |          | *REAR END PANEL STOPPER               | Not Necessary        | 70.00 FL   | *- FL      |
| 33  | 1   |          | *SPARE TYRE PANEL TOP BOARD           | Not Necessary        | 185.90 FL  | *- FL      |
| 34  | 1   |          | *SPARE TYRE TOOL SPONGE               | Not Necessary        | 98.50 FL   | *- FL      |
| 35  | 1   |          | *REAR SILENCER BOX                    | Not Necessary        | 750.20 FL  | *- FL      |
| 36  | 2   |          | *REAR SILENCER BOX MOUNTING           | Not Necessary        | 76.00 FL   | *- FL      |
| 37  | 1   |          | *REAR SILENCER HEAT SHIELD            | Not Necessary        | 119.80 FL  | *- FL      |
| 38  | 1   |          | *SET REAR NUMBER PLATE WITH CASING    | Not Necessary        | 50.00 FS   | *- FS      |
| 39  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary            | 30.00 FS   | *30.00 FS  |
| 40  | 2   |          | *SET BOOTLID LAMP CLIPS               | Not Necessary        | 60.00 FS   | *- FS      |
| 41  | 2   |          | *TAILLAMP CLIPS                       | Not Necessary        | 60.00 FS   | *- FS      |
| 42  | 1   |          | *REAR CENTRE LOWER LIP (ACCESSORIES)  | Cracked              | 680.00 FS  | *500.00 FS |
| 43  | 2   |          | *REAR EXHAUST GARNISH (ACCESSORIES)   | Not Necessary        | 360.00 FS  | *- FS      |
| 44  | 1   |          | *REAR SIDE LIPS (ACCESSORIES)         | O/S Deformed         | 900.00 FS  | *300.00 FS |
| 45  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary            | 30.00 FS   | *10.00 FS  |
| 46  | 1   |          | *SET BOOTLID OUTER GARNISH CLIPS      | Not Necessary        | 30.00 FS   | *- FS      |
| 47  | 2   |          | *SET REAR FENDER COWLING CLIPS        | Not Necessary        | 60.00 FS   | *- FS      |
| 48  | 1   |          | *SET BOOTLID INNER TRIM CLIPS         | Not Necessary        | 30.00 FS   | *- FS      |
| 49  | 2   |          | *END PANEL INSULATOR SEAL             | Necessary            | 80.00 FS   | *60.00 FS  |

Report was unsubmitted during this print-out.

| No.                                                       | Qty | Part<br>No. | Particulars | Condition | Repairer's       | Amount          |
|-----------------------------------------------------------|-----|-------------|-------------|-----------|------------------|-----------------|
| F=Franchise part. S=SpcNett. L=ListItemDisc.              |     |             |             |           |                  |                 |
| <b>Sub Total (S\$)</b>                                    |     |             |             |           | <b>11,705.30</b> | <b>4,522.10</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (S\$)</b> |     |             |             |           | 1,867.06         | 724.42          |
| <b>Total Parts (S\$)</b>                                  |     |             |             |           | <b>9,838.24</b>  | <b>3,797.68</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                            |          |                 |                 |
| 1                               | TO RENEW DAMAGED PARTS ,REPLACE ,BEAT WELD<br>REALIGN AND ALIGNE ALL PARTS | New      | 1,600.00        | 800.00          |
| 2                               | TO RESPRAY AFFECTED AREAS                                                  | New      | 1,600.00        | 800.00          |
| 3                               | TO TUFFCOAT AFFECTED AREA                                                  | New      | 200.00          | 60.00           |
| 4                               | TO REMOVE/REFIT INTERIOR UPHOLSTERY                                        | New      | 150.00          | 60.00           |
| 5                               | TO APPLY SEALANT TO THE AFFECTED AREAS                                     | New      | 150.00          | 60.00           |
| 6                               | TO REMOVE/REFIT WIRING CHECKS ON REAR<br>TAILLAMPS                         | New      | 120.00          | 30.00           |
| 7                               | TO CONDUCT WATER LEAKAGE TEST                                              | New      | 150.00          | 0.00            |
| 8                               | LABOUR TO REMOVE/REFIT REAR SILENCER BOX                                   | New      | 120.00          | 0.00            |
| 9                               | TO REMOVE/REPLACE REVERSE SENSOS AND<br>DISTANCE SETTLING                  | New      | 150.00          | 50.00           |
| 10                              | TO REMOVE AND REPLACE BOOTLID MECHANISM                                    | New      | 120.00          | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                            |          | <b>4,360.00</b> | <b>1,920.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >