

102200

INS. CASE OWNER:

Sundari

CC 3/III1901

A4G2, K967

LKK: IDAC

Surveyor:

Kenneth

ASSIGNMENT
DOI: 1/11/19

Date / Time: 1/11/19

Registered in Merimen: 4/11/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 2303H

Claim No.:

MITI9100737

Name of Insured:

UPU

Policy No.:

2102002

Insured Tel No.:

HP:

Make / Model:

Hyundai

Excess Sec II :SS

D.O.A.:

20/10/19

Place of Accident:

MONSIEUR RD

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

WONG KWAN PATT

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHF 743M



INSRS:
WSP: TRANS
Tel: CMB
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

| Date/ Time | STAGE | DATE / PIC |
|------------|--|-------------------------------------|
| 1/11 | Pending liability approval | |
| 5/2 | RAC WOR TO TP (Pending LOD) | |
| 14/2 | LOD in file pass Bt type report | |
| 20/2 | Prdny mandate approval | |
| 26/2 | offer call @ \$9994.04 as per LOD, file pass su 4 sand dv. | |
| | Documentation Check List: | Handler Typist |
| | Notification ltr (if non-pickup) | <input checked="" type="checkbox"/> |
| | After call ltr to OI: | <input checked="" type="checkbox"/> |
| | Authorisation To Act: | <input checked="" type="checkbox"/> |
| | Release Voucher: | <input checked="" type="checkbox"/> |
| | Final Repair Bill: | <input checked="" type="checkbox"/> |
| | Car Rental Invoice: | <input checked="" type="checkbox"/> |
| | Towing Invoice: | <input checked="" type="checkbox"/> |
| | LTA / GIA : | <input checked="" type="checkbox"/> |
| | Medical Bill: | <input checked="" type="checkbox"/> |
| | PIR: | <input checked="" type="checkbox"/> |
| | Mandate/Reject Instruction: | <input checked="" type="checkbox"/> |
| | LOD | <input checked="" type="checkbox"/> |
| | Payment Breakdown Form: | <input checked="" type="checkbox"/> |
| | Post-Repair Photos: | <input checked="" type="checkbox"/> |
| | Others: | <input checked="" type="checkbox"/> |

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: KENNETH

FINALIZATION Date/Time: Confirm with: Confirm by: KENNETH
 Repair Cost: 45 SS 8300.00 (7 days) Reduction: \$51,157.79 @ 86

FINAL SETTLEMENT Date/Time: Confirm with: Confirm by: KENNETH
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 77

Repair Cost: W/ST SS 8881.00

Loss of Rental (LOR): SS 793.04 (8 days) x \$99.13

Loss of Use (LOU): SS - (\$ x days)

Loss of Income (LOI): SS 320.00 (\$ 40 x 2 days)

LOR only LOU only LOR + LOU LOR + LOI (Tick only one)

GIA/LTA Search SS -

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS 9994.04 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Confirm by: KENNETH

Payee 1: SS 9994.04 Name 1: TRANS-CAR AUTO SERVICES PE Ltd

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

COPY SENT
5/3/2020

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

AAD1910-239

*Not Authorized
L/Sep @ 8300h*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHF 743M
VF1ABL15AUC282731
RENAULT
LATITUDE
30.10.19
III
30/6/2016

01 NOV 2019

| PART | | LIST | |
|------|-------------------------------|------|---|
| 1 | 1 BUMPER COVER REAR | \$ | <i>By</i> 561.70 ✓ |
| 2 | 1 BUMPER LOWER REAR | \$ | <i>nd/d</i> 411.90 ✓ |
| 3 | 1 BUMPER BRACKET CTR REAR | \$ | <i>Sn</i> 98.10 X |
| 4 | 1 BUMPER BRACKET SIDE RH REAR | \$ | <i>D/I</i> 82.10 ✓ |
| 5 | 1 BUMPER RETAINER RH REAR | \$ | <i>CM</i> 59.80 ✓ |
| 6 | 1 BUMPER REFLECTOR RH | \$ | <i>CM</i> 16.60 ✓ |
| 7 | 1 BUMPER BRACKET SIDE LH REAR | \$ | <i>R</i> 80.80 X |
| 8 | 1 BUMPER RETAINER LH REAR | \$ | <i>Sn</i> 54.20 X |
| 9 | 1 BUMPER REFLECTOR LH | \$ | <i>Sn</i> 16.60 X |
| 10 | 1 BUMPER BEAM REAR | \$ | <i>By</i> 547.80 ✓ |
| 11 | 1 BUMPER BEAM BRACKET LH REAR | \$ | <i>R</i> 114.50 X |
| 12 | 1 BUMPER BEAM BRACKET RH REAR | \$ | <i>R</i> 100.90 X |
| 13 | 1 BUMPER BLOCK RH REAR | \$ | <i>Sn</i> 76.50 X |
| 14 | 1 BOOT REAR | \$ | <i>By</i> 1,677.20 ✓ |
| 15 | 1 BOOT FINISHER | \$ | <i>Sn</i> 344.70 X |
| 16 | 1 BOOT WHEATERSTRIP | \$ | <i>nd/d</i> 178.20 <i>502sn 89.105n</i> |
| 17 | 1 BOOT REFLECTOR LAMP LH | \$ | <i>Sn</i> 277.70 X |
| 18 | 1 BOOT REFLECTOR LAMP RH | \$ | <i>nd</i> 277.70 ✓ |
| 19 | 1 BOOT BADGE 'RENAULT' | \$ | <i>nd</i> 82.40 ✓ |
| 20 | 1 BOOT BADGE | \$ | <i>nd</i> 95.80 ✓ |
| 21 | 1 BOOT STRUT LH | \$ | <i>Sn</i> 145.10 |
| 22 | 1 BOOT STRUT RH | \$ | <i>Sn</i> 145.10 |
| 23 | 1 BOOT HINGE LH | \$ | <i>R</i> 254.20 |
| 24 | 1 BOOT HINGE RH | \$ | <i>R</i> 253.80 |
| 25 | 1 BOOT INNER TRIM BOARD | \$ | <i>Sn</i> 611.00 |
| 26 | 1 BOOT SWITCH | \$ | <i>Sn</i> 113.00 |

Trans-cab Auto Services Pte Ltd

AAD1910-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

| | | | | | | |
|----|---|---|----|--------|----------|---|
| 27 | 1 | BOOT LOCK | \$ | M | 246.60 | } |
| 28 | 1 | BOOT LOCK CATCH | \$ | M | 41.70 | |
| 29 | 2 | LICENCE PLATE LAMP | \$ | PL | 26.30 | |
| 30 | 2 | BOOT RUBBER PLUG | \$ | PL | 139.30 | |
| 31 | 2 | BOOT BUFFER | \$ | PL | 26.80 | |
| 32 | 1 | BOOT LOCK LINKAGE HOLDER | \$ | PL | 99.50 | |
| 33 | 1 | BOOT LOCK LINKAGE | \$ | PL | 20.60 | |
| 34 | 1 | CHASSIS PANEL REAR RH | \$ | M | 2,192.40 | |
| 35 | 1 | FENDER WHEEL HOUSE PANEL REAR RH | \$ | M | 1,933.20 | |
| 36 | 1 | FENDER INNER BOARD RH | \$ | PL | 561.40 | |
| 37 | 1 | FENDER PANEL INNER REAR RH | \$ | M | 952.50 | |
| 38 | 1 | FENDER PANEL INNER TRIM REAR RH | \$ | return | 671.45 | ✓ |
| 39 | 1 | FENDER PANEL REAR RH | \$ | PL | 1,933.20 | ✓ |
| 40 | 1 | WHEELARCH REAR RH | \$ | PL | 275.40 | X |
| 41 | 1 | SPARE TYRE BOARD | \$ | PL | 680.90 | X |
| 42 | 1 | TAILLAMP RH | \$ | CM | 313.10 | ✓ |
| 43 | 1 | TAILLAMP PANEL RH | \$ | PL | 401.40 | ✓ |
| 44 | 1 | TAILLAMP LH | \$ | PL | 401.40 | X |
| 45 | 1 | TAILLAMP PANEL LH | \$ | M | 401.40 | X |
| 46 | 1 | AIR VENT RH | \$ | PL | 59.40 | X |
| 47 | 1 | OUTER PANEL REAR (End Panel) | \$ | PL | 745.80 | ✓ |
| 48 | 1 | OUTER PANEL REAR (End Panel) TRIM | \$ | PL | 404.56 | } |
| 49 | 1 | SPARE WHEEL PANEL (Luggage Floor Panel) | \$ | M | 1,229.40 | |
| 50 | 1 | SPARE WHEEL PANEL TRIM | \$ | PL | 612.21 | |
| 51 | 1 | EXHAUST REAR | \$ | M | 5,263.60 | |
| 52 | 1 | EXHAUST CAP REAR | \$ | M | 125.40 | |
| 53 | 1 | EXHAUST PIPE CLAMP | \$ | PL | 68.80 | |
| 54 | 1 | EXHAUST HEAT SHIELD REAR | \$ | PL | 134.60 | |
| 55 | 1 | EXHAUST HEAT SHIELD TUNNEL | \$ | PL | 131.00 | |
| 56 | 1 | BUMPER HARNESS REAR | \$ | PL | 301.10 | |
| 57 | 1 | KNUCKLE ARM REAR RH | \$ | PL | 472.10 | |
| 58 | 1 | BRAKE DISC REAR | \$ | PL | 266.50 | |
| 59 | 1 | ABS SENSOR REAR RH | \$ | PL | 190.50 | |
| 60 | 1 | WHEEL HUB NUT | \$ | PL | 41.80 | |
| 61 | 1 | WHEEL HUB CAP | \$ | PL | 30.50 | |
| 62 | 1 | KNUCKLE HUB+ BEARING RH | \$ | PL | 272.30 | |

Trans-cab Auto Services Pte Ltd

AAD1910-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

| | | | | | | |
|--------------|---|-------------------------------|-----------|------------------|---|--|
| 63 | 1 | REAR AXLE | \$ | RM 3,469.00 | } | |
| 64 | 1 | AXLE ARM RH | \$ | RM 69.50 | | |
| 65 | 2 | REAR AXLE SPACER | \$ | RM 49.00 | | |
| 66 | 1 | REAR AXLE ARM ROD | \$ | RM 69.50 | | |
| 67 | 1 | LOWER ARM REAR RH | \$ | RM 543.50 | | |
| 68 | 1 | AXLE SPRING ARM RH | \$ | RM 220.60 | | |
| 69 | 1 | AXLE SPRING ARM BUSH UPPER | \$ | RM 42.50 | | |
| 70 | 1 | AXLE SPRING ARM BUSH LOWER | \$ | RM 30.80 | | |
| 71 | 1 | ABSORBER REAR | \$ | RM 217.30 | | |
| 72 | 1 | ABSORBER DUST COVER REAR | \$ | RM 47.10 | | |
| 73 | 1 | ABSORBER MOUNTING REAR | \$ | RM 49.40 | | |
| 74 | 1 | STABILIZER BAR REAR | \$ | RM 427.90 | | |
| 75 | 1 | STABILIZER LINK REAR | \$ | RM 55.20 | | |
| 76 | 1 | BRAKE CALIPER REAR RH | \$ | RM 659.10 | | |
| 77 | 1 | BRAKE PAD REAR | \$ | RM 145.60 | | |
| 78 | 1 | BRAKE CALIPER BRACKET REAR RH | \$ | RM 384.00 | | |
| 79 | 1 | BRAKE HOSE REAR RH | \$ | RM 79.50 | | |
| 80 | 1 | SUBFRAME ARM REAR | \$ | RM 198.33 | | |
| 81 | 1 | RODE- LONG REAR | \$ | RM 120.16 | | |
| 82 | 1 | DOOR PANEL REAR RH | \$ | RM 758.70 | | |
| TOTAL | | | \$ | 35,982.21 | | |
| 10% | | | \$ | 3,598.22 | | |
| | | | \$ | 32,383.99 | | |

Special Nett

| | | | | | |
|----|------|--------------------------------|----|-----------|-------|
| 1 | 1SET | PARKING AID | \$ | RM 700.00 | 40000 |
| 2 | 1SET | REAR BUMPER CLIP | \$ | RM 66.00 | — |
| 3 | 1SET | BUMPER BRACKET CTR CLIP | \$ | RM 33.00 | — |
| 4 | 1SET | BUMPER BRACKET SIDE CLIP RH RR | \$ | RM 10.00 | X |
| 5 | 1SET | BUMPER RETAINER RH CLIP RR | \$ | RM 20.00 | X |
| 6 | 1SET | BUMPER BRACKET SIDE CLIP LH RR | \$ | RM 10.00 | X |
| 7 | 1SET | BUMPER RETAINER CLIP LH RR | \$ | RM 20.00 | X |
| 8 | 1SET | BUMPER LOWER REAR RIVET | \$ | RM 22.00 | X |
| 9 | 1SET | BUMPER LOWER REAR CLIP | \$ | RM 66.00 | ✓ |
| 10 | 1 | EXHAUST MOUNTING REAR | \$ | RM 16.00 | X |
| 11 | 1 | EXHAUST BRACKET REAR | \$ | RM 24.80 | X |

Trans-cab Auto Services Pte Ltd

AAD1910-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

| | | | | | | |
|----|------|------------------------------------|----|----|--------|------|
| 12 | 1SET | BOOT FINISHER CLIP | \$ | na | 24.20 | X |
| 13 | 1 | BOOT STICKER "Trans-cab" | \$ | na | 30.00 | — |
| 14 | 1 | BOOT STICKER "6555-3333" | \$ | na | 30.00 | — |
| 15 | 1 | BOOT INNER TRIM CLIP | \$ | na | 45.00 | X |
| 16 | 1 | SPARE TYRE RIM (ROUE 7J 16H 2547) | \$ | SL | 385.00 | X |
| 17 | 1 | SPARE TYRE | \$ | SL | 330.00 | X |
| 18 | 1 | TAILLAMP CLIP RH | \$ | na | 5.00 | ✓ |
| 19 | 2 | REAR WINDSCREEN SEALANT | \$ | na | 80.00 | fojn |
| 20 | 1 | WINDSCREEN MOULDING | \$ | na | 100.00 | X |
| 21 | 1 | REAR WINDSCREEN INNER SPONGE SEAL | \$ | na | 100.00 | 30jn |
| 22 | 1 | TAILLAMP CLIP LH | \$ | na | 5.00 | X |
| 23 | 1 | Rear Bumper Protector | \$ | na | 100.00 | X |
| 24 | 2 | AXLE BOLT | \$ | na | 26.20 | } X |
| 25 | 2 | AXLE NUT | \$ | na | 60.80 | |
| 26 | 2 | AXLE SPRING ARM BOLT | \$ | na | 30.80 | |
| 27 | 2 | AXLE SPRING ARM BOLT | \$ | na | 25.80 | |
| 28 | 4 | AXLE SPRING ARM NUT | \$ | na | 9.70 | |
| 29 | 4 | LOWER ARM BOLT | \$ | na | 25.80 | |
| 30 | 4 | LOWER ARM NUT | \$ | na | 9.70 | |
| 31 | 1 | LOWER ARM BALANCER REAR RH | \$ | na | 20.50 | |
| 32 | 2 | ABSORBER BOLT REAR | \$ | na | 29.90 | |
| 33 | 1 | BRAKE CALIPER BRACKET BOLT REAR RH | \$ | na | 29.60 | |
| 34 | 1SET | Rear licence plate with holder | \$ | SL | 80.00 | |
| 35 | 1 | REAR RIGHT TYRE | \$ | SL | 300.00 | |
| 36 | 1 | REAR RIGHT TYRE RIM | \$ | SL | 380.00 | |
| 37 | 1SET | FENDER WHEELARCH REAR RH CLIP | \$ | na | 35.00 | |
| 38 | 1 | FENDER INNER TRIM CLIP RH | \$ | na | 28.00 | |
| 39 | 1 | REAR DOOR STICKER "6555-3333" | \$ | na | 80.00 | |

TOTAL \$ 3,393.80

TOTAL PARTS \$ 35,777.79

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 9,000.00 *ppol*

Trans-cab Auto Services Pte Ltd

AAD1910-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

| | | | |
|---|----|----------|--------|
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 9,000.00 | 1200/ |
| To supply and re-do rear luggage floor panel insulation padding. | \$ | ~ 380.00 | X |
| To transfer of bootlid fittings, attachments and perform water seepage test. | \$ | 170.00 | 60/ |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. | \$ | 170.00 | 60/ |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | 170.00 | } 100/ |
| To transfer of rear luggage floor panel fittings, attachment and perform water seepage test. | \$ | 170.00 | |
| To check steering geometry and computer wheel alignment | \$ | ~ 220.00 | X |
| To Rust-Proofing Of The Affected Areas. | \$ | 170.00 | 90/ |
| To transfer of tire, rim and on wheel balancing. | \$ | ~ 170.00 | X |
| To transfer of rear tender fittings, attachment and perform water seepage test. | \$ | ~ 170.00 | X |
| To transfer of rear windscreen glass to facilitate bodywork repair. | \$ | 170.00 | 120/ |
| To repair and realign rear exhaust pipe. | \$ | ~ 170.00 | X |
| To reinstall rear bumper parking sensor. | \$ | 170.00 | 60/ |

Trans-cab Auto Services Pte Ltd

AAD1910-239

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 743M

| | | |
|---|-----------|------------------|
| To transfer of rear bumper fittings, attachment and perform water seepage test. | \$ | ~ 380.00 X |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | ~ 380.00 X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 201 |
| To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing. | \$ | ~ 380.00 X |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$ | ~ 380.00 X |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. | \$ | ~ 380.00 X |
| To dismantle and refit rear undercarriage parts, final checking and testing. | \$ | ~ 380.00 X |
| To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing. | \$ | ~ 380.00 X |
| To transfer of door fittings, attachment and perform water seepage test. | \$ | ~ 170.00 X |
| To check ABS and brake efficiency, final checking and testing. | \$ | ~ 380.00 X |
| TOTAL | \$ | 23,680.00 |
| Over All Total | \$ | 59,457.79 |

(LUMP SUM) Repair Days**30 DAYS**

7 days

LKK Auto Consultants hereby notify the Repairer of the following:

- To restore to condition before damage
- To display damaged parts during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary limit(s) must be ascertained and is subject to final approval from Insurance Company

Authorised by: [Signature]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|---|--------------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 878K |
| Vehicle Details | |
| Vehicle No.: | SHF743M |
| Vehicle to be Exported: | Yes |
| Intended Deregistration Date: | 31 Oct 2019 |
| Vehicle Make: | RENAULT |
| Vehicle Model: | LATITUDE 2.0L DCI AUTO D/AB 4DR |
| Primary Colour: | Red |
| Manufacturing Year: | 2015 |
| Engine No.: | M9R8839C003034 |
| Chassis No.: | VF1ABL15AUC282731 |
| Maximum Power Output: | 127.0 kW (170 bhp) |
| Open Market Value: | \$19,998.00 |
| Original Registration Date: | 30 Jun 2016 |
| First Registration Date: | 30 Jun 2016 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$19,998.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Jun 2024 |
| PARF Rebate Amount: | \$14,998.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 29 Jun 2024 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$37,164.00 |
| COE Rebate Amount: | \$21,666.00 |
| Total Rebate Amount: | \$36,664.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 31 Oct 2019

OK

Print Received Message

This mail is associated with :

***SHF743M (MCT19100732)**
[SHC2303C]

TP

TRANS-CAB SERVICES PTE LTD
Oct 30 2019 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 21/02/2020 18:43 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9994.04) - SHF743M - Claim Handler: Sundari Nagarajan

Approved:9994.04:Please request TP WS to raise Tax Invoice for Cost of repairs in III's name

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|--|---------------|--|--|--|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 14 Feb 2020 12:57 Edit Reg | | 01 Nov 2019 00:00 Edit Adj Rpt | \$58,300.00 Edit Estimates | \$58,300.00 View Rpt | | Pending for Survey Report Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|--|------------------------|--|----------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | | | | | | | | | |
| Insured: | COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R | | | | | | | | |
| Main Claimant: | TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K | | | | | | | | |
| Vehicle Reg. No.: | SHF743M | Date of Loss: | 30/10/2019 23:00 - :59 [40 Months From LTA Reg Date (Man Yr)] | | | | | | |
| Claim Type: | TP / MCT19100732 | Policy/Cover Note No.: | MCOM0015 (TP, Fire & Theft) | | | | | | |
| Vehicle Reg. No. (Insured): | SHC2303C | Policy No. (Claimant): | VFX/P1680520 | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2 , Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666 | | | | | | | | |
| Handling Insurer: | India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071] | | | | | | | | |
| Claimant's Insurer: | AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888 | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/11/2019] | | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| <ul style="list-style-type: none"> • III_SG (21/02/2020): Alert - Adj Mandate Approved (\$9994.04) - SHF743M - Claim Handler: Sundari Naga... • III_SG (17/12/2019): Alert - Adj Mandate Approved (\$0.00) - SHF743M - Claim Handler: Sundari Nagara... | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

Claim Documents

*SHF743M (MCT19100732)
[SHC2303C]
TP
TRANS-CAB SERVICES PTE LTD
Oct 30 2019 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

| Upload Documents Upload Photos Compose New Letter | | | View View in Browser | |
|---|-----------------|--|---|-------------------------------------|
| Video | | | 1 per page <input type="checkbox"/> | |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 02/03/20 16:10 | Video - Accident-IV | Load MP4 | <input type="checkbox"/> |
| Photos/Images | | | 3 per page <input type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 2 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 3 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 4 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 5 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 6 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 7 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 8 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 9 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 10 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 11 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 12 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 13 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 14 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 15 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 16 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 17 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 18 | 20/02/20 10:52 | General View | Load JPG | <input checked="" type="checkbox"/> |
| 19 | 20/02/20 10:52 | Odometer Reading | Load JPG | <input checked="" type="checkbox"/> |
| 20 | 20/02/20 10:52 | Chassis Number | Load JPG | <input checked="" type="checkbox"/> |
| Documentation | | | 1 per page <input type="checkbox"/> | |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 04/11/19 16:50 | TP ESTIMATE- MARKED | Load PDF | <input type="checkbox"/> |
| 2 | 04/11/19 16:50 | TP GIA REPORT | Load PDF | <input type="checkbox"/> |
| 3 | 20/02/20 10:51 | LOD AND OTHER DOCUMENTS | Load PDF | <input type="checkbox"/> |
| 4 | 06/03/20 10:39 | WORKSHOP INVOICE | Load PDF | <input type="checkbox"/> |
| 5 | 06/03/20 10:39 | AUTHORISATION TO ACT FORM | Load PDF | <input type="checkbox"/> |
| 6 | 06/03/20 10:39 | DISCHARGE VOUCHER | Load PDF | <input type="checkbox"/> |
| 7 | 06/03/20 10:39 | RENTAL RECEIPT | Load PDF | <input type="checkbox"/> |
| 8 | 06/03/20 10:39 | RENTAL MILEAGE | Load PDF | <input type="checkbox"/> |
| 9 | 06/03/20 10:39 | LOD | Load PDF | <input type="checkbox"/> |
| No | Finalized On | India International Insurance Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 11/12/19 16:52 | Singapore Accident Statement IV SHC2303C | Load PDF | <input type="checkbox"/> |

Documents Checklist

| | |
|--|--|
| DOCUMENTS CHECKLIST | Reset Save Print |
| There are no document checklists configured. | |

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19019452/KGS3Q2

Date: 06/03/2020

REFERENCE

| | | |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant | | |
| Vehicle No : SHF743M | Insured Vehicle No : | SHC2303C |
| Date of Loss: 30/10/2019 | Nature of Claim: TP | Claim No: MCT19100732 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SHF743M | Engine No: | M9R8839C003034 |
| Make & Model: | RENAULT LATITUDE, 2.0 D dCi (A) | Chassis No: | VF1ABL15AUC282731 |
| Reg. Date: | 30/06/2016 (Man. Year: 2015) | Odometer: | 525520 km |
| Colour: | Metallic White/Red | | |
| Engine Capacity: | 1995 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 215/60 R16 | Rear Tyre Size: | 215/60 R16 |
| Front Left Side: | Sailun 9 mm | Rear Left Side: | Sailun 9 mm |
| Front Right Side: | Sailun 9 mm | Rear Right Side: | Sailun 9 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|------------------|------------------|--------------|
| Parts | 35,777.79 | 7,879.25 | 27,898.54 | 77.98 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 23,680.00 | 2,590.00 | 21,090.00 | 89.06 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 59,457.79 | 10,469.25 | 48,988.54 | 82.39 |
| Approved Total (Overridden) (S\$) | | 8,300.00 | | |
| (S\$) | 59,457.79 | 8,300.00 | 51,157.79 | 86.04 |
| + GST 7.00/7.00% (S\$) | 4,162.05 | 581.00 | 3,581.05 | 86.04 |
| Nett Amount (S\$) | 63,619.84 | 8,881.00 | 54,738.84 | 86.04 |
| + Loss of Use (8.0 x S\$40.00/day) (S\$) | | 320.00 | | |
| + Car Rental (8.0 x S\$99.13/day) (S\$) | | 793.04 | | |
| Nett Liability (S\$) | | 9,994.04 | | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 01/11/2019 | |
| Date Inspected: | 01/11/2019 Inspected At: | Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111 |
| Estimated Period of Repair: | 7.0 days | |

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | |
|---|--|
| Reference | |
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 14 Feb 2020) |
| Parts: 143 | RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SHF743M) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|--------------------|-------------|--------------|
| 1 | 1 | | *BUMPER COVER REAR | Bent | 561.70 FL | *561.70 FL |
| 2 | 1 | | *BUMPER LOWER REAR | Dented / Distorted | 411.90 FL | *411.90 FL |
| 3 | 1 | | *BUMPER BRACKET CTR REAR | Serviceable | 98.10 FL | *- FL |
| 4 | 1 | | *BUMPER BRACKET SIDE RH REAR | Distorted | 82.10 FL | *82.10 FL |
| 5 | 1 | | *BUMPER RETAINER RH REAR | Cracked | 59.80 FL | *59.80 FL |
| 6 | 1 | | *BUMPER REFLECTOR RH | Cracked | 16.60 FL | *16.60 FL |
| 7 | 1 | | *BUMPER BRACKET SIDE LH REAR | Repair | 80.80 FL | *- FL |
| 8 | 1 | | *BUMPER RETAINER LH REAR | Serviceable | 54.20 FL | *- FL |
| 9 | 1 | | *BUMPER REFLECTOR LH | Serviceable | 16.60 FL | *- FL |
| 10 | 1 | | *BUMPER BEAM REAR | Bent | 547.80 FL | *547.80 FL |
| 11 | 1 | | *BUMPER BEAM BRACKET LH REAR | Repair | 114.50 FL | *- FL |
| 12 | 1 | | *BUMPER BEAM BRACKET RH REAR | Repair | 100.90 FL | *- FL |
| 13 | 1 | | *BUMPER BLOCK RH REAR | Serviceable | 76.50 FL | *- FL |
| 14 | 1 | | *BOOT REAR | Bent | 1,677.20 FL | *1,677.20 FL |
| 15 | 1 | | *BOOT FINISHER | Serviceable | 344.70 FL | *- FL |
| 16 | 1 | | *BOOT WEATHERSTRIP (50%) | Distorted / Dented | 160.38 FS | *89.10 FS |
| 17 | 1 | | *BOOT REFLECTOR LAMP LH | Serviceable | 277.70 FL | *- FL |
| 18 | 1 | | *BOOT REFLECTOR LAMP RH | Dented | 277.70 FL | *277.70 FL |
| 19 | 1 | | *BOOT BADGE RENAULT | Necessary | 82.40 FL | *82.40 FL |
| 20 | 1 | | *BOOT BADGE | Necessary | 95.80 FL | *95.80 FL |
| 21 | 1 | | *BOOT STRUT LH | Serviceable | 145.10 FL | *- FL |
| 22 | 1 | | *BOOT STRUT RH | Serviceable | 145.10 FL | *- FL |
| 23 | 1 | | *BOOT HINGE LH | Repair | 254.20 FL | *- FL |
| 24 | 1 | | *BOOT HINGE RH | Repair | 253.80 FL | *- FL |
| 25 | 1 | | *BOOT INNER TRIM BOARD | Serviceable | 611.00 FL | *- FL |
| 26 | 1 | | *BOOT SWITCH | Serviceable | 113.00 FL | *- FL |
| 27 | 1 | | *BOOT LOCK | Repair | 246.60 FL | *- FL |
| 28 | 1 | | *BOOT LOCK CATCH | Repair | 41.70 FL | *- FL |
| 29 | 2 | | *LICENCE PLATE LAMP | Serviceable | 26.30 FL | *- FL |
| 30 | 2 | | *BOOT RUBBER PLUG | Serviceable | 139.30 FL | *- FL |
| 31 | 2 | | *BOOT BUFFER | Serviceable | 26.80 FL | *- FL |
| 32 | 1 | | *BOOT LOCK LINKAGE HOLDER | Serviceable | 99.50 FL | *- FL |
| 33 | 1 | | *BOOT LOCK LINKAGE | Serviceable | 20.60 FL | *- FL |
| 34 | 1 | | *CHASSIS PANEL REAR RH | Repair | 2,192.40 FL | *- FL |
| 35 | 1 | | *FENDER WHEEL HOUSE PANEL REAR RH | Repair | 1,933.20 FL | *- FL |
| 36 | 1 | | *FENDER INNER BOARD RH | Serviceable | 561.40 FL | *- FL |
| 37 | 1 | | *FENDER PANEL INNER REAR RH | Repair | 952.50 FL | *- FL |
| 38 | 1 | | *FENDER PANEL INNER TRIM REAR RH | Deformed | 671.45 FL | *671.45 FL |
| 39 | 1 | | *FENDER PANEL REAR RH | Buckled | 1,933.20 FL | *1,933.20 FL |
| 40 | 1 | | *WHEELARCH REAR RH | Serviceable | 275.40 FL | *- FL |
| 41 | 1 | | *SPARE TYRE BOARD | Serviceable | 680.90 FL | *- FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|------------|
| 42 | 1 | | *TAILLAMP RH | Cracked | 313.10 FL | *313.10 FL |
| 43 | 1 | | *TAILLAMP PANEL RH | Bent | 401.40 FL | *401.40 FL |
| 44 | 1 | | *TAILLAMP LH | Serviceable | 401.40 FL | *-FL |
| 45 | 1 | | *TAILLAMP PANEL LH | Repair | 401.40 FL | *-FL |
| 46 | 1 | | *AIR VENT RH | Serviceable | 59.40 FL | *-FL |
| 47 | 1 | | *OUTER PANEL REAR (END PANEL) | Bent | 745.80 FL | *745.80 FL |
| 48 | 1 | | *OUTER PANEL REAR (END PANEL)TRIM | Serviceable | 404.56 FL | *-FL |
| 49 | 1 | | *SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) | Repair | 1,229.40 FL | *-FL |
| 50 | 1 | | *SPARE WHEEL PANEL TRIM | Serviceable | 612.21 FL | *-FL |
| 51 | 1 | | *EXHAUST REAR | Repair | 5,263.60 FL | *-FL |
| 52 | 1 | | *EXHAUST CAP REAR | Repair | 125.40 FL | *-FL |
| 53 | 1 | | *EXHAUST PIPE CLAMP | Serviceable | 68.80 FL | *-FL |
| 54 | 1 | | *EXHAUST HEAT SHIELD REAR | Serviceable | 134.60 FL | *-FL |
| 55 | 1 | | *EXHAUST HEAT SHIELD TUNNEL | Serviceable | 131.00 FL | *-FL |
| 56 | 1 | | *BUMPER CHASSIS REAR | Serviceable | 301.10 FL | *-FL |
| 57 | 1 | | *KNUCKLE ARM REAR RH | Serviceable | 472.10 FL | *-FL |
| 58 | 1 | | *BRAKE DISC REAR | Serviceable | 266.50 FL | *-FL |
| 59 | 1 | | *ABS SENSOR REAR RH | Serviceable | 190.50 FL | *-FL |
| 60 | 1 | | *WHEEL HUB NUT | Serviceable | 41.80 FL | *-FL |
| 61 | 1 | | *WHEEL HUB CAP | Serviceable | 30.50 FL | *-FL |
| 62 | 1 | | *KNUCKLE HUB+BEARING RH | Serviceable | 272.30 FL | *-FL |
| 63 | 1 | | *REAR AXLE | Serviceable | 3,469.00 FL | *-FL |
| 64 | 1 | | *AXLE ARM RH | Serviceable | 69.50 FL | *-FL |
| 65 | 2 | | *REAR AXLE SPACER | Serviceable | 49.00 FL | *-FL |
| 66 | 1 | | *REAR AXLE ARM ROD | Serviceable | 69.50 FL | *-FL |
| 67 | 1 | | *LOWER ARM REAR RH | Serviceable | 543.50 FL | *-FL |
| 68 | 1 | | *AXLE SPRING ARM RH | Serviceable | 220.60 FL | *-FL |
| 69 | 1 | | *AXLE SPRING ARM BUSH UPPER | Serviceable | 42.50 FL | *-FL |
| 70 | 1 | | *AXLE SPRING ARM BUSH LOWER | Serviceable | 30.80 FL | *-FL |
| 71 | 1 | | *ABSORBER REAR | Serviceable | 217.30 FL | *-FL |
| 72 | 1 | | *ABSORBER DUST COVER REAR | Serviceable | 47.10 FL | *-FL |
| 73 | 1 | | *ABSORBER MOUNTING REAR | Serviceable | 49.40 FL | *-FL |
| 74 | 1 | | *STABILIZER BAR REAR | Serviceable | 427.90 FL | *-FL |
| 75 | 1 | | *STABILIZER LINK REAR | Serviceable | 55.20 FL | *-FL |
| 76 | 1 | | *BRAKE CALIPER REAR RH | Serviceable | 659.10 FL | *-FL |
| 77 | 1 | | *BRAKE PAD REAR | Serviceable | 145.60 FL | *-FL |
| 78 | 1 | | *BRAKE CALIPER BRACKER REAR RH | Serviceable | 384.00 FL | *-FL |
| 79 | 1 | | *BRAKE HOSE REAR RH | Serviceable | 79.50 FL | *-FL |
| 80 | 1 | | *SUBFRAME ARM REAR | Serviceable | 198.33 FL | *-FL |
| 81 | 1 | | *RODE-LONG REAR | Serviceable | 120.16 FL | *-FL |
| 82 | 1 | | *DOOR PANEL REAR RH | Serviceable | 758.70 FL | *-FL |
| 83 | 1 | | *SET PARKING AID | Shorted | 700.00 FS | *400.00 FS |
| 84 | 1 | | *SET REAR BUMPER CLIP | Necessary | 66.00 FS | *66.00 FS |
| 85 | 1 | | *SET BUMPER BRACKET CTR CLIP | Necessary | 33.00 FS | *33.00 FS |
| 86 | 1 | | *SET BUMPER BRACKET SIDE CLIP RH RR | Not Necessary | 10.00 FS | *-FS |
| 87 | 1 | | *SET BUMPER RETAINER RH CLIP RR | Not Necessary | 20.00 FS | *-FS |
| 88 | 1 | | *SET BUMPER BRACKET SIDE CLIP LH RR | Not Necessary | 10.00 FS | *-FS |
| 89 | 1 | | *SET BUMPER RETAINER CLIP LH RR | Not Necessary | 20.00 FS | *-FS |
| 90 | 1 | | *SET BUMPER LOWER REAR RIVET | Not Necessary | 22.00 FS | *-FS |
| 91 | 1 | | *SET BUMPER LOWER REAR CLIP | Necessary | 66.00 FS | *66.00 FS |
| 92 | 1 | | *EXHAUST MOUNTING REAR | Serviceable | 16.00 FS | *-FS |
| 93 | 1 | | *EXHAUST BRACKET REAR | Serviceable | 24.80 FS | *-FS |
| 94 | 1 | | *SET BOOT FINISHER CLIP | Not Necessary | 24.20 FS | *-FS |
| 95 | 1 | | *BOOT STICKER TRANS-CAB | Necessary | 30.00 FS | *30.00 FS |
| 96 | 1 | | *BOOT STICKER 6555-3333 | Necessary | 30.00 FS | *30.00 FS |
| 97 | 1 | | *BOOT INNER TRIM CLIP | Not Necessary | 45.00 FS | *-FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|---------------|------------|-----------|
| 98 | 1 | | *SPARE TYRE RIM (ROUE 7J 16H 2547) | Serviceable | 385.00 FS | *- FS |
| 99 | 1 | | *SPARE TYRE | Serviceable | 330.00 FS | *- FS |
| 100 | 1 | | *TAILLAMP CLIP RH | Necessary | 5.00 FS | *5.00 FS |
| 101 | 2 | | *REAR WINDSCREEN SEALANT | Necessary | 80.00 FS | *40.00 FS |
| 102 | 1 | | *WINDSCREEN MOULDING | Not Necessary | 100.00 FS | *- FS |
| 103 | 1 | | *REAR WINDSCREEN INNER SPONGE SEAL | Necessary | 100.00 FS | *30.00 FS |
| 104 | 1 | | *TAILLAMP CLIP LH | Not Necessary | 5.00 FS | *- FS |
| 105 | 1 | | *REAR BUMPER PROTECTOR | Not Necessary | 100.00 FS | *- FS |
| 106 | 2 | | *AXLE BOLT | Not Necessary | 26.20 FS | *- FS |
| 107 | 2 | | *AXLE NUT | Not Necessary | 60.80 FS | *- FS |
| 108 | 2 | | *AXLE SPRING ARM BOLT | Not Necessary | 30.80 FS | *- FS |
| 109 | 2 | | *AXLE SPRING ARM BOLT | Not Necessary | 25.80 FS | *- FS |
| 110 | 4 | | *AXLE SPRING ARM NUT | Not Necessary | 9.70 FS | *- FS |
| 111 | 4 | | *LOWER ARM BOLT | Not Necessary | 25.80 FS | *- FS |
| 112 | 4 | | *LOWER ARM NUT | Not Necessary | 9.70 FS | *- FS |
| 113 | 1 | | *LOWER ARM BALANCER REAR RH | Not Necessary | 20.50 FS | *- FS |
| 114 | 2 | | *ABSORBER BOLT REAR | Not Necessary | 29.90 FS | *- FS |
| 115 | 1 | | *BRAKE CALIPER BRACKET BOLT REAR RH | Not Necessary | 29.60 FS | *- FS |
| 116 | 1 | | *SET REAR LICENCE PLATE WITH HOLDER | Serviceable | 80.00 FS | *- FS |
| 117 | 1 | | *REAR RIGHT TYRE | Serviceable | 300.00 FS | *- FS |
| 118 | 1 | | *REAR RIGHT TYRE RIM | Serviceable | 380.00 FS | *- FS |
| 119 | 1 | | *SET FENDER WHEELARCH REAR RH CLIP | Not Necessary | 35.00 FS | *- FS |
| 120 | 1 | | *FENDER INNER TRIM CLIP RH | Not Necessary | 28.00 FS | *- FS |
| 121 | 1 | | *REAR DOOR STICKER 6555-3333 | Not Necessary | 80.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc

| | | |
|---|------------------|-----------------|
| Sub Total (S\$) | 39,358.19 | 8,667.05 |
| - List Item Discount on L Items 10.00/10.00% (S\$) | 3,580.40 | 787.80 |
| Total Parts (S\$) | 35,777.79 | 7,879.25 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION | New | 9,000.00 | 880.00 |
| 2 | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME | New | 9,000.00 | 1,200.00 |
| 3 | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING | New | 380.00 | 0.00 |
| 4 | TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 60.00 |
| 5 | TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE | New | 170.00 | 60.00 |
| 6 | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST) | New | 170.00 | 100.00 |
| 7 | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST) | New | 170.00 | 0.00 |
| 8 | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT | New | 220.00 | 0.00 |
| 9 | TO RUST-PROOFING OF THE AFFECTED AREAS | New | 170.00 | 90.00 |
| 10 | TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING | New | 170.00 | 0.00 |
| 11 | TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 12 | TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR | New | 170.00 | 120.00 |
| 13 | TO REPAIR AND REALIGN REAR EXHAUST PIPE | New | 170.00 | 0.00 |
| 14 | TO REINSTALL REAR BUMPER PARKING SENSOR | New | 170.00 | 60.00 |
| 15 | TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST | New | 380.00 | 0.00 |
| 16 | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR | New | 380.00 | 0.00 |
| 17 | TO CHECK ELECTRICAL LIGHTING CONCERNED | New | 170.00 | 20.00 |
| 18 | TO DROP DIESEL TANK ,PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING | New | 380.00 | 0.00 |
| 19 | LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR | New | 380.00 | 0.00 |
| 20 | TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK | New | 380.00 | 0.00 |
| 21 | TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING | New | 380.00 | 0.00 |
| 22 | TO DISMANTLE AND REFIT REAR AXLE ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING | New | 380.00 | 0.00 |
| 23 | TO TRANSFER OF DOOR FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST | New | 170.00 | 0.00 |
| 24 | TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING | New | 380.00 | 0.00 |

Report was unsubmitted during this print-out.

| No | Particulars | Lab.Type | Repairer's | Amount |
|----|-------------|-------------------------|------------|----------|
| | | Gross Labour Cost (S\$) | 23,680.00 | 2,590.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >