





PRE-REPAIR INSPECTION REPORT				
MS FIRST CAPITAL INSURANCE LTD		Ref: CS3/FCI19019458/Hcf3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 03-12-2019		
Code: FCI2				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHB 4079S	Veh. Inspected	FBD 993P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006668MFSH	Excess (\$)	0.00	
Assign From	JASON TEA CHEE KIAT	Assign Date	04/11/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA T135	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	5YP009230	Colour	BLACK	
Odometer	184170 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	NORTON	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	NORTON	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.			
5. General Information				
Accident Date	16/10/2019	Inspect Date / Time	04/11/2019 (05:17 PM)	
Survey held at	25 KAKI BUKIT ROAD 4 #01-68 SYNERGY			
Repairer	MY CAR CONSULTANT PTE LTD			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$3,500.00			

Report Ref No. CS3/FCI19019458/Hcf3e2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.