

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Nov 2019 Edit Reg		04 Nov 2019 00:00 Edit Adj Rpt	S\$13,000.00 Edit Estimates	S\$13,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -									
Main Claimant: LIM CHIN LUM , ID: S1402544H									
Vehicle Reg. No.:	SLC323K	Date of Loss:	27/10/2019 14:00 - :59 [108 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19100646	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA2191T	Policy No. (Claimant):	GA177398						
		Excess:							
Repairer:	K Kim Hin Auto Pte Ltd () BLK 34 SIN MING DRIVE,#01-114,, 575708 Sin Ming - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/11/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (25/03/2020): Alert - Adj Mandate Approved (S\$0.00) - SLC323K - Claim Handler: Zuhaidah Bte Sa... - III_SG (22/01/2020): Alert - Adj Mandate Revoked - SLC323K - Claim Handler: Zuhaidah Bte Samsuri - III_SG (20/11/2019): Alert - Adj Mandate Maintained - SLC323K - Claim Handler: Zuhaidah Bte Samsuri									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC323K (MCT19100646)
[SHA2191T]
TP
LIM CHIN LUM
Oct 27 2019 2:00PM
[COMFORT TRANSPORTATION PTE LTD]
K Kim Hin Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/03/20 10:22	General View	 Load JPG	☒
2	25/03/20 10:22	General View	 Load JPG	☒
3	25/03/20 10:22	General View	 Load JPG	☒
4	25/03/20 10:22	General View	 Load JPG	☒
5	25/03/20 10:22	General View	 Load JPG	☒
6	25/03/20 10:22	General View	 Load JPG	☒
7	25/03/20 10:22	General View	 Load JPG	☒
8	25/03/20 10:22	General View	 Load JPG	☒
9	25/03/20 10:22	General View	 Load JPG	☒
10	25/03/20 10:22	General View	 Load JPG	☒
11	25/03/20 10:22	General View	 Load JPG	☒
12	25/03/20 10:22	General View	 Load JPG	☒
13	25/03/20 10:22	General View	 Load JPG	☒
14	25/03/20 10:22	General View	 Load JPG	☒
15	25/03/20 10:22	General View	 Load JPG	☒
16	25/03/20 10:22	General View	 Load JPG	☒
17	25/03/20 10:22	General View	 Load JPG	☒
18	25/03/20 10:22	General View	 Load JPG	☒
19	25/03/20 10:22	General View	 Load JPG	☒
20	25/03/20 10:22	General View	 Load JPG	☒
21	25/03/20 10:22	General View	 Load JPG	☒
22	25/03/20 10:22	General View	 Load JPG	☒
23	25/03/20 10:22	Odometer Reading	 Load JPG	☒
24	25/03/20 10:22	General View	 Load JPG	☒
25	25/03/20 10:22	General View	 Load JPG	☒
26	25/03/20 10:22	General View	 Load JPG	☒
27	25/03/20 10:22	General View	 Load JPG	☒
28	25/03/20 10:22	General View	 Load JPG	☒
29	25/03/20 10:22	General View	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/11/19 16:11	EMAIL FROM III DD 04112019	 Load PDF	
2	04/11/19 16:11	TP GIA REPORT	 Load PDF	
3	04/11/19 16:48	TP EST MARKED-NO PART PRICE	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/11/19 08:43	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19019460/KGA3S2**Date:** 17/04/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLC323K	Insured Vehicle No :	SHA2191T
Date of Loss:	27/10/2019	Nature of Claim:	TP
		Claim No:	MCT19100646

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC323K	Engine No:	MR20995931A
Make & Model:	NISSAN QASHQAI, 1.2 (A)	Chassis No:	SJNJBNI10U7024380
Reg. Date:	30/09/2010 (Man. Year: 2010)	Odometer:	140269 km
Colour:	Metallic Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,142.40	11,820.80	6,321.60	34.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	4,620.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,762.40	16,440.80	6,321.60	27.77
Approved Total (Overridden) (S\$)		13,000.00		
(S\$)	22,762.40	13,000.00	9,762.40	42.89
+ GST 7.00/7.00% (S\$)	1,593.37	910.00	683.37	42.89
Nett Amount (S\$)	24,355.77	13,910.00	10,445.77	42.89

INSPECTION

Date of Assignment:	04/11/2019	
Date Inspected:	01/11/2019	Inspected At: K Kim Hin Auto Pte Ltd BLK 34 SIN MING DRIVE,#01-114, Singapore 575708
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/17/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$4,586.70 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Apr 2020)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC323K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	777.10 F	*777.10 F
2	1		*N/S FRONT BUMPER SIDE RETAINER	Cracked	35.20 F	*35.20 F
3	10		*FRONT BUMPER CLIPS	Necessary	26.00 F	*26.00 F
4	1		*FRONT BUMPER & LOWER RUBBER LID	Buckled / Distorted	80.30 F	*80.30 F
5	1		*N/S FRONT BUMPER FOG COVER CHROME	Missing	130.10 F	*130.10 F
6	1		*N/S FRONT BUMPER FOG LAMP BRACKET	*Check	53.80 F	*- F
7	1		*FRONT GRILLE	*Check	422.10 F	*- F
8	6		*FRONT GRILLE CLIPS	*Check	33.00 F	*- F
9	2		*HEADLAMP ASSY (LH/RH)	Mtg Cracked	1,344.40 F	*1,344.40 F
10	2		*HEADLAMP LOWER BRACKET (LH/RH)	*Check	83.40 F	*- F
11	1		*N/S FRONT FENDER	Bent	753.50 F	*753.50 F
12	1		*N/S FRONT FENDER WHEEL ARCH GARNISH	Distorted	654.00 F	*654.00 F
13	1		*N/S FRONT FENDER INNER SHIELD	Cracked	156.10 F	*156.10 F
14	8		*N/S FRONT FENDER INNER SHIELD CLIPS	Necessary	20.80 F	*20.80 F
15	1		*N/S FRONT FENDER LAMP	*Check	60.10 F	*- F
16	1		*N/S FRONT FENDER INNER VERTICAL SPONGE	*Check	22.10 F	*- F
17	1		*N/S FRONT FENDER LOWER GARNISH	*Check	39.20 F	*- F
18	1		*FRONT WINDSCREEN GLASS MOULDING	*Check	155.00 F	*- F
19	1		*N/S DOOR FRONT A PILLAR	Repair	1,566.50 F	*- F
20	1		*N/S FRONT DOOR	Bent	1,282.80 F	*1,282.80 F
21	1		*N/S FRONT DOOR WEATHERSTRIP	Serviceable	181.60 F	*- F
22	2		*N/S FRONT DOOR HINGES (TOP / LOWER)	*Check	69.10 F	*- F
23	1		*N/S FRONT DOOR CHECKER	Serviceable	50.90 F	*- F
24	1		*N/S FRONT DOOR PROTECTOR	Necessary	382.10 F	*382.10 F
25	1		*N/S FRONT LOWER ARM	Bent	232.80 F	*232.80 F
26	1		*N/S FRONT BRAKE PIPE	*Check	55.00 F	*- F
27	1		*N/S FRONT STABILIZER BAR LINKAGE	Distorted	44.30 F	*44.30 F
28	1		*N/S FRONT SHOCK ABSORBER MOUNTING	*Check	103.10 F	*- F
29	1		*N/S FRONT SHOCK ABSORBER COIL SPRING LOWER	*Check	33.00 F	*- F
30	2		*FRONT STABILIZER BAR BUSH	*Check	35.60 F	*- F
31	1		*FRONT FENDER WINDSCREEN GLASS MOULDING SEALANT	*Check	40.00 FS	*- FS
32	1		*N/S FRONT BUMPER FOG LAMP	Cracked	327.30 FS	*327.30 FS
33	1		*N/S FRONT FENDER MUDFLAP	Buckled	123.20 FS	*123.20 FS
34	1		*AIR RESONATOR	Cracked	134.40 FS	*134.40 FS
35	1		*N/S FRONT TYRE (@ \$280.00 DISC 80%)	Punctured	280.00 FS	*224.00 FS
36	1		*N/S FRONT SPORT RIM	Bent	850.00 FS	*850.00 FS
37	1		*N/S FRONT KNUCKLE ARM	Bent	557.00 FS	*557.00 FS
38	1		*N/S FRONT KNUCKLE ARM BEARING }	Necessary	336.50 FS	*336.50 FS
39	1		*N/S FRONT BEARING HUB }		0.00 FS	*- FS
40	1		*N/S FRONT DRIVE SHAFT	Bent	1,159.80 FS	*1,159.80 FS
41	1		*N/S FRONT ROTOR DISC	*Check	205.20 FS	*- FS
42	1		*N.S FRONT ROTOR DISC BACK PLATE	*Check	196.90 FS	*- FS
43	1		*N.S FRONT BRAKE HOSE	*Check	64.80 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*N/S FRONT BRAKE SENSOR	*Check	383.10 FS	*- FS
45	1		*N/S FRONT TIE ROD END	Bent	140.20 FS	*140.20 FS
46	1		*N/S FRONT SHOCK ABSORBER	Bent	431.00 FS	*431.00 FS
47	1		*N/S FRONT SHOCK ABSORBER STOPPER (LWR)	*Check	51.00 FS	*- FS
48	1		*N/S FRONT SHOCK ABSORBER BEARING	*Check	133.30 FS	*- FS
49	1		*N/S FRONT SHOCK ABSORBER COIL SPRING	*Check	248.10 FS	*- FS
50	1		*N/S FRONT SHOCK ABSORBER STOPPER (UPP)	*Check	51.00 FS	*- FS
51	1		*FRONT STABILIZER BAR	*Check	353.60 FS	*- FS
52	1		*FRONT STEERING RACK & PINION	Bent / Jammed	1,617.90 FS	*1,617.90 FS
53	1		*ENGINE SUB FRAME	*Check	817.80 FS	*- FS
54	1		*ENGINE SUB FRAME SCREW	*Check	17.40 FS	*- FS
55	1		*TYRE PRESSURE SENSOR	*Check	250.00 FS	*- FS
56	1		*ENGINE MOUNTING - LH	*Check	151.10 FS	*- FS
57	1		*ENGINE MOUNTING - RH	*Check	243.70 FS	*- FS
58	1		*ENGINE MOUNTING - REAR	*Check	95.10 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 18,142.40 11,820.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT FRONT WINDSCREEN AND CONDUCT WATER LEAK TEST.	New	4,620.00	4,620.00
Gross Labour Cost (\$)			4,620.00	4,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >