

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19019461/KBA3Q2

Date: 28/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SGB3802P **Insured Vehicle No :** SLN6826D

Date of Loss: 31/10/2019 **Nature of Claim:** TP **Claim No:** 1125266759SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGB3802P		
Make & Model:	MERCEDES-BENZ C180K, 1.6 (A)	Engine No:	27191031339053
Reg. Date:	13/12/2010 (Man. Year: 2010)	Chassis No:	WDD2040452A459695
Colour:	Metallic Silver	Odometer:	210426 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,315.00	7,902.60	412.40	4.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	1,850.00	400.00	17.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,565.00	9,752.60	812.40	7.69
Approved Total (Overridden) (\$\$)		7,800.00		
(\$\$)	10,565.00	7,800.00	2,765.00	26.17
+ GST 7.00/7.00% (\$\$)	739.55	546.00	193.55	26.17
Nett Amount (\$\$)	11,304.55	8,346.00	2,958.55	26.17
+ Car Rental (8.0 x S\$85.00/day + 7.00% GST) (\$\$)		727.60		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		9,081.60		

INSPECTION

Date of Assignment: 04/11/2019

Date Inspected: 04/11/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,615.00 FN	*1,615.00 FN
2	1		*REAR BUMPER REINFORCEMENT	Bent	720.00 FN	*720.00 FN
3	1		*REAR BUMPER INNER CENTRE BRACKET	Cracked	145.00 FN	*145.00 FN
4	2		*REAR BUMPER INNER SIDE BRACKET	Cracked	152.00 FN	*152.00 FN
5	1		*REAR BUMPER CENTRE CHROME MOULDING	Necessary	114.00 FN	*114.00 FN
6	2		*REAR BUMPER SIDE CHROME MOULDING	Necessary	216.00 FN	*216.00 FN
7	2		*REAR BUMPER SIDE RETAINER	Distorted	90.00 FN	*90.00 FN
8	1		*REAR BOOT	Bent	1,695.00 FN	*1,695.00 FN
9	1		*REAR BOOT INNER RUBBER (50%)	Cut	158.40 FS	*88.00 FS
10	1		*REAR BOOT INNER LOCK	Dented	320.00 FN	*320.00 FN
11	1		*REAR BOOT LOGO	Necessary	49.00 FN	*49.00 FN
12	1		*REAR BOOT EMBLEM C180	Necessary	87.00 FN	*87.00 FN
13	1		*REAR BOOT EMBLEM KOMPRESSOR	Necessary	112.00 FN	*112.00 FN
14	1		*REAR BOOT OUTER CHROME GARNISH	Scratched	211.00 FN	*211.00 FN
15	6		*REAR BOOT INSULATOR CLIP	Necessary	72.00 FN	*72.00 FN
16	2		*TAILLAMP	Cracked	1,120.00 FN	*1,120.00 FN
17	2		*REAR FENDER INNER SIDE GARNISH	Cut	64.00 FN	*64.00 FN
18	10		*REAR FENDER INNER SIDE GARNISH CLIP	Necessary	90.00 FN	*90.00 FN
19	1		*REAR END PANEL	Bent	1,297.00 FN	*1,297.00 FN
20	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	125.00 FN	*125.00 FN
21	2		*FRONT HEAD REST	Repair	380.00 FN	*- FN
22	1		*REAR BOOT EMBLEM C&C	Necessary	35.00 FS	*35.00 FS
23	1		*SET REVERSE SENSOR	Cracked	280.00 FS	*280.00 FS
24	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	9,182.40	8,732.00
- Nett Item Discount on N Items 10.00/10.00% (S\$)	867.40	829.40
Total Parts (S\$)	8,315.00	7,902.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX REAR BUMPER & PARKING SENSORS ,REAR BOOT & ATTACHMENTS ,TAILLAMPS TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	New	900.00	750.00
2	PUTTY & RESPRAY REAR BUMPER ,PARKING SENSORS ,REAR BOOT BOTH FENDERS ,REAR END PANEL & ALL AFFECTED AREAS	New	950.00	800.00
3	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	60.00	60.00
4	REMOVE & REFIX BOTH FRONT HEAD RESTS & REALIGN THE SAME	New	280.00	180.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (\$\$)			2,250.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >