



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

04/11/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAIG.

MRHGM6660GP000070.

Jiale.

Accident date: 03/11/2019

Estimated repair cost for vehicle no: SMD1218H HONDA CITY 1.5 A '15

CHASSIS: MRHGM6660GP000070

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Distorted.		\$638.70 ✓
2	2	Rear Boot Lid Hinge Bent.	\$51.80	\$103.60 ✓
3	1	Rear Boot Lid Lock Damaged		\$90.30 ✓
4	1	Rear Boot Lid Weatherstrip ut		\$71.60 ✓
5	1	Rear Boot Lid Inner Trim Board		\$130.20 ✓
6	8	Rear Boot Lid Inner Trim Board Clip } New	\$6.50	\$52.00 +
7	1	Rear Boot Lid Emblem Logo ?		\$24.70 ✓
8	1	Rear Boot Lid City Logo } New		\$21.30 ✓
9	1	Rear Boot Lid I-Vtec Logo		\$32.30 ✓
10	1	Rear Boot Lid Center Chrome Moulding cracked.		\$165.00 ✓
11	1	Rear Boot Lid Number Plate Bent		\$50.00 ✓
12	2	Rear Boot Lid Side Reflector ut	\$402.90	\$402.90 ✓
13	1	Rear Boot Lid Camera Not Nec		\$392.60 x
14	2	Rear Taillamp cracked	\$225.70	\$451.40 ✓
15	4	Rear Taillamp Clip New	\$6.50	\$26.00 ✓
16	2	Rear Taillamp Panel RH Dented.	\$89.80	\$179.60 89.80
17	1	Rear Bumper Distorted		\$483.70 ✓
18	10	Rear Bumper Clip New	\$6.50	\$65.00 30.
19	2	Rear Bumper Side Retainer New	\$15.90	\$31.80 ✓
20	2	Rear Bumper Side Reflector RH cracked.	\$30.00	\$60.00 30.
21	2	Rear Bumper Side Under Cover 1 piece deformed	\$30.10	\$60.20 30.10.
22	2	Rear Fender RH Buckled	\$1,109.40	\$2,218.80 795.
23	2	Rear Fender Cowling } New	\$30.20	\$60.40 x
24	16	Rear Fender Cowling Clip } New	\$6.50	\$104.00 x
25	2	Rear Fender Inner Trim Board Not Nec	\$70.80	\$141.60 x
26	16	Rear Fender Inner Trim Board Clip Not Nec	\$6.50	\$104.00 x
27	1	Rear End Panel Distorted		\$336.90 ✓
28	1	Rear End Panel Top Garnish Deformed		\$86.40 ✓
29	1	Rear Spare Tyre Panel Buckled		\$450.80 ✓

30	1	Rear Spare Tyre Panel Top Cover	torn		\$65.00	✓
31	1	Rear Spare Tyre Panel Sealant	Nec		\$450.00	250(SN)
32	1	Rear Exhaust	Bent.		\$455.30	✓
33	2	Rear Exhaust Mounting	Nec Nec	\$19.00	\$38.00	✗
34	1	Rear Exhaust Insulation Cover	Crumpled.		\$68.00	✓
35	1	Rear Center Exhaust	Repair		\$291.70	✗
36	1	Rear Windscreen Moulding	Nec		\$131.80	✗
37	1	Reverse Sensor	Damaged	5030.60	S.N 450	
		385 200(SN)		4024.48		
Subtotal :-					\$8,335.40	

Labour charges

To remove & refit rear windscreen	\$120.00	✓
Gum	\$60.00	✓
To remove & refit reverse camera	\$180.00	60
To remove & refit reverse sensor	\$100.00	60
To remove & refit rear & center exhaust	\$380.00	160
To check wiring	\$150.00	30
Towing fee	\$150.00	60
Tuff kote	\$200.00	120
Panel beating	\$3,600.00	1600
Spray painting	\$2,800.00	1300

Subtotal :- \$7,740.00

Total:- \$16,075.40

Total: 8044.48

w/s: 6.4K.

12 Days.

6.4K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: